

TABLE OF CONTENTS  
TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD (TLTRR)

February 10, 2006

**0.0 - TABLE OF CONTENTS/INDEX**

**1.0 - SITE IDENTIFICATION/PRE-REMEDIAL ACTIVITIES**

- 1.1 - Correspondence
  - 1.1.1 - Formal Correspondence
- 1.2 - Background Documents
- 1.4 - Site Assessment
  - 1.4.1 - Preliminary Assessment
  - 1.4.2 - Integrated Assessment
  - 1.4.3 - Field Log Books
- 1.5 - Site Inspection
  - 1.5.1 - Work Plans
  - 1.5.2 - Field Logs
  - 1.5.3 - Site Inspection Report
  - 1.5.4 - Listing Site Inspection Report
  - 1.5.5 - Spill Response Reports
- 1.7 - NPL Documentation
- 1.8 - Sampling and Analysis
  - 1.8.1 - Sampling and Analysis Plan
  - 1.8.2 - Sampling Data/Results
  - 1.8.3 - Chain of Custody Documents
  - 1.8.4 - Field Log Books
  - 1.8.5 - Water Well Reports
  - 1.8.6 - Geophysical Survey Report
- 1.9 - Pre-NPL Removal Activities
  - 1.9.1 - Correspondence
    - 1.9.1.1 - Formal Correspondence
  - 1.9.4 - Action Memoranda
  - 1.9.5 - Work Plan
  - 1.9.6 - Sampling Plan/QAPP
  - 1.9.7 - Site Safety

TABLE OF CONTENTS  
TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD (TLTRR)

February 10, 2006

- 1.9.8 - Pollution Reports on CD-ROM
- 1.9.9 - Sampling Data
- 1.9.10 - Chain of Custody Documents
- 1.9.11 - Well Logs
- 1.9.13 - Removal Action Report
- 1.9.14 - Groundwater Characterization Report

1.10 - Stormwater Treatment

- 1.10.1 - Correspondence
  - 1.10.1.1 - Formal Correspondence
- 1.10.2 - Stormwater Treatment Plan
- 1.10.3 - Stormwater Treatment System
- 1.10.4 - Stormwater Treatment System Operation & Maintenance Manual

**2.0 - REMEDIAL INVESTIGATION/FEASIBILITY STUDY**

- 2.1 - Correspondence
  - 2.1.1 - Formal Correspondence
  - 2.1.2 - Notes/Email
- 2.2 - Work Plan
- 2.3 - Sampling Plan
- 2.4 - Sampling Data
- 2.7 - Reports
  - 2.7.1 - Remedial Investigation/Feasibility Study Report
    - 2.7.1.1 - Final RI/FS Report on CD-ROM
- 2.9 - Proposed Plan
  - 2.9.1 - Comments on Proposed Plan

**3.0 - RECORD OF DECISION**

- 3.1 - Correspondence/Email
- 3.2 - Record of Decision

**4.0 - POST-NPL REMOVAL ACTIONS**

- 4.3 - Action Memoranda
- 4.5 - Removal Action Report

TABLE OF CONTENTS  
TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD (TLTRR)

February 10, 2006

4.7 - NPDES Waste Discharge Permit

**8.0 - STATE COORDINATION**

8.1 - Correspondence/Email

**10.0 - TRIBAL COORDINATION**

10.1 - Grand Ronde Tribe

**12.0 - ENFORCEMENT**

12.1 - Correspondence/Email

12.6 - Administrative Orders

12.9 - Prospective Purchaser Agreement

**13.0 - HEALTH ASSESSMENTS**

13.1 - Correspondence

13.2 - ATSDR Health Assessment

**14.0 - NATURAL RESOURCE TRUSTEES**

14.1 - Correspondence

**16.0 - PUBLIC PARTICIPATION**

16.1 - Correspondence

16.2 - Community Relations Plan

16.5 - Fact Sheets/Press Releases

16.6 - Mailing Lists

16.9 - Newspaper/Journal Articles

**17.0 - GRAPHICS**

17.1 - Blueprints/Drawings

17.2 - Maps/Plans

17.3 - Photographs

17.3.1 - Photographs on CD-ROM

**HEADING: 0. 0...**

**TABLE OF CONTENTS/INDEX**

**HEADING: 1. 0... SITE IDENTIFICATION/PRE-REMEDIAL ACTIVITIES**

**SUB-HEAD: 1. 1... Vol. 1 - Correspondence**

**SUB-HEAD: 1. 1. 1.. Vol. 1 - Formal Correspondence**

1. 1. 1.. Vol. 1 - 1116500 DOC ID: 1116500 IMAGED  
DATE: 8/4/1988 PAGES: 18  
AUTHOR(S): ADDRESSSEE(S):  
Jeffrey Villnow/Ecology & Environment, Inc. Weston Alt/Taylor Lumber and Treating, Inc.

DESCRIPTION: Letter discusses a visit to Taylor Lumber regarding a preliminary assessment.

1. 1. 1.. Vol. 1 - 1116289 DOC ID: 1116289 IMAGED  
DATE: 10/31/1988 PAGES: 1  
AUTHOR(S): ADDRESSSEE(S):  
James J. Maul/Sweet Edwards/Emcon, Inc. Deborah D. Flood/EPA

DESCRIPTION: Letter transmits and discusses the Phase II Investigation Work Plan, the Phase I Final Report, and the Sampling and Analysis Plan. (Less enclosures)

1. 1. 1.. Vol. 1 - 1116503 DOC ID: 1116503 IMAGED  
DATE: 1/4/1989 PAGES: 1  
AUTHOR(S): ADDRESSSEE(S):  
Karl A. Morgenstern/Ecology & Environment, Inc. John E. Osborn/EPA

DESCRIPTION: Memo discusses disposal of investigation-derived wastes.

1. 1. 1.. Vol. 1 - 1116504 DOC ID: 1116504 IMAGED  
DATE: 1/4/1989 PAGES: 2  
AUTHOR(S): ADDRESSSEE(S):  
Karl A. Morgenstern/Ecology & Environment, Inc. John E. Osborn/EPA

DESCRIPTION: Memo suggests pre-remedial activities to be performed. (Less enclosures)

1. 1. 1.. Vol. 1 - 1116488 DOC ID: 1116488 IMAGED  
DATE: 12/21/1989 PAGES: 19  
AUTHOR(S): ADDRESSSEE(S):  
Deborah D. Flood/EPA Weston Alt/Taylor Lumber and Treating, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Letter transmits quality assurance data from the sampling conducted on the Taylor Lumber facility.

1. 1. 1.. Vol. 1 - 1116311 DOC ID: 1116311 IMAGED  
DATE: 1/31/1990 PAGES: 1  
AUTHOR(S): Chris Mebane/NOAA ADDRESSEE(S):  
Deborah D. Flood/EPA

DESCRIPTION:

Memo discusses the results of a drainage ditch inspection.

1. 1. 1.. Vol. 1 - 1116313 DOC ID: 1116313 IMAGED  
DATE: 3/8/1990 PAGES: 1  
AUTHOR(S): Karl A. Morgenstern/Ecology & Environment, Inc. ADDRESSEE(S):  
John E. Osborn/EPA

DESCRIPTION:

Memo recommends certain pre-remedial activities be performed. (Less enclosures)

1. 1. 1.. Vol. 1 - 1088882 DOC ID: 1088882 IMAGED  
DATE: 4/9/1999 PAGES: 2  
AUTHOR(S): Annette Sackman-Franzen/Ecology & Environment, Inc. ADDRESSEE(S):  
Roland Mueller/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter of notification that an Integrated Assessment is to be conducted at Taylor Lumber and Treating site, Sheridan, Oregon.

1. 1. 1.. Vol. 1 - 1114252 DOC ID: 1114252 IMAGED  
DATE: 5/26/1999 PAGES: 4  
AUTHOR(S): Andrew Miller/Maul Foster & Alongi, Inc. ADDRESSEE(S):  
Roland Mueller/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Faxed memorandum of transmittal for selected pages from report of 8/19/94 entitled Amended Surface Impoundment Closure Plan for the Former Concrete Cooling Water Vault (pages attached).

1. 1. 1.. Vol. 1 - 1088894 DOC ID: 1088894 IMAGED  
DATE: 6/10/1999 PAGES: 1  
AUTHOR(S): Carl G. Kitz/EPA ADDRESSEE(S):  
File

DESCRIPTION:

Memorandum concerning meeting of 6/10/99 with R. Mueller, Taylor Lumber, discussing possible corrective actions for oil storage facility.

1. 1. 1.. Vol. 1 - 1114281 DOC ID: 1114281 IMAGED  
DATE: 8/17/1999 PAGES: 8  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Suzanne Dolberg/Ecology & Environment, Inc.

Michael Sibley/EPA

DESCRIPTION:

Memorandum describes removal alternatives that may be applicable to the Taylor Lumber and Treating site.

1. 1. 1.. Vol. 1 - 1088895 DOC ID: 1088895 IMAGED  
DATE: 9/22/1999 PAGES: 2  
AUTHOR(S): Annette Sackman-Franzen/Ecology & Environment, Inc. ADDRESSEE(S):  
Carl G. Kitz/EPA

DESCRIPTION:

Memo summarizes preliminary data collected during Integrated Assessment activities conducted at Taylor Lumber site, 5/17-6/11/99.

**SUB-HEAD: 1. 2... Vol. 1 - Background Documents**

1. 2... Vol. 1 - 1124062 DOC ID: 1124062 IMAGED  
DATE: 1/1/1974 PAGES: 196  
AUTHOR(S): U. S. Dept. of Agriculture ADDRESSEE(S):  
Unknown

DESCRIPTION:

Report: Soil Survey of Yamhill Area, Oregon.

1. 2... Vol. 1 - 1116610 DOC ID: 1116610 IMAGED  
DATE: 8/20/1979 PAGES: 2  
AUTHOR(S): Stephen C. Downs/Unknown ADDRESSEE(S):  
Unknown

DESCRIPTION:

Inventory: Possible Sources of Hazardous Waste.

1. 2... Vol. 1 - 1116611 DOC ID: 1116611 IMAGED  
DATE: 1/1/1980 PAGES: 2  
AUTHOR(S): Unknown ADDRESSEE(S):  
Unknown

DESCRIPTION:

Inventory: Possible Sources of Hazardous Waste.

Note: Document date is estimated.

1. 2... Vol. 1 - 1116612 DOC ID: 1116612 IMAGED  
DATE: 1/1/1980 PAGES: 3  
AUTHOR(S): Unknown ADDRESSEE(S):  
Unknown

DESCRIPTION:

Biographical Information on Taylor Treating.

Note: Document date is estimated.

1. 2... Vol. 1 - 1116613 DOC ID: 1116613 IMAGED  
DATE: 7/24/1981 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Andrew Thomas/Ecology & Environment, Inc.

EPA

DESCRIPTION: Inspection Report.

1. 2... Vol. 1 - 1116614 DOC ID: 1116614 IMAGED  
DATE: 3/31/1983 PAGES: 3  
AUTHOR(S): Thomas A. Tobin/Ecology & Environment, Inc. ADDRESSEE(S): Unknown

DESCRIPTION: File Review Checklist.

1. 2... Vol. 1 - 1116615 DOC ID: 1116615 IMAGED  
DATE: 1/1/1985 PAGES: 12  
AUTHOR(S): Pete Ayala/Taylor Lumber and Treating, Inc. ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: 1985 Discharge Monitoring Reports.

1. 2... Vol. 1 - 1116619 DOC ID: 1116619 IMAGED  
DATE: 12/23/1985 PAGES: 1  
AUTHOR(S): Fritz A. Skirvin/Oregon State Dept. of Environmental Quality ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: DMR Review Form.

1. 2... Vol. 1 - 1116616 DOC ID: 1116616 IMAGED  
DATE: 1/1/1986 PAGES: 11  
AUTHOR(S): Pete Ayala/Taylor Lumber and Treating, Inc. ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: 1986 Discharge Monitoring Reports.

Note: The October page is missing.

1. 2... Vol. 1 - 1116620 DOC ID: 1116620 IMAGED  
DATE: 1/1/1986 PAGES: 1  
AUTHOR(S): Unknown ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: 1986 Once a Year Discharge Monitoring Report.

1. 2... Vol. 1 - 1116621 DOC ID: 1116621 IMAGED  
DATE: 5/9/1986 PAGES: 2  
AUTHOR(S): Fritz A. Skirvin/Oregon State Dept. of Environmental Quality ADDRESSEE(S): Oregon State Dept. of Environmental Quality



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION: DMR Review Form.

1. 2... Vol. 1 - 1116622 DOC ID: 1116622 IMAGED  
DATE: 5/9/1986 PAGES: 1  
AUTHOR(S): Fritz A. Skirvin/Oregon State Dept. of Environmental Quality  
ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: Source Inspection Form.

1. 2... Vol. 1 - 1116617 DOC ID: 1116617 IMAGED  
DATE: 1/1/1987 PAGES: 12  
AUTHOR(S): Pete Ayala/Taylor Lumber and Treating, Inc.  
ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: 1987 Discharge Monitoring Reports.

1. 2... Vol. 1 - 1116623 DOC ID: 1116623 IMAGED  
DATE: 7/22/1987 PAGES: 1  
AUTHOR(S): Fritz A. Skirvin/Oregon State Dept. of Environmental Quality  
ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: Source Inspection Form.

1. 2... Vol. 1 - 1116618 DOC ID: 1116618 IMAGED  
DATE: 1/1/1988 PAGES: 7  
AUTHOR(S): Pete Ayala/Taylor Lumber and Treating, Inc.  
ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: 1988 Discharge Monitoring Reports.

Note: The following months are missing: May, September, October, November, December.

1. 2... Vol. 1 - 1114251 DOC ID: 1114251 IMAGED  
DATE: 4/14/1988 PAGES: 113  
AUTHOR(S): John G. Kuhlman/Sweet Edwards/Emcon, Inc.  
ADDRESSEE(S): Pete Ayala/Taylor Lumber and Treating, Inc.

DESCRIPTION: Taylor Lumber Phase I Final Report.

1. 2... Vol. 1 - 1116625 DOC ID: 1116625 IMAGED  
DATE: 5/5/1988 PAGES: 1  
AUTHOR(S): Fritz A. Skirvin/Oregon State Dept. of Environmental Quality  
ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: Source Inspection Form.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 2... Vol. 1 - 1116624 DOC ID: 1116624 IMAGED  
DATE: 7/11/1988 PAGES: 1  
AUTHOR(S): Fritz A. Skirvin/Oregon State Dept. of Environmental Quality  
ADDRESSEE(S): Oregon State Dept. of Environmental Quality

DESCRIPTION: DMR Review Form.

1. 2... Vol. 1 - 1116626 DOC ID: 1116626 IMAGED  
DATE: 9/1/1989 PAGES: 49  
AUTHOR(S): Ecology & Environment, Inc.  
ADDRESSEE(S): John E. Osborn/EPA

DESCRIPTION: Report: Pentachlorophenol and Polycyclic Aromatic Hydrocarbon In Soil FASP Results.

1. 2... Vol. 1 - 1114396 DOC ID: 1114396 IMAGED  
DATE: 7/22/1991 PAGES: 135  
AUTHOR(S): Sweet Edwards/Emcon, Inc.  
ADDRESSEE(S): Bogle & Gates

DESCRIPTION: Report on Removal of Drums from Concrete Vault, Taylor Lumber and Treating, Sheridan, Oregon.

1. 2... Vol. 1 - 1114397 DOC ID: 1114397 IMAGED  
DATE: 9/24/1991 PAGES: 181  
AUTHOR(S): Sweet Edwards/Emcon, Inc.  
ADDRESSEE(S): Taylor Lumber and Treating, Inc.

DESCRIPTION: Report: Retort Area Characterization, Taylor Lumber and Treating, Sheridan, Oregon.

1. 2... Vol. 1 - 1114398 DOC ID: 1114398 IMAGED  
DATE: 11/26/1991 PAGES: 343  
AUTHOR(S): Dorothy Fisher-Atwood/Sweet Edwards/Emcon, Inc.  
ADDRESSEE(S): Taylor Lumber and Treating, Inc.  
Mike Renz/Oregon State Dept. of Environmental Quality

DESCRIPTION: Report: Resource Conservation and Recovery Act Facility Investigation Workplan, Taylor Lumber and Treating, Inc., Sheridan, Oregon.

1. 2... Vol. 1 - 1114399 DOC ID: 1114399 IMAGED  
DATE: 3/16/1992 PAGES: 125  
AUTHOR(S): Denise E. Mills/Sweet Edwards/Emcon, Inc.  
ADDRESSEE(S): Taylor Lumber and Treating, Inc.

Tim Browning/EMCON Northwest, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Tim Browning/EMCON Northwest, Inc.

Max Rosenberg/Oregon State Dept. of  
Environmental Quality

Denise E. Mills/Sweet Edwards/Emcon, Inc.

DESCRIPTION:

Report: UST (Underground Storage Tank) Decommissioning Initial Site Characterization, Taylor Lumber and Treating, Inc., Sheridan, Oregon.

1. 2... Vol. 1 - 1114253 DOC ID: 1114253 IMAGED  
DATE: 12/1/1994 PAGES: 105  
AUTHOR(S): EPA ADDRESSEE(S):  
Unknown

DESCRIPTION:

Report: RCRA Facility Assessment, Taylor Lumber and Treating, Inc., Sheridan, Oregon.  
(Annotated)

Note: Document is incomplete, missing pages 96-98, all Figures, Tables, and Attachments.

1. 2... Vol. 1 - 1124196 DOC ID: 1124196 IMAGED  
DATE: 12/1/1994 PAGES: 158  
AUTHOR(S): EPA ADDRESSEE(S):  
Unknown

DESCRIPTION:

Report: RCRA Facility Assessment.

Note: This document is incomplete, but is more complete than DocID 138562 which is in the Removal AR.

1. 2... Vol. 1 - 1114254 DOC ID: 1114254 IMAGED  
DATE: 4/21/1997 PAGES: 330  
AUTHOR(S): Maul Foster & Alongi, Inc. ADDRESSEE(S):  
Taylor Lumber and Treating, Inc.

DESCRIPTION:

Phase 1 RCRA Facility Investigation Final Report, Taylor Lumber and Treating, Inc., Sheridan, Oregon, Volume 1 (Text, Tables, Figures, and Appendix A-C).

1. 2... Vol. 1 - 1114255 DOC ID: 1114255 IMAGED  
DATE: 4/21/1997 PAGES: 855  
AUTHOR(S): Maul Foster & Alongi, Inc. ADDRESSEE(S):  
Taylor Lumber and Treating, Inc.

DESCRIPTION:

Phase 1 RCRA Facility Investigation Final Report, Taylor Lumber and Treating, Inc., Sheridan, Oregon, Volume 2 (Appendix D-H).

1. 2... Vol. 1 - 1116782 DOC ID: 1116782 IMAGED  
DATE: 3/2/1999 PAGES: 3  
AUTHOR(S): Oregon State Dept. of Human Resources ADDRESSEE(S):  
Unknown

DESCRIPTION:

Report: Drinking Water Program; Chemical Detection Summary.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 2... Vol. 1 - 1109190 DOC ID: 1109190 IMAGED  
DATE: 4/1/1999 PAGES: 76  
AUTHOR(S): James J. Maul/Maul Foster & Alongi, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION: Letter of transmittal for tables with updated groundwater monitoring data for monitoring wells at Taylor Lumber and Treating site (tables attached).

**SUB-HEAD: 1. 4... Vol. 1 - Site Assessment**

**SUB-HEAD: 1. 4. 1.. Vol. 1 - Preliminary Assessment**

1. 4. 1.. Vol. 1 - 1116627 DOC ID: 1116627 IMAGED  
DATE: 8/1/1979 PAGES: 4  
AUTHOR(S): Judith W. Fey/EPA ADDRESSEE(S): EPA

DESCRIPTION: Potential Hazardous Waste Site Identification and Preliminary Assessment.

1. 4. 1.. Vol. 1 - 1116628 DOC ID: 1116628 IMAGED  
DATE: 3/6/1980 PAGES: 1  
AUTHOR(S): Judith W. Fey/EPA ADDRESSEE(S): EPA

DESCRIPTION: Potential Hazardous Waste Site Log.

1. 4. 1.. Vol. 1 - 1116532 DOC ID: 1116532 IMAGED  
DATE: 11/21/1983 PAGES: 8  
AUTHOR(S): Hussein Aldis/Ecology & Environment, Inc. ADDRESSEE(S): John E. Osborn/EPA

DESCRIPTION: Memo describes the preliminary assessment.

1. 4. 1.. Vol. 1 - 1116533 DOC ID: 1116533 IMAGED  
DATE: 4/16/1984 PAGES: 2  
AUTHOR(S): Joan McNamee/EPA ADDRESSEE(S): Unknown

DESCRIPTION: Potential Hazardous Waste Site Disposition form.

1. 4. 1.. Vol. 1 - 1114248 DOC ID: 1114248 IMAGED  
DATE: 9/1/1988 PAGES: 17  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Karl A. Morgenstern/Ecology & Environment, Inc.

John E. Osborn/EPA

DESCRIPTION:

Preliminary Assessment Report, J.C. Taylor Lumber and Treating, Inc., Sheridan, Oregon.

1. 4. 1.. Vol. 1 - 1116534 DOC ID: 1116534 IMAGED  
DATE: 12/30/1988 PAGES: 2  
AUTHOR(S): ADDRESSSEE(S):  
Deborah D. Flood/EPA Unknown

DESCRIPTION:

Potential Hazardous Waste Site Disposition form.

**SUB-HEAD: 1. 4. 2.. Vol. 1 - Integrated Assessment**

1. 4. 2.. Vol. 1 - 1116935 DOC ID: 1116935 IMAGED  
DATE: 10/6/1999 PAGES: 46  
AUTHOR(S): ADDRESSSEE(S):  
Annette Sackman-Franzen/Ecology & Environment, Inc. Steven P. Taylor/Maul Foster & Alongi, Inc.

DESCRIPTION:

Draft analytical summary tables and related figures for the Integrated Assessment.

1. 4. 2.. Vol. 1 - 1127794 DOC ID: 1127794 IMAGED  
DATE: 10/27/1999 PAGES: 5  
AUTHOR(S): ADDRESSSEE(S):  
Annette Sackman-Franzen/Ecology & Environment, Inc. Michael Sibley/EPA

DESCRIPTION:

Memo transmitting updated figures for the Integrated Assessment.

1. 4. 2.. Vol. 1 - DOC ID: 1150690 IMAGED  
DATE: 6/1/2000 PAGES: 929  
AUTHOR(S): ADDRESSSEE(S):  
Superfund Technical Assessment and Response Team Mark A. Ader/EPA  
(START)

DESCRIPTION:

Integrated Assessment Report. TDD: 99-03-0006.

1. 4. 2.. Vol. 1 - 1114275 DOC ID: 1114275 IMAGED  
DATE: 7/1/2000 PAGES: 416  
AUTHOR(S): ADDRESSSEE(S):  
Superfund Technical Assessment and Response Team Mark A. Ader/EPA  
(START)

DESCRIPTION:

Integrated Assessment Report, Taylor Lumber and Treating, Sheridan, Oregon. TDD: 99-03-0006

1. 4. 2.. Vol. 1 - 1114277 DOC ID: 1114277 IMAGED  
DATE: 7/1/2000 PAGES: 1,349  
AUTHOR(S): ADDRESSSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Superfund Technical Assessment and Response Team  
(START)

Mark A. Ader/EPA

DESCRIPTION:

Part 1 of Appendix E (Data Validation Memoranda and Analytical Results) of Taylor Lumber and Treating Site Integrated Assessment Report, Sheridan, Oregon.

1. 4. 2.. Vol. 1 - 1114278 DOC ID: 1114278 IMAGED

DATE: 7/1/2000 PAGES: 1,281

AUTHOR(S):

Superfund Technical Assessment and Response Team  
(START)

ADDRESSEE(S):

Mark A. Ader/EPA

DESCRIPTION:

Part 2 of Appendix E (Data Validation Memoranda and Analytical Results) of Taylor Lumber and Treating Site Integrated Assessment Report, Sheridan, Oregon.

1. 4. 2.. Vol. 1 - 1114279 DOC ID: 1114279 IMAGED

DATE: 7/1/2000 PAGES: 499

AUTHOR(S):

Superfund Technical Assessment and Response Team  
(START)

ADDRESSEE(S):

Mark A. Ader/EPA

DESCRIPTION:

Part 3 of Appendix E (Data Validation Memoranda and Analytical Results) of Taylor Lumber and Treating Site Integrated Assessment Report, Sheridan, Oregon.

1. 4. 2.. Vol. 1 - 1114280 DOC ID: 1114280 IMAGED

DATE: 7/1/2000 PAGES: 1,099

AUTHOR(S):

Superfund Technical Assessment and Response Team  
(START)

ADDRESSEE(S):

Mark A. Ader/EPA

DESCRIPTION:

Part 4 of Appendix E (Data Validation Memoranda and Analytical Results) of Taylor Lumber and Treating Site Integrated Assessment Report, Sheridan, Oregon.

**SUB-HEAD: 1. 4. 3.. Vol. 1 - Field Log Books**

1. 4. 3.. Vol. 1 - 1127758 DOC ID: 1127758 IMAGED

DATE: 5/17/1999 PAGES: 8

AUTHOR(S):

Michael Sibley/EPA

ADDRESSEE(S):

Unknown

DESCRIPTION:

Field Log Book: Integrated Assessment.

**SUB-HEAD: 1. 5... Vol. 1 - Site Inspection**

**SUB-HEAD: 1. 5. 1.. Vol. 1 - Work Plans**

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 5. 1.. Vol. 1 - 1116361 DOC ID: 1116361 IMAGED  
DATE: 9/1/1988 PAGES: 40  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S): John E. Osborn/EPA

DESCRIPTION: Field Operations Work Plan.

1. 5. 1.. Vol. 1 - 1116362 DOC ID: 1116362 IMAGED  
DATE: 10/31/1988 PAGES: 13  
AUTHOR(S): Sweet Edwards/Emcon, Inc. ADDRESSEE(S): EPA

DESCRIPTION: Phase II Soil and Groundwater Investigation Work Plan.  
Note: Document date is estimated.

1. 5. 1.. Vol. 1 - 1116363 DOC ID: 1116363 IMAGED  
DATE: 7/1/1989 PAGES: 100  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S): John E. Osborn/EPA

DESCRIPTION: Listing Site Inspection Field Operations Work Plan.

**SUB-HEAD: 1. 5. 2.. Vol. 1 - Field Logs**

1. 5. 2.. Vol. 1 - 1116510 DOC ID: 1116510 IMAGED  
DATE: 7/29/1988 PAGES: 48  
AUTHOR(S): Karl A. Morgenstern/Ecology & Environment, Inc. ADDRESSEE(S): Unknown

DESCRIPTION: Field notes from July 29, 1988 to August 15, 1989.

1. 5. 2.. Vol. 1 - 1116513 DOC ID: 1116513 IMAGED  
DATE: 8/14/1989 PAGES: 24  
AUTHOR(S): Unknown ADDRESSEE(S): Unknown

DESCRIPTION: Field notes from August 14 to August 25, 1989 regarding soil sampling.

1. 5. 2.. Vol. 1 - 1116511 DOC ID: 1116511 IMAGED  
DATE: 8/16/1989 PAGES: 49  
AUTHOR(S): Karl A. Morgenstern/Ecology & Environment, Inc. ADDRESSEE(S): Unknown

DESCRIPTION: Field notes from August 16 to August 22, 1989 regarding the Listing Site Inspection sampling visit.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 5. 2.. Vol. 1 - 1116512 DOC ID: 1116512 IMAGED  
DATE: 8/22/1989 PAGES: 13  
AUTHOR(S): Karl A. Morgenstern/Ecology & Environment, Inc. ADDRESSEE(S): Unknown

DESCRIPTION: Field notes from August 22, 1989 to July 5, 1990 regarding the Listing Site Inspection sampling visit, air permits, and Hazard Ranking System scoring.

1. 5. 2.. Vol. 1 - 1116514 DOC ID: 1116514 IMAGED  
DATE: 8/23/1989 PAGES: 20  
AUTHOR(S): Unknown ADDRESSEE(S): Unknown

DESCRIPTION: Field notes regarding a geophysical survey.

**SUB-HEAD: 1. 5. 3.. Vol. 1 - Site Inspection Report**

1. 5. 3.. Vol. 1 - 1114241 DOC ID: 1114241 IMAGED  
DATE: 12/1/1988 PAGES: 122  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S): John E. Osborn/EPA

DESCRIPTION: Site Inspection Report for Taylor Lumber and Treating, Inc., Sheridan, Oregon.

**SUB-HEAD: 1. 5. 4.. Vol. 1 - Listing Site Inspection Report**

1. 5. 4.. Vol. 1 - 1114242 DOC ID: 1114242 IMAGED  
DATE: 3/1/1990 PAGES: 393  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S): John E. Osborn/EPA

DESCRIPTION: Listing Site Inspection Report for Taylor Lumber and Treating, Inc., Sheridan, Oregon, Volume 3 of 3.

1. 5. 4.. Vol. 1 - 1114243 DOC ID: 1114243 IMAGED  
DATE: 3/1/1990 PAGES: 105  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S): John E. Osborn/EPA

DESCRIPTION: Listing Site Inspection Report for Taylor Lumber and Treating, Inc., Sheridan, Oregon, Volume 1 of 3.

1. 5. 4.. Vol. 1 - 1114244 DOC ID: 1114244 IMAGED  
DATE: 3/1/1990 PAGES: 398  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S): John E. Osborn/EPA



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Listing Site Inspection Report for Taylor Lumber and Treating, Inc., Sheridan, Oregon, Volume 2 of 3.

**SUB-HEAD: 1. 5. 5.. Vol. 1 - Spill Response Reports**

1. 5. 5.. Vol. 1 - 1127776 DOC ID: 1127776 IMAGED  
DATE: 10/9/1996 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
National Response Center Unknown

DESCRIPTION: Spill Release Report from the National Database: Creosote.

1. 5. 5.. Vol. 1 - 1127777 DOC ID: 1127777 IMAGED  
DATE: 11/5/1996 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
National Response Center Unknown

DESCRIPTION: Spill Release Report from the National Database: Pentachlorophenol.

1. 5. 5.. Vol. 1 - 1127778 DOC ID: 1127778 IMAGED  
DATE: 12/9/1997 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
National Response Center Unknown

DESCRIPTION: Spill Release Report from the National Database: Creosote, Coal Tar.

1. 5. 5.. Vol. 1 - 1127779 DOC ID: 1127779 IMAGED  
DATE: 2/25/1999 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
National Response Center Unknown

DESCRIPTION: Spill Release Report from the National Database: Pentachlorophenol.

1. 5. 5.. Vol. 1 - 1127759 DOC ID: 1127759 IMAGED  
DATE: 2/27/1999 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION: Field log book titled: Spill Log.

1. 5. 5.. Vol. 1 - 1127775 DOC ID: 1127775 IMAGED  
DATE: 4/9/1999 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
National Response Center Anthony Barber/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Incident Report: Creosote Spill.

1. 5. 5.. Vol. 1 - 1127780 DOC ID: 1127780 IMAGED  
DATE: 4/9/1999 PAGES: 1  
AUTHOR(S): ADDRESSSEE(S):  
National Response Center Unknown

DESCRIPTION:

Spill Release Report from the National Database: Creosote.

1. 5. 5.. Vol. 1 - 1114246 DOC ID: 1114246 IMAGED  
DATE: 4/14/1999 PAGES: 144  
AUTHOR(S): ADDRESSSEE(S):  
Jessica Baker/Ecology & Environment, Inc. Michael Sibley/EPA

DESCRIPTION:

Emergency Response Trip Report regarding a pentachlorophenol discharge.

1. 5. 5.. Vol. 1 - 1127781 DOC ID: 1127781 IMAGED  
DATE: 5/4/1999 PAGES: 1  
AUTHOR(S): ADDRESSSEE(S):  
National Response Center Unknown

DESCRIPTION:

Spill Release Report from the National Database: Creosote.

1. 5. 5.. Vol. 1 - 1127792 DOC ID: 1127792 IMAGED  
DATE: 5/4/1999 PAGES: 2  
AUTHOR(S): ADDRESSSEE(S):  
National Response Center Unknown

DESCRIPTION:

Incident Report: Creosote Release.

1. 5. 5.. Vol. 1 - 1127708 DOC ID: 1127708 IMAGED  
DATE: 9/14/1999 PAGES: 3  
AUTHOR(S): ADDRESSSEE(S):  
Jeffrey Fowlow/Ecology & Environment, Inc. Carl G. Kitz/EPA

DESCRIPTION:

Memo reports an oil spill occurring September 10, 1999.

1. 5. 5.. Vol. 1 - 1127709 DOC ID: 1127709 IMAGED  
DATE: 9/17/1999 PAGES: 2  
AUTHOR(S): ADDRESSSEE(S):  
Jeffrey Fowlow/Ecology & Environment, Inc. Carl G. Kitz/EPA

DESCRIPTION:

Spill Response Update #2 regarding the oil spill occurring September 10, 1999.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 5. 5.. Vol. 1 - 1127710 DOC ID: 1127710 IMAGED  
DATE: 9/17/1999 PAGES: 5  
AUTHOR(S): ADDRESSSEE(S):  
Steven P. Taylor/Maul Foster & Alongi, Inc. Carl G. Kitz/EPA

DESCRIPTION: Letter responds to the oil spill occurring September 10, 1999.

1. 5. 5.. Vol. 1 - 1127711 DOC ID: 1127711 IMAGED  
DATE: 9/21/1999 PAGES: 1  
AUTHOR(S): ADDRESSSEE(S):  
Jeffrey Fowlow/Ecology & Environment, Inc. Carl G. Kitz/EPA

DESCRIPTION: Spill Response Update #3 regarding the oil spill occurring September 10, 1999.

1. 5. 5.. Vol. 1 - 1127712 DOC ID: 1127712 IMAGED  
DATE: 10/4/1999 PAGES: 26  
AUTHOR(S): ADDRESSSEE(S):  
Vince Gullette/Taylor Lumber and Treating, Inc. Kevin Schanilec/EPA

DESCRIPTION: Letter supplements the recent response to the oil spill occurring September 10, 1999.

1. 5. 5.. Vol. 1 - 1127713 DOC ID: 1127713 IMAGED  
DATE: 10/4/1999 PAGES: 26  
AUTHOR(S): ADDRESSSEE(S):  
Vince Gullette/Taylor Lumber and Treating, Inc. Chris Gillett/Oregon State Dept. of Environmental Quality

DESCRIPTION: Letter transmits a spill/release report regarding the oil spill occurring September 10, 1999.

1. 5. 5.. Vol. 1 - 1127793 DOC ID: 1127793 IMAGED  
DATE: 1/4/2000 PAGES: 2  
AUTHOR(S): ADDRESSSEE(S):  
National Response Center Unknown

DESCRIPTION: Incident Report: Creosote Release.

1. 5. 5.. Vol. 1 - 1116969 DOC ID: 1116969 IMAGED  
DATE: 1/20/2000 PAGES: 19  
AUTHOR(S): ADDRESSSEE(S):  
Vince Gullette/Taylor Lumber and Treating, Inc. Claudia Johansen/Oregon State Dept. of Environmental Quality

DESCRIPTION: Letter reports on the creosote spill of December 31, 1999.

1. 5. 5.. Vol. 1 - 1114256 DOC ID: 1114256 IMAGED  
DATE: 4/1/2000 PAGES: 49  
AUTHOR(S): ADDRESSSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Jeffrey Fowlow/Ecology & Environment, Inc.

Michael Sibley/EPA

DESCRIPTION:

Spill Response Trip Report regarding an oil spill in September, 1999.

**SUB-HEAD: 1. 7... Vol. 1 - NPL Documentation**

1. 7... Vol. 1 - 1116331 DOC ID: 1116331 IMAGED  
DATE: 6/28/2000 PAGES: 2  
AUTHOR(S): ADDRESSSEE(S):  
Richard Albright/EPA Michael F. Gearheard/EPA

DESCRIPTION:

Memo provides the RCRA program's concurrence on placing Taylor Lumber on the National Priorities List.

1. 7... Vol. 1 - 1116333 DOC ID: 1116333 IMAGED  
DATE: 7/12/2000 PAGES: 5  
AUTHOR(S): ADDRESSSEE(S):  
Michael F. Gearheard/EPA Charles E. Findley/EPA

DESCRIPTION:

Memo recommends placing Taylor Lumber on the National Priorities List.

**SUB-HEAD: 1. 8... Vol. 1 - Sampling and Analysis**

**SUB-HEAD: 1. 8. 1.. Vol. 1 - Sampling and Analysis Plan**

1. 8. 1.. Vol. 1 - 1116536 DOC ID: 1116536 IMAGED  
DATE: 7/23/1986 PAGES: 37  
AUTHOR(S): ADDRESSSEE(S):  
Sweet Edwards and Associate, Inc. Taylor Lumber and Treating, Inc.

DESCRIPTION:

Sampling and Analysis Plan.

1. 8. 1.. Vol. 1 - 1116909 DOC ID: 1116909 IMAGED  
DATE: 5/1/1999 PAGES: 274  
AUTHOR(S): ADDRESSSEE(S):  
Annette Sackman-Franzen/Ecology & Environment, Inc. Michael Sibley/EPA

DESCRIPTION:

Final Sampling and Quality Assurance Plan. TDD: 99-03-0006.

1. 8. 1.. Vol. 1 - DOC ID: 1167077 IMAGED  
DATE: 10/25/1999 PAGES: 8  
AUTHOR(S): ADDRESSSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Ecology & Environment, Inc.

Unknown

DESCRIPTION:

Table showing XRF and Commercial samples, and sample location map.

Note: Document date is estimated.

**SUB-HEAD: 1. 8. 2.. Vol. 1 - Sampling Data/Results**

1. 8. 2.. Vol. 1 - 1116496 DOC ID: 1116496 IMAGED  
DATE: 5/27/1988 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Pete Ayala/Taylor Lumber and Treating, Inc. Fritz A. Skirvin/Oregon State Dept. of Environmental Quality

DESCRIPTION:

Letter transmits results of oil separator station samples.

1. 8. 2.. Vol. 1 - 1116475 DOC ID: 1116475 IMAGED  
DATE: 11/16/1988 PAGES: 17  
AUTHOR(S): ADDRESSEE(S):  
Andrew Hafferty/Ecology & Environment, Inc. Joyce M. Crosson/EPA

Tracy D. Yerian/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of seven water and five soil samples, Case 4192J.

1. 8. 2.. Vol. 1 - 1116476 DOC ID: 1116476 IMAGED  
DATE: 12/7/1988 PAGES: 15  
AUTHOR(S): ADDRESSEE(S):  
James J. Maul/Sweet Edwards/Emcon, Inc. Deborah D. Flood/EPA

DESCRIPTION:

Letter transmits and discusses the results of a laboratory analysis of drip pad and drainage sediment samples.

1. 8. 2.. Vol. 1 - 1116477 DOC ID: 1116477 IMAGED  
DATE: 12/12/1988 PAGES: 42  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Joyce M. Crosson/EPA

DESCRIPTION:

Memo transmits a quality assurance review of seven water and five soil samples, Case 10624.

1. 8. 2.. Vol. 1 - 1116478 DOC ID: 1116478 IMAGED  
DATE: 9/29/1989 PAGES: 68  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA

Mark Woodke/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo transmits a quality assurance review of 20 soil samples, Case 12523.

1. 8. 2.. Vol. 1 - 1116479 DOC ID: 1116479 IMAGED  
DATE: 10/11/1989 PAGES: 27  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Andrew Riddell/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of 20 water samples, Case 12523.

1. 8. 2.. Vol. 1 - 1116480 DOC ID: 1116480 IMAGED  
DATE: 10/13/1989 PAGES: 28  
AUTHOR(S): ADDRESSEE(S):  
David A. Ikeda/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Tracy D. Yerian/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of 20 soil samples, Case 12523.

1. 8. 2.. Vol. 1 - 1116481 DOC ID: 1116481 IMAGED  
DATE: 10/13/1989 PAGES: 8  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Andrew Riddell/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of two soil samples, Case 12523.

1. 8. 2.. Vol. 1 - 1116482 DOC ID: 1116482 IMAGED  
DATE: 10/20/1989 PAGES: 70  
AUTHOR(S): ADDRESSEE(S):  
David A. Ikeda/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Tracy D. Yerian/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of 20 water samples, Case 12523.

1. 8. 2.. Vol. 1 - 1116483 DOC ID: 1116483 IMAGED  
DATE: 10/20/1989 PAGES: 66  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
David A. Ikeda/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo transmits a quality assurance review of 19 soil samples, Case 12523.

1. 8. 2.. Vol. 1 - 1116484 DOC ID: 1116484 IMAGED  
DATE: 10/20/1989 PAGES: 23  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
David A. Ikeda/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of six water samples, Case 12523.

1. 8. 2.. Vol. 1 - 1116485 DOC ID: 1116485 IMAGED  
DATE: 10/26/1989 PAGES: 13  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Andrew Riddell/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of six water samples, Case 12523.

1. 8. 2.. Vol. 1 - 1116486 DOC ID: 1116486 IMAGED  
DATE: 11/2/1989 PAGES: 24  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Lila Accra/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of 17 soil samples, Case 12523.

1. 8. 2.. Vol. 1 - 1116487 DOC ID: 1116487 IMAGED  
DATE: 11/17/1989 PAGES: 48  
AUTHOR(S): ADDRESSEE(S):  
Lila Accra/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Tracy D. Yerian/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of 33 air samples, Case 4846J.

1. 8. 2.. Vol. 1 - 1116489 DOC ID: 1116489 IMAGED  
DATE: 1/4/1990 PAGES: 50  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Andrew Riddell/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo transmits a quality assurance review of 23 air samples, Case 4846J.

1. 8. 2.. Vol. 1 - 1116490 DOC ID: 1116490 IMAGED  
DATE: 1/15/1990 PAGES: 40  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Andrew Riddell/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of five water samples, Case 12730.

1. 8. 2.. Vol. 1 - 1116491 DOC ID: 1116491 IMAGED  
DATE: 1/17/1990 PAGES: 34  
AUTHOR(S): ADDRESSEE(S):  
Tracy D. Yerian/Ecology & Environment, Inc. Rhonda Wreggelsworth/EPA  
  
Mark Woodke/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits a quality assurance review of 23 air filter samples, Case 4846J.

1. 8. 2.. Vol. 1 - 1116492 DOC ID: 1116492 IMAGED  
DATE: 2/8/1990 PAGES: 10  
AUTHOR(S): ADDRESSEE(S):  
Karl A. Morgenstern/Ecology & Environment, Inc. John E. Osborn/EPA

DESCRIPTION:

Memo transmits three analytical data tables and seven air sampling data sheets.

1. 8. 2.. Vol. 1 - 1114257 DOC ID: 1114257 IMAGED  
DATE: 4/12/1995 PAGES: 143  
AUTHOR(S): ADDRESSEE(S):  
EMCON Northwest, Inc. Taylor Lumber and Treating, Inc.

DESCRIPTION:

Soil Stockpile Analytical Data.

1. 8. 2.. Vol. 1 - 1124129 DOC ID: 1124129 IMAGED  
DATE: 1/23/1997 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Paula Young/Agriculture and Priority Pollutants Laboratories, Inc. Chris Mullen/Environmental Sampling and Supply

DESCRIPTION:

Pesticide sample results.

1. 8. 2.. Vol. 1 - 1124130 DOC ID: 1124130 IMAGED  
DATE: 7/18/1997 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
George Krisztian/National Testing Laboratories, Inc. Environmental Sampling and Supply



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION: Organic chemicals analysis.

1. 8. 2.. Vol. 1 - 1116537 DOC ID: 1116537 IMAGED  
DATE: 3/1/1999 PAGES: 12  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION: Stormwater sampling analytical results.

1. 8. 2.. Vol. 1 - 1116933 DOC ID: 1116933 IMAGED  
DATE: 3/5/1999 PAGES: 50  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION: Analytical results for water samples collected at the City of Sheridan intake.

1. 8. 2.. Vol. 1 - 1116538 DOC ID: 1116538 IMAGED  
DATE: 6/24/1999 PAGES: 22  
AUTHOR(S): Chris Pace/EPA ADDRESSEE(S): Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 18 water samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116539 DOC ID: 1116539 IMAGED  
DATE: 6/25/1999 PAGES: 38  
AUTHOR(S): Chris Pace/EPA ADDRESSEE(S): Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 20 soil samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116540 DOC ID: 1116540 IMAGED  
DATE: 6/28/1999 PAGES: 24  
AUTHOR(S): Chris Pace/EPA ADDRESSEE(S): Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 20 soil samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116541 DOC ID: 1116541 IMAGED  
DATE: 6/29/1999 PAGES: 24  
AUTHOR(S): Chris Pace/EPA ADDRESSEE(S): Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 20 soil samples, Case 27027.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 8. 2.. Vol. 1 - 1116542 DOC ID: 1116542 IMAGED  
DATE: 6/29/1999 PAGES: 24  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 20 soil samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116543 DOC ID: 1116543 IMAGED  
DATE: 7/1/1999 PAGES: 24  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 20 water samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116544 DOC ID: 1116544 IMAGED  
DATE: 7/2/1999 PAGES: 24  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 20 water samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116545 DOC ID: 1116545 IMAGED  
DATE: 7/2/1999 PAGES: 6  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of two water samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116546 DOC ID: 1116546 IMAGED  
DATE: 7/6/1999 PAGES: 24  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 20 soil samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116547 DOC ID: 1116547 IMAGED  
DATE: 7/22/1999 PAGES: 16  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 11 soil and one water samples, Case 27084.

1. 8. 2.. Vol. 1 - 1116548 DOC ID: 1116548 IMAGED  
DATE: 7/22/1999 PAGES: 21  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Chris Pace/EPA

Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 15 soil and two water samples, Case 27084.

1. 8. 2.. Vol. 1 - 1116549 DOC ID: 1116549 IMAGED  
DATE: 7/23/1999 PAGES: 16  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 12 soil samples, Case 27084.

1. 8. 2.. Vol. 1 - 1116550 DOC ID: 1116550 IMAGED  
DATE: 7/23/1999 PAGES: 25  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 20 soil samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116551 DOC ID: 1116551 IMAGED  
DATE: 7/23/1999 PAGES: 24  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 19 soil and one water samples, Case 27084.

1. 8. 2.. Vol. 1 - 1116552 DOC ID: 1116552 IMAGED  
DATE: 7/25/1999 PAGES: 9  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of five soil samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116553 DOC ID: 1116553 IMAGED  
DATE: 7/25/1999 PAGES: 25  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION: Memo transmits a quality assurance review of 20 soil samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116554 DOC ID: 1116554 IMAGED  
DATE: 7/26/1999 PAGES: 440  
AUTHOR(S): ADDRESSEE(S):  
Gerald H. Dodo/EPA Mark A. Ader/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo transmits a quality assurance data validation report for the polynuclear aromatic hydrocarbon screening analysis results for soil samples.

1. 8. 2.. Vol. 1 - 1116555 DOC ID: 1116555 IMAGED  
DATE: 7/28/1999 PAGES: 114  
AUTHOR(S): ADDRESSSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION:

Memo transmits a quality assurance review of 20 water samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116556 DOC ID: 1116556 IMAGED  
DATE: 7/29/1999 PAGES: 31  
AUTHOR(S): ADDRESSSEE(S):  
Peggy Knight/EPA Arthur D. Baker/EPA

DESCRIPTION:

Memo transmits a quality assurance review of four water samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116557 DOC ID: 1116557 IMAGED  
DATE: 7/29/1999 PAGES: 104  
AUTHOR(S): ADDRESSSEE(S):  
Peggy Knight/EPA Arthur D. Baker/EPA

DESCRIPTION:

Memo transmits a quality assurance review of 20 water samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116558 DOC ID: 1116558 IMAGED  
DATE: 7/29/1999 PAGES: 65  
AUTHOR(S): ADDRESSSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION:

Memo transmits a quality assurance review of 20 soil samples, Case 27027.

1. 8. 2.. Vol. 1 - 1116559 DOC ID: 1116559 IMAGED  
DATE: 7/30/1999 PAGES: 440  
AUTHOR(S): ADDRESSSEE(S):  
Gerald H. Dodo/EPA Mark A. Ader/EPA

DESCRIPTION:

Memo transmits a quality assurance validation report for pentachlorophenol screening results for soil samples.

1. 8. 2.. Vol. 1 - 1116560 DOC ID: 1116560 IMAGED  
DATE: 8/16/1999 PAGES: 435  
AUTHOR(S): ADDRESSSEE(S):  
EPA EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Combined Final Report for Project TEC-440F (soil samples).

1. 8. 2.. Vol. 1 - 1116931 DOC ID: 1116931 IMAGED  
DATE: 12/29/1999 PAGES: 37  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION:

Soil profile analytical data for stockpile soils.

1. 8. 2.. Vol. 1 - 1124033 DOC ID: 1124033 IMAGED  
DATE: 4/6/2000 PAGES: 31  
AUTHOR(S): ADDRESSEE(S):  
Noah H. Myers/Ecology & Environment, Inc. Michael Sibley/EPA

DESCRIPTION:

Air Sample Analytical Data.

1. 8. 2.. Vol. 1 - DOC ID: 1150113 IMAGED  
DATE: 6/19/2000 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Gerald H. Dodo/EPA Michael Sibley/EPA

DESCRIPTION:

Memo reporting data validation of pentachlorophenol screening results.

1. 8. 2.. Vol. 1 - 1116991 DOC ID: 1116991 IMAGED  
DATE: 6/20/2000 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Gerald H. Dodo/EPA Michael Sibley/EPA

DESCRIPTION:

Report of data validation of polynuclear aromatic hydrocarbon screening results for soil samples.

1. 8. 2.. Vol. 1 - DOC ID: 1150116 IMAGED  
DATE: 6/23/2000 PAGES: 101  
AUTHOR(S): ADDRESSEE(S):  
EPA EPA

DESCRIPTION:

Report by Parameter for Project TEC-440G.

1. 8. 2.. Vol. 1 - 1124010 DOC ID: 1124010 IMAGED  
DATE: 6/27/2000 PAGES: 101  
AUTHOR(S): ADDRESSEE(S):  
EPA EPA

DESCRIPTION:

Analytical Data Report by Parameter for Project TEC-440G (Solid).

1. 8. 2.. Vol. 1 -	DOC ID: 1150114	IMAGED
DATE: 6/28/2000	PAGES: 103	
AUTHOR(S): EPA		ADDRESSEE(S): EPA

1. 8. 2.. Vol. 1 -	1124032	DOC ID:	1124032	IMAGED
DATE:	11/16/2000	PAGES:	25	
AUTHOR(S):				ADDRESSEE(S):
Columbia Analytical Services, Inc.				Unknown

1. 8. 3.. Vol. 1 -	1116463	DOC ID:	1116463	IMAGED
DATE:	10/15/1988	PAGES:	4	
AUTHOR(S):				ADDRESSEE(S):
Karl A. Morgenstern/Ecology & Environment, Inc.				Unknown

1. 8. 3.. Vol. 1 - 1116464 DOC ID: 1116464 IMAGED  
DATE: 10/17/1988 PAGES: 4  
AUTHOR(S): Karl A. Morgenstern/Ecology & Environment, Inc. ADDRESSEE(S): Associated Laboratories, Inc.

1. 8. 3.. Vol. 1 - 1116465 DOC ID: 1116465 IMAGED  
DATE: 11/22/1988 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
Karl A. Morgenstern/Ecology & Environment, Inc. Unknown

1. 8. 3.. Vol. 1 -	1116466	DOC ID:	1116466	IMAGED
DATE:	3/25/1989	PAGES:	1	
AUTHOR(S):				ADDRESSEE(S):
Ecology & Environment, Inc.				Unknown

Page 1-26

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 8. 3.. Vol. 1 - 1116467 DOC ID: 1116467 IMAGED  
DATE: 8/14/1989 PAGES: 12  
AUTHOR(S): Karl A. Morgenstern/Ecology & Environment, Inc. ADDRESSEE(S):  
EPA

Jerry Lee/Ecology & Environment, Inc.

DESCRIPTION: Sample Tracking Report, Case No. 12523 and 4846J.

1. 8. 3.. Vol. 1 - 1116468 DOC ID: 1116468 IMAGED  
DATE: 8/14/1989 PAGES: 15  
AUTHOR(S): Jerry Lee/Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Field Sample Data and Chain of Custody Sheet.

1. 8. 3.. Vol. 1 - 1116469 DOC ID: 1116469 IMAGED  
DATE: 8/15/1989 PAGES: 30  
AUTHOR(S): Karl A. Morgenstern/Ecology & Environment, Inc. ADDRESSEE(S):  
Enseco Rocky Mountain Analytical

DESCRIPTION: Inorganic Traffic Report, Case No. 12523.

1. 8. 3.. Vol. 1 - 1116471 DOC ID: 1116471 IMAGED  
DATE: 8/15/1989 PAGES: 21  
AUTHOR(S): Karl A. Morgenstern/Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Field Sample Data and Chain of Custody Sheet, Case No. 12523.

1. 8. 3.. Vol. 1 - 1116472 DOC ID: 1116472 IMAGED  
DATE: 8/16/1989 PAGES: 4  
AUTHOR(S): Jerry Lee/Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Receipt for Samples.

1. 8. 3.. Vol. 1 - 1116473 DOC ID: 1116473 IMAGED  
DATE: 8/21/1989 PAGES: 8  
AUTHOR(S): Karl A. Morgenstern/Ecology & Environment, Inc. ADDRESSEE(S):  
Silver Valley Analytical Laboratory

DESCRIPTION: Sample Packing List, SAS 4846J.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 8. 3.. Vol. 1 - 1116474 DOC ID: 1116474 IMAGED  
DATE: 8/21/1989 PAGES: 8  
AUTHOR(S): ADDRESSSEE(S):  
Jerry Lee/Ecology & Environment, Inc. Unknown

DESCRIPTION: Field Sample Data and Chain of Custody Sheet, SAS 4846J.

**SUB-HEAD: 1. 8. 4.. Vol. 1 - Field Log Books**

1. 8. 4.. Vol. 1 - 1124041 DOC ID: 1124041 IMAGED  
DATE: 3/23/1999 PAGES: 40  
AUTHOR(S): ADDRESSSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book #2: P.M.

1. 8. 4.. Vol. 1 - 1124040 DOC ID: 1124040 IMAGED  
DATE: 4/12/1999 PAGES: 52  
AUTHOR(S): ADDRESSSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book #1: Site Visit.

1. 8. 4.. Vol. 1 - 1124042 DOC ID: 1124042 IMAGED  
DATE: 5/16/1999 PAGES: 103  
AUTHOR(S): ADDRESSSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book #3: Site Management.

1. 8. 4.. Vol. 1 - 1124043 DOC ID: 1124043 IMAGED  
DATE: 5/17/1999 PAGES: 40  
AUTHOR(S): ADDRESSSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book #4: Sampling and Photo Log, ESAT Geoprobe.

1. 8. 4.. Vol. 1 - 1124044 DOC ID: 1124044 IMAGED  
DATE: 5/17/1999 PAGES: 40  
AUTHOR(S): ADDRESSSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book #5: Sampling and Photo Log, E&E Geoprobe.



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 8. 4.. Vol. 1 - 1124045 DOC ID: 1124045 IMAGED  
DATE: 5/22/1999 PAGES: 50  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Log Book #6: Sample and Photo Log, Residential Soil and Water Sampling, Yamhill River  
Sediment and Surface Water Sampling, Overland Surface Water Pathway Samples, Ditch and  
Rock Creek Sampling.

1. 8. 4.. Vol. 1 - 1124046 DOC ID: 1124046 IMAGED  
DATE: 5/24/1999 PAGES: 3  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Log Book #7: Calibration Log.

1. 8. 4.. Vol. 1 - 1124047 DOC ID: 1124047 IMAGED  
DATE: 5/24/1999 PAGES: 50  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Log Book #8: On Site Groundwater and Product Sampling.

1. 8. 4.. Vol. 1 - 1124048 DOC ID: 1124048 IMAGED  
DATE: 5/24/1999 PAGES: 22  
AUTHOR(S): Dave Franzen/Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Log Book: Dave Franzen Daily Log, AOC/SWMU.

1. 8. 4.. Vol. 1 - 1124049 DOC ID: 1124049 IMAGED  
DATE: 5/26/1999 PAGES: 19  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Log Book #9: Personal Data RAM Calibration Logbook.

1. 8. 4.. Vol. 1 - 1124050 DOC ID: 1124050 IMAGED  
DATE: 5/28/1999 PAGES: 40  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Log Book #10: Sampling and Photo Log, E&E Geoprobe.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 8. 4.. Vol. 1 - 1124051 DOC ID: 1124051 IMAGED  
DATE: 5/28/1999 PAGES: 41  
AUTHOR(S): ADDRESSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book #11: Sampling and Photo Log, ESAT Geoprobe, Containment Tables.

1. 8. 4.. Vol. 1 - 1124052 DOC ID: 1124052 IMAGED  
DATE: 6/3/1999 PAGES: 17  
AUTHOR(S): ADDRESSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book #12: Sampling and Photo Log, Surface Water Pathway Sampling, GPS Data Collection, Containment Evaluation.

1. 8. 4.. Vol. 1 - 1124053 DOC ID: 1124053 IMAGED  
DATE: 6/4/1999 PAGES: 39  
AUTHOR(S): ADDRESSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book #13: Sampling and Photo Log, SW/Sed Sampling, Wetland Evaluation.

1. 8. 4.. Vol. 1 - 1124054 DOC ID: 1124054 IMAGED  
DATE: 6/9/1999 PAGES: 10  
AUTHOR(S): ADDRESSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book: Photo Log of SWMU and AOC Investigation.

1. 8. 4.. Vol. 1 - 1124055 DOC ID: 1124055 IMAGED  
DATE: 6/10/1999 PAGES: 9  
AUTHOR(S): ADDRESSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book #14: Sampling and Photo Log, E&E Geoprobe.

1. 8. 4.. Vol. 1 - 1124056 DOC ID: 1124056 IMAGED  
DATE: 8/12/1999 PAGES: 49  
AUTHOR(S): ADDRESSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Log Book: Taylor Air.

1. 8. 4.. Vol. 1 - 1124057 DOC ID: 1124057 IMAGED  
DATE: 8/19/1999 PAGES: 39  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Ecology & Environment, Inc.

Unknown

DESCRIPTION: Log Book: Air Sampling.

1. 8. 4.. Vol. 1 - 1124058 DOC ID: 1124058 IMAGED  
DATE: 8/21/1999 PAGES: 15  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Log Book: Air Sampling Project.

1. 8. 4.. Vol. 1 - DOC ID: 1167078 IMAGED  
DATE: 10/25/1999 PAGES: 7  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: XRF Field Log Book (Book 2) associated with TDD: 99-09-0019. (Existence of Book 1 unknown)

**SUB-HEAD: 1. 8. 5.. Vol. 1 - Water Well Reports**

1. 8. 5.. Vol. 1 - 1124161 DOC ID: 1124161 IMAGED  
DATE: PAGES: 83  
AUTHOR(S): Unknown ADDRESSEE(S):  
State of Oregon

DESCRIPTION: Water Well Reports.

1. 8. 5.. Vol. 1 - 1124162 DOC ID: 1124162 IMAGED  
DATE: PAGES: 7  
AUTHOR(S): Unknown ADDRESSEE(S):  
State of Oregon

DESCRIPTION: Water Well Reports; one quarter mile.

1. 8. 5.. Vol. 1 - 1124163 DOC ID: 1124163 IMAGED  
DATE: PAGES: 27  
AUTHOR(S): Unknown ADDRESSEE(S):  
State of Oregon

DESCRIPTION: Water Well Reports; one half mile.

1. 8. 5.. Vol. 1 - 1124164 DOC ID: 1124164 IMAGED  
DATE: PAGES: 17  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Unknown

State of Oregon

DESCRIPTION: Water Well Reports; one mile.

1. 8. 5.. Vol. 1 - 1124165 DOC ID: 1124165 IMAGED  
DATE: PAGES: 10  
AUTHOR(S): ADDRESSEE(S):  
Unknown State of Oregon

DESCRIPTION: Water Well Reports; two miles.

1. 8. 5.. Vol. 1 - 1124166 DOC ID: 1124166 IMAGED  
DATE: PAGES: 134  
AUTHOR(S): ADDRESSEE(S):  
Unknown State of Oregon

DESCRIPTION: Water Well Reports; three miles.

1. 8. 5.. Vol. 1 - 1124167 DOC ID: 1124167 IMAGED  
DATE: PAGES: 110  
AUTHOR(S): ADDRESSEE(S):  
Unknown State of Oregon

DESCRIPTION: Water Well Reports; four miles.

**SUB-HEAD: 1. 8. 6.. Vol. 1 - Geophysical Survey Report**

1. 8. 6.. Vol. 1 - 1124015 DOC ID: 1124015 IMAGED  
DATE: 8/1/2000 PAGES: 19  
AUTHOR(S): ADDRESSEE(S):  
EPA EPA

DESCRIPTION: Geophysical Survey Report.

**SUB-HEAD: 1. 9... Vol. 1 - Pre-NPL Removal Activities**

**SUB-HEAD: 1. 9. 1.. Vol. 1 - Correspondence**

**SUB-HEAD: 1. 9. 1. 1. Vol. 1 - Formal Correspondence**

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 1. 1. Vol. 1 - 1127726 DOC ID: 1127726 IMAGED  
DATE: 6/1/1998 PAGES: 4  
AUTHOR(S): Unknown ADDRESSEE(S):  
Unknown

DESCRIPTION: Outline summarizes the responsibilities and authority of each organization involved in construction QA/QC administration.

1. 9. 1. 1. Vol. 1 - 1124017 DOC ID: 1124017 IMAGED  
DATE: 5/5/1999 PAGES: 2  
AUTHOR(S): Ginna Grepo-Grove/EPA ADDRESSEE(S):  
Mark A. Ader/EPA  
Carl G. Kitz/EPA  
Michael Sibley/EPA

DESCRIPTION: Memo comments on the quality assurance review of the Sampling and Quality Assurance Plan for the combined Removal and Site Assessment of Taylor Lumber and Treating.

1. 9. 1. 1. Vol. 1 - 1124176 DOC ID: 1124176 IMAGED  
DATE: 6/3/1999 PAGES: 6  
AUTHOR(S): Unknown ADDRESSEE(S):  
Unknown

DESCRIPTION: AFS Compliance Source Data Report-SV Program.

Note: Pages 1 and 2 are missing.

1. 9. 1. 1. Vol. 1 - 1124177 DOC ID: 1124177 IMAGED  
DATE: 6/7/1999 PAGES: 3  
AUTHOR(S): Kristin Clayton/Waste Management, Inc. ADDRESSEE(S):  
Jeffrey Fowlow/Ecology & Environment, Inc.

DESCRIPTION: Fax memo transmits a waste disposal agreement.

1. 9. 1. 1. Vol. 1 - 1124178 DOC ID: 1124178 IMAGED  
DATE: 6/9/1999 PAGES: 2  
AUTHOR(S): Kristin Clayton/Waste Management, Inc. ADDRESSEE(S):  
Jeffrey Fowlow/Ecology & Environment, Inc.

DESCRIPTION: Fax memo transmits a permit to dispose of non-hazardous materials.

1. 9. 1. 1. Vol. 1 - 1116373 DOC ID: 1116373 IMAGED  
DATE: 6/18/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S):  
Annette Franzen/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo reports completing organic data quality assurance summary checks of 52 soil samples.

1. 9. 1. 1. Vol. 1 - 1116374 DOC ID: 1116374 IMAGED  
DATE: 7/7/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary checks of five oil samples.

1. 9. 1. 1. Vol. 1 - 1116375 DOC ID: 1116375 IMAGED  
DATE: 7/7/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary checks of 12 water samples.

1. 9. 1. 1. Vol. 1 - 1116376 DOC ID: 1116376 IMAGED  
DATE: 7/7/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary checks of 69 soil samples.

1. 9. 1. 1. Vol. 1 - 1116377 DOC ID: 1116377 IMAGED  
DATE: 7/16/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing inorganic data quality assurance summary checks of 60 water and 100 soil samples.

1. 9. 1. 1. Vol. 1 - 1116379 DOC ID: 1116379 IMAGED  
DATE: 7/28/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary reviews of 20 soil samples.

1. 9. 1. 1. Vol. 1 - 1116380 DOC ID: 1116380 IMAGED  
DATE: 7/28/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo reports completing organic data quality assurance summary reviews of 20 water samples.

1. 9. 1. 1. Vol. 1 - 1116381 DOC ID: 1116381 IMAGED  
DATE: 7/28/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary reviews of 20 water samples.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167079 IMAGED  
DATE: 7/28/1999 PAGES: 60  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc. ADDRESSEE(S): Bryson Twidwell/Oregon State Dept. of Environmental Quality

DESCRIPTION:

Application for renewal of a National Pollutant Discharge Elimination System Permit.

1. 9. 1. 1. Vol. 1 - 1116382 DOC ID: 1116382 IMAGED  
DATE: 7/30/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic and inorganic data quality assurance summary reviews of one liquid and two solid samples.

1. 9. 1. 1. Vol. 1 - 1116383 DOC ID: 1116383 IMAGED  
DATE: 7/30/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary reviews of six soil samples.

1. 9. 1. 1. Vol. 1 - 1116384 DOC ID: 1116384 IMAGED  
DATE: 7/30/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary reviews of 20 soil samples.

1. 9. 1. 1. Vol. 1 - 1116385 DOC ID: 1116385 IMAGED  
DATE: 7/30/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo reports completing inorganic data quality assurance summary checks of eight soil samples.

1. 9. 1. 1. Vol. 1 - 1116386 DOC ID: 1116386 IMAGED  
DATE: 7/30/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing inorganic data quality assurance summary checks of 15 soil samples.

1. 9. 1. 1. Vol. 1 - 1116323 DOC ID: 1116323 IMAGED  
DATE: 8/6/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary reviews of five water and 15 soil samples.

1. 9. 1. 1. Vol. 1 - 1116432 DOC ID: 1116432 IMAGED  
DATE: 8/6/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing inorganic data quality assurance summary reviews of four water and 102 soil samples.

1. 9. 1. 1. Vol. 1 - 1116416 DOC ID: 1116416 IMAGED  
DATE: 8/9/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary reviews of three water and 37 soil samples.

1. 9. 1. 1. Vol. 1 - 1116388 DOC ID: 1116388 IMAGED  
DATE: 8/12/1999 PAGES: 1  
AUTHOR(S): Alasdair Turner/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing inorganic data quality assurance summary reviews of 12 soil samples.

1. 9. 1. 1. Vol. 1 - 1116389 DOC ID: 1116389 IMAGED  
DATE: 8/16/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo reports completing data quality assurance summary checks of 12 soil samples.

1. 9. 1. 1. Vol. 1 - 1116390 DOC ID: 1116390 IMAGED  
DATE: 8/16/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing data quality assurance summary checks of 20 soil samples.

1. 9. 1. 1. Vol. 1 - 1127727 DOC ID: 1127727 IMAGED  
DATE: 8/17/1999 PAGES: 8  
AUTHOR(S): Suzanne Dolberg/Ecology & Environment, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Memo provides the EPA with general information about removal alternatives.

1. 9. 1. 1. Vol. 1 - 1116326 DOC ID: 1116326 IMAGED  
DATE: 8/25/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary checks for pentachlorophenol in soil samples.

1. 9. 1. 1. Vol. 1 - 1116327 DOC ID: 1116327 IMAGED  
DATE: 8/25/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary checks for polynuclear aromatic hydrocarbons in soil samples.

1. 9. 1. 1. Vol. 1 - 1116391 DOC ID: 1116391 IMAGED  
DATE: 8/25/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing inorganic data quality assurance summary checks of six soil samples.

1. 9. 1. 1. Vol. 1 - 1116392 DOC ID: 1116392 IMAGED  
DATE: 8/25/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo reports completing organic data quality assurance summary checks of 20 soil samples.

1. 9. 1. 1. Vol. 1 - 1114282 DOC ID: 1114282 IMAGED  
DATE: 9/7/1999 PAGES: 4  
AUTHOR(S): Noah H. Myers/Ecology & Environment, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Memorandum outlining proposed approach to removal actions at Taylor Lumber and Treating site.

1. 9. 1. 1. Vol. 1 - 1116393 DOC ID: 1116393 IMAGED  
DATE: 9/20/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing data quality assurance summary checks of six soil samples.

1. 9. 1. 1. Vol. 1 - 1116394 DOC ID: 1116394 IMAGED  
DATE: 9/20/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing data quality assurance summary checks of 19 soil samples.

1. 9. 1. 1. Vol. 1 - 1116395 DOC ID: 1116395 IMAGED  
DATE: 9/20/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing data quality assurance summary checks of two soil samples.

1. 9. 1. 1. Vol. 1 - 1116396 DOC ID: 1116396 IMAGED  
DATE: 9/23/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary reviews of 19 soil/sediment samples.

1. 9. 1. 1. Vol. 1 - 1116397 DOC ID: 1116397 IMAGED  
DATE: 9/23/1999 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo reports completing organic data quality assurance summary reviews of 20 water samples.

1. 9. 1. 1. Vol. 1 - 1116398 DOC ID: 1116398 IMAGED  
DATE: 10/11/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing data quality assurance summary checks of 26 soil and six water samples.

1. 9. 1. 1. Vol. 1 - 1127686 DOC ID: 1127686 IMAGED  
DATE: 10/18/1999 PAGES: 2  
AUTHOR(S): Michael F. Gearheard/EPA ADDRESSEE(S): Bruce Summers/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter discusses the removal plan and the Action Memo. (Less enclosure)

1. 9. 1. 1. Vol. 1 - 1127696 DOC ID: 1127696 IMAGED  
DATE: 10/21/1999 PAGES: 2  
AUTHOR(S): Vince Gullette/Taylor Lumber and Treating, Inc. ADDRESSEE(S): Michael F. Gearheard/EPA

DESCRIPTION:

Letter discusses the removal action.

1. 9. 1. 1. Vol. 1 - 1116399 DOC ID: 1116399 IMAGED  
DATE: 10/22/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing data quality assurance summary checks of two product samples.

1. 9. 1. 1. Vol. 1 - 1116928 DOC ID: 1116928 IMAGED  
DATE: 11/5/1999 PAGES: 1  
AUTHOR(S): Michael Sibley/EPA ADDRESSEE(S): Bruce Summers/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter transmitting the Quality Assurance Project Plan. (Less attachment)

1. 9. 1. 1. Vol. 1 - 1116400 DOC ID: 1116400 IMAGED  
DATE: 11/8/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo reports completing organic data quality assurance summary checks of eight water and 30 soil/sediment samples.

1. 9. 1. 1. Vol. 1 - 1116401 DOC ID: 1116401 IMAGED  
DATE: 11/11/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Memo reports completing organic data quality assurance summary checks of two bulk and nine soil samples.

1. 9. 1. 1. Vol. 1 - 1127697 DOC ID: 1127697 IMAGED  
DATE: 11/15/1999 PAGES: 28  
AUTHOR(S): Annette Sackman-Franzen/Ecology & Environment, Inc. ADDRESSEE(S): Steven P. Taylor/Maul Foster & Alongi, Inc.

DESCRIPTION:

Letter transmitting draft abandonment borehole logs for the Integrated Assessment.

1. 9. 1. 1. Vol. 1 - 1127718 DOC ID: 1127718 IMAGED  
DATE: 11/23/1999 PAGES: 12  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Fax transmitting employee training information from Sumco Excavating.

1. 9. 1. 1. Vol. 1 - 1116970 DOC ID: 1116970 IMAGED  
DATE: 12/14/1999 PAGES: 2  
AUTHOR(S): Unknown ADDRESSEE(S): Unknown

DESCRIPTION:

Schedule for the Taylor Lumber Removal Action.

1. 9. 1. 1. Vol. 1 - 1127699 DOC ID: 1127699 IMAGED  
DATE: 1/1/2000 PAGES: 1  
AUTHOR(S): Unknown ADDRESSEE(S): Unknown

DESCRIPTION:

Memo outlines job information, Job No. 030159-0001.

Note: Document date is estimated.

1. 9. 1. 1. Vol. 1 - 1127700 DOC ID: 1127700 IMAGED  
DATE: 1/4/2000 PAGES: 2  
AUTHOR(S): Michael Sibley/EPA ADDRESSEE(S): Bruce Summers/Taylor Lumber and Treating, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Letter approves the Ditch Excavation Plan.

1. 9. 1. 1. Vol. 1 - 1124024 DOC ID: 1124024 IMAGED  
DATE: 3/4/2000 PAGES: 2  
AUTHOR(S): Noah H. Myers/Ecology & Environment, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Letter transmits a memo summarizing a review of the retort slab design.

1. 9. 1. 1. Vol. 1 - 1116406 DOC ID: 1116406 IMAGED  
DATE: 3/7/2000 PAGES: 2  
AUTHOR(S): Michael Sibley/EPA ADDRESSEE(S): Bruce Summers/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter disapproves the Surface Water Runoff Inspection and Maintenance Plan.

1. 9. 1. 1. Vol. 1 - 1124025 DOC ID: 1124025 IMAGED  
DATE: 3/9/2000 PAGES: 1  
AUTHOR(S): Greg Powell/EPA ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Memo discusses the hydrogeologic conditions at the site.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167080 IMAGED  
DATE: 3/21/2000 PAGES: 64  
AUTHOR(S): Recep Yilmaz/Fugro Geosciences, Inc. ADDRESSEE(S): Ron McManamy/Environmental Quality Management, Inc.

DESCRIPTION:

Data report for Cone Penetration and Rapid Optical Screening Tool testing.

1. 9. 1. 1. Vol. 1 - 1116971 DOC ID: 1116971 IMAGED  
DATE: 3/30/2000 PAGES: 23  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Letter transmits and discusses the revised Surface Water Runoff Inspection and Maintenance Plan.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167081 IMAGED  
DATE: 3/30/2000 PAGES: 23  
AUTHOR(S): Gary Chow/Unknown ADDRESSEE(S): Roger Culleton/Ecology & Environment, Inc.  
Alan Noell/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo with attached comments for the Groundwater Characterization Report.

1. 9. 1. 1. Vol. 1 - 1116972 DOC ID: 1116972 IMAGED  
DATE: 4/14/2000 PAGES: 2  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S):  
Beth Sheldrake/EPA

DESCRIPTION:

Letter transmits START's comments regarding the Asphalt Cover Inspection and Maintenance Plan.

1. 9. 1. 1. Vol. 1 - 1116973 DOC ID: 1116973 IMAGED  
DATE: 5/3/2000 PAGES: 8  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S):  
Beth Sheldrake/EPA

DESCRIPTION:

Letter transmits the revised Scope of Work for drilling services.

1. 9. 1. 1. Vol. 1 - 1116974 DOC ID: 1116974 IMAGED  
DATE: 5/17/2000 PAGES: 2  
AUTHOR(S): Michael Sibley/EPA ADDRESSEE(S):  
Bruce Summers/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter approves the Surface Water Runoff Inspection and Maintenance Plan, and the Concrete Retort Rail Cart Slab Design.

1. 9. 1. 1. Vol. 1 - 1116975 DOC ID: 1116975 IMAGED  
DATE: 6/14/2000 PAGES: 2  
AUTHOR(S): Roger Culleton/Ecology & Environment, Inc. ADDRESSEE(S):  
Michael Sibley/EPA  
Steven P. Taylor/Maul Foster & Alongi, Inc.

DESCRIPTION:

Fax memo transmits details for the slurry wall.

1. 9. 1. 1. Vol. 1 - 1124005 DOC ID: 1124005 IMAGED  
DATE: 6/19/2000 PAGES: 12  
AUTHOR(S): Gordon Randall/Ecology & Environment, Inc. ADDRESSEE(S):  
Roger Culleton/Ecology & Environment, Inc.  
Julie Wroble/Ecology & Environment, Inc.

DESCRIPTION:

Technical Memorandum analyzes the particulate inhalation risks during removal action.

1. 9. 1. 1. Vol. 1 - 1124006 DOC ID: 1124006 IMAGED  
DATE: 6/20/2000 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Jeffrey Fowlow/Ecology & Environment, Inc.

Beth Sheldrake/EPA

DESCRIPTION:

Letter transmits a Technical Memorandum on particulate inhalation risks to provide data to define the area to be paved. (Less enclosure)

1. 9. 1. 1. Vol. 1 - 1116976 DOC ID: 1116976 IMAGED  
DATE: 6/23/2000 PAGES: 9  
AUTHOR(S): Marcia L. Bailey/EPA ADDRESSEE(S): Michael Slater/EPA

DESCRIPTION:

Email discusses the excess cancer risks calculated for the soil pile.

1. 9. 1. 1. Vol. 1 - 1116977 DOC ID: 1116977 IMAGED  
DATE: 6/28/2000 PAGES: 1  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S): Beth Sheldrake/EPA

DESCRIPTION:

Letter transmits START's Technical Specifications and Detailed Design Drawings for installation of a Soil Bentonite Slurry Trench Cutoff Wall.

1. 9. 1. 1. Vol. 1 - 1124007 DOC ID: 1124007 IMAGED  
DATE: 6/30/2000 PAGES: 2  
AUTHOR(S): Michael Sibley/EPA ADDRESSEE(S): Bruce Summers/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter discusses installation of the concrete retort rail slab.

1. 9. 1. 1. Vol. 1 - 1124034 DOC ID: 1124034 IMAGED  
DATE: 7/3/2000 PAGES: 1  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S): Beth Sheldrake/EPA

DESCRIPTION:

Letter transmits two replacement drawings for the Removal Action Investigation Technical Specifications for the Soil-Bentonite Slurry Trench Cutoff Wall.

Note: Replacement drawings are inserted in the referenced document and original drawings destroyed per instructions.

1. 9. 1. 1. Vol. 1 - 1116979 DOC ID: 1116979 IMAGED  
DATE: 7/19/2000 PAGES: 2  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S): Beth Sheldrake/EPA

DESCRIPTION:

Letter transmits amendments to Section 02260 Soil Bentonite Wall Construction.

1. 9. 1. 1. Vol. 1 - 1124008 DOC ID: 1124008 IMAGED  
DATE: 7/24/2000 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Carl G. Kitz/EPA

Roland Mueller/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter clarifies issues regarding removal work scheduled to start July 19, 2000.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167082 IMAGED  
DATE: 8/4/2000 PAGES: 6  
AUTHOR(S): Jason Coury/Environmental Quality Management, Inc. ADDRESSEE(S):  
Roger Culleton/Ecology & Environment, Inc.

DESCRIPTION:

Letter describing the two containment cells.

1. 9. 1. 1. Vol. 1 - 1124026 DOC ID: 1124026 IMAGED  
DATE: 8/8/2000 PAGES: 1  
AUTHOR(S): Jason Coury/Environmental Quality Management, Inc. ADDRESSEE(S):  
Roger Culleton/Ecology & Environment, Inc.

DESCRIPTION:

Letter discusses timelines and processes for installing air lines and water discharge lines for groundwater extraction wells.

1. 9. 1. 1. Vol. 1 - 1127701 DOC ID: 1127701 IMAGED  
DATE: 8/8/2000 PAGES: 1  
AUTHOR(S): Jason Coury/Environmental Quality Management, Inc. ADDRESSEE(S):  
Roger Culleton/Ecology & Environment, Inc.

DESCRIPTION:

Letter discusses the Addendum to the RFP for the Wearing Course Pavement.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167083 IMAGED  
DATE: 8/9/2000 PAGES: 1  
AUTHOR(S): Jason Coury/Environmental Quality Management, Inc. ADDRESSEE(S):  
Roger Culleton/Ecology & Environment, Inc.

DESCRIPTION:

Letter regarding hauling and stockpiling excavated material from the slurry wall.

1. 9. 1. 1. Vol. 1 - 1127702 DOC ID: 1127702 IMAGED  
DATE: 8/11/2000 PAGES: 5  
AUTHOR(S): Ron McManamy/Environmental Quality Management, Inc. ADDRESSEE(S):  
Jason Nesseth/Environmental Reclamation, Inc.

DESCRIPTION:

Letter reviews the Construction Operation Plan and Submittals, Soil-Bentonite Slurry Wall Construction.

1. 9. 1. 1. Vol. 1 - 1127703 DOC ID: 1127703 IMAGED  
DATE: 8/21/2000 PAGES: 1  
AUTHOR(S): Ron McManamy/Environmental Quality Management, Inc. ADDRESSEE(S):  
Jason Nesseth/Environmental Reclamation, Inc.



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Letter gives notice of termination of subcontract.

1. 9. 1. 1. Vol. 1 - 1124014 DOC ID: 1124014 IMAGED  
DATE: 8/30/2000 PAGES: 17  
AUTHOR(S): Michael Sibley/EPA ADDRESSEE(S): File

DESCRIPTION:

Memo documents the designation of an area of contamination at the removal site.

1. 9. 1. 1. Vol. 1 - 1127704 DOC ID: 1127704 IMAGED  
DATE: 9/7/2000 PAGES: 2  
AUTHOR(S): Alexander Whitman/Ecology & Environment, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Memo responds to comments on the pavement design.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167084 IMAGED  
DATE: 9/7/2000 PAGES: 5  
AUTHOR(S): Stephen Martin/TC Mirafi ADDRESSEE(S): Chad Manterro/Unknown

DESCRIPTION:

Fax memo transmitting design results for the haul road.

1. 9. 1. 1. Vol. 1 - 1127705 DOC ID: 1127705 IMAGED  
DATE: 9/12/2000 PAGES: 1  
AUTHOR(S): Alexander Whitman/Ecology & Environment, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Memo reviews Submittal 002-02511 regarding asphalt paving.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167085 IMAGED  
DATE: 9/13/2000 PAGES: 9  
AUTHOR(S): Josh McKnight/Geo-Con ADDRESSEE(S): Jason Coury/Environmental Quality Management, Inc.

DESCRIPTION:

Letter regarding the Mix Design Report associated with the Cutoff Wall.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167086 IMAGED  
DATE: 9/14/2000 PAGES: 9  
AUTHOR(S): Josh McKnight/Geo-Con ADDRESSEE(S): Jason Coury/Environmental Quality Management, Inc.

DESCRIPTION:

Letter regarding conformance testing for the soil-bentonite backfill material.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 1. 1. Vol. 1 - DOC ID: 1167087 IMAGED  
DATE: 9/15/2000 PAGES: 10  
AUTHOR(S): ADDRESSEE(S):  
Josh McKnight/Geo-Con Jason Coury/Environmental Quality Management,  
Inc.  
DESCRIPTION: Letter certifying each load of bentonite.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167088 IMAGED  
DATE: 9/25/2000 PAGES: 17  
AUTHOR(S): ADDRESSEE(S):  
Brad Miller/CETCO Josh McKnight/Geo-Con

DESCRIPTION: Memo regarding the slurry wall Claymax cap equivalence.

1. 9. 1. 1. Vol. 1 - 1116982 DOC ID: 1116982 IMAGED  
DATE: 10/9/2000 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Steven P. Taylor/Maul Foster & Alongi, Inc. Michael Sibley/EPA  
Roger Culleton/Ecology & Environment, Inc.

DESCRIPTION: Memo discusses pavement calculations.

1. 9. 1. 1. Vol. 1 - 1127706 DOC ID: 1127706 IMAGED  
DATE: 10/10/2000 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
David Brown/Superfund Technical Assessment and Response Team (START) Roland Mueller/Taylor Lumber and Treating, Inc.

DESCRIPTION: Memo discusses analytical methods for soil testing.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167089 IMAGED  
DATE: 10/12/2000 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Connie Winsley/Oregon Culvert Company Environmental Quality Management, Inc.

DESCRIPTION: Memo certifying the culvert pipe and fittings.

1. 9. 1. 1. Vol. 1 - 1116983 DOC ID: 1116983 IMAGED  
DATE: 10/13/2000 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Alexander Whitman/Ecology & Environment, Inc. Michael Sibley/EPA

DESCRIPTION: Memo discusses the design thickness of asphalt pavement.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 1. 1. Vol. 1 - 1124027 DOC ID: 1124027 IMAGED  
DATE: 10/20/2000 PAGES: 3  
AUTHOR(S): Michael Sibley/EPA ADDRESSEE(S):  
Bruce Summers/Taylor Lumber and Treating, Inc.

DESCRIPTION: Letter clarifies the issue concerning design thickness of the asphalt pavement.

1. 9. 1. 1. Vol. 1 - 1116984 DOC ID: 1116984 IMAGED  
DATE: 11/10/2000 PAGES: 1  
AUTHOR(S): Vince Gullette/Taylor Lumber and Treating, Inc. ADDRESSEE(S):  
Jennifer Byrne/EPA

DESCRIPTION: Letter alerts addressee about asphalt pavement problems.

1. 9. 1. 1. Vol. 1 - 1124012 DOC ID: 1124012 IMAGED  
DATE: 11/28/2000 PAGES: 28  
AUTHOR(S): Harry Allen/EPA ADDRESSEE(S):  
Michael Sibley/EPA

DESCRIPTION: Memo transmits a Technical Memorandum discussing evaluation of pentachlorophenol degradative activity in soil samples.

1. 9. 1. 1. Vol. 1 - 1124028 DOC ID: 1124028 IMAGED  
DATE: 12/4/2000 PAGES: 3  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S):  
Beth Sheldrake/EPA

DESCRIPTION: Letter transmits START's review of the certification for the base aggregate used at the Taylor Lumber site.

1. 9. 1. 1. Vol. 1 - 1124029 DOC ID: 1124029 IMAGED  
DATE: 12/15/2000 PAGES: 4  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc. ADDRESSEE(S):  
Michael Sibley/EPA

DESCRIPTION: Letter regarding the final report for removal activities at the Taylor Lumber site.

1. 9. 1. 1. Vol. 1 - 1116985 DOC ID: 1116985 IMAGED  
DATE: 12/21/2000 PAGES: 1  
AUTHOR(S): Vince Gullette/Taylor Lumber and Treating, Inc. ADDRESSEE(S):  
Jennifer Byrne/EPA

DESCRIPTION: Letter alerts addressee about more asphalt pavement problems.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 1. 1. Vol. 1 - 1116986 DOC ID: 1116986 IMAGED  
DATE: 12/28/2000 PAGES: 1  
AUTHOR(S): Vince Gullette/Taylor Lumber and Treating, Inc. ADDRESSEE(S): Jennifer Byrne/EPA

DESCRIPTION: Letter alerts addressee about further asphalt pavement problems.

1. 9. 1. 1. Vol. 1 - 1124030 DOC ID: 1124030 IMAGED  
DATE: 1/10/2001 PAGES: 17  
AUTHOR(S): Roger Culleton/Ecology & Environment, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION: Memo reviews submittals regarding the soil-bentonite wall, asphalt paving, pipe bedding and base course aggregate.

1. 9. 1. 1. Vol. 1 - DOC ID: 1167116 IMAGED  
DATE: 1/22/2001 PAGES: 4  
AUTHOR(S): Jason Coury/Environmental Quality Management, Inc. ADDRESSEE(S): Roger Culleton/Ecology & Environment, Inc.

DESCRIPTION: Handwritten fax memo regarding the plans for Taylor Lumber, and certifications for AMOCO Style 2044 geotextile for the Cutoff Wall.

1. 9. 1. 1. Vol. 1 - DOC ID: 1150952 IMAGED  
DATE: 3/26/2001 PAGES: 2  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S): Michael J. Szerlog/EPA

DESCRIPTION: Letter transmitting an As-Built Survey Plans CD for the Taylor Lumber Site Removal Action completed October 2000. (Less enclosure) TDD: 01-01-0011.

**SUB-HEAD: 1. 9. 4.. Vol. 1 - Action Memoranda**

1. 9. 4.. Vol. 1 - 1088897 DOC ID: 1088897 IMAGED  
DATE: 9/28/1999 PAGES: 23  
AUTHOR(S): Carl G. Kitz/EPA ADDRESSEE(S): Charles C. Clarke/EPA  
Michael Sibley/EPA

DESCRIPTION: Action Memorandum: Request for a Removal Action at the Taylor Lumber and Treating, Inc. Site, Yamhill County, Oregon.

1. 9. 4.. Vol. 1 - 1124013 DOC ID: 1124013 IMAGED  
DATE: 9/18/2000 PAGES: 6  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Michael Sibley/EPA

Michelle Pirzadeh/EPA

DESCRIPTION: Action Memorandum Amendment: Request for a change in the Scope of Work. (Less attachment)

**SUB-HEAD: 1. 9. 5.. Vol. 1 - Work Plan**

1. 9. 5.. Vol. 1 - 1116420 DOC ID: 1116420 IMAGED  
DATE: 10/1/1999 PAGES: 25  
AUTHOR(S): Superfund Technical Assessment and Response Team (START)  
ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION: Removal Action Work Plan.  
Note: Attachment 1, Quality Assurance and Project Plan is not attached.

1. 9. 5.. Vol. 1 - 1116930 DOC ID: 1116930 IMAGED  
DATE: 12/15/1999 PAGES: 18  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc.  
ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION: Letter transmits and discusses the Ditch Excavation Plan.

1. 9. 5.. Vol. 1 - 1086236 DOC ID: 1086236 IMAGED  
DATE: 12/16/1999 PAGES: 8  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc.  
ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION: Plan for Placing a Concrete Cover in the Area of the Retort Tracks at Taylor Lumber and Treating, Inc., Sheridan, Oregon.

1. 9. 5.. Vol. 1 - 1127580 DOC ID: 1127580 IMAGED  
DATE: 1/1/2000 PAGES: 3  
AUTHOR(S): Unknown  
ADDRESSEE(S): Unknown

DESCRIPTION: Table showing Tasks, Status, Due Dates, and Actual Timing.  
Note: Document date is estimated.

1. 9. 5.. Vol. 1 - 1116989 DOC ID: 1116989 IMAGED  
DATE: 1/13/2000 PAGES: 12  
AUTHOR(S): Stricker Engineering  
ADDRESSEE(S): Unknown

DESCRIPTION: Retort Rail Cart Slab Design.

1. 9. 5.. Vol. 1 - 1086237 DOC ID: 1086237 IMAGED  
DATE: 1/14/2000 PAGES: 3  
AUTHOR(S):  
ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Steven P. Taylor/Maul Foster & Alongi, Inc.

Michael Sibley/EPA

DESCRIPTION:

Asphalt Cover Inspection and Maintenance Plan for Taylor Lumber and Treating, Inc., Sheridan, Oregon.

1. 9. 5.. Vol. 1 - 1114261 DOC ID: 1114261 IMAGED

DATE: 2/10/2000 PAGES: 11

AUTHOR(S):

Harry Allen/EPA

ADDRESSEE(S):

Jason Coury/Environmental Quality Management, Inc.

DESCRIPTION:

Faxed transmittal of Work Plan for Taylor Lumber and Treating dated 1/3/00.

1. 9. 5.. Vol. 1 - 1127579 DOC ID: 1127579 IMAGED

DATE: 3/9/2000 PAGES: 8

AUTHOR(S):

Vinod Jayaram/Geo-Con

ADDRESSEE(S):

Jason Coury/Environmental Quality Management, Inc.

DESCRIPTION:

Fax transmitting information on slurry walls.

1. 9. 5.. Vol. 1 - 1127581 DOC ID: 1127581 IMAGED

DATE: 4/17/2000 PAGES: 4

AUTHOR(S):

Unknown

ADDRESSEE(S):

Unknown

DESCRIPTION:

Charts showing Timelines.

Note: Document date is estimated.

1. 9. 5.. Vol. 1 - 1116988 DOC ID: 1116988 IMAGED

DATE: 6/1/2000 PAGES: 130

AUTHOR(S):

Superfund Technical Assessment and Response Team  
(START)

ADDRESSEE(S):

Beth Sheldrake/EPA

DESCRIPTION:

Technical Specifications for the Soil-Bentonite Slurry Trench Cutoff Wall. TDD: 99-09-0019-B.

1. 9. 5.. Vol. 1 - 1124031 DOC ID: 1124031 IMAGED

DATE: 6/15/2000 PAGES: 3

AUTHOR(S):

Unknown

ADDRESSEE(S):

Unknown

DESCRIPTION:

Outline of Taylor Lumber Work Status and Work in Progress.

1. 9. 5.. Vol. 1 - 1114283 DOC ID: 1114283 IMAGED

DATE: 8/23/2000 PAGES: 4

AUTHOR(S):

Unknown

ADDRESSEE(S):

Unknown

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Outline of removal Work in Progress and Planned Field Work with estimated start-completion dates.

**SUB-HEAD: 1. 9. 6.. Vol. 1 - Sampling Plan/QAPP**

1. 9. 6.. Vol. 1 - 1116423 DOC ID: 1116423 IMAGED  
DATE: 5/17/1999 PAGES: 49  
AUTHOR(S): Linda Foster/Ecology & Environment, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Letter transmits revised pages for the final version of the Site-Specific Sampling and Quality Assurance Plan.

1. 9. 6.. Vol. 1 - 1116929 DOC ID: 1116929 IMAGED  
DATE: 10/1/1999 PAGES: 32  
AUTHOR(S): Superfund Technical Assessment and Response Team ADDRESSEE(S): Michael Sibley/EPA  
(START)

DESCRIPTION: Removal Action Quality Assurance Project Plan. TDD: 99-09-0019.

1. 9. 6.. Vol. 1 - 1088903 DOC ID: 1088903 IMAGED  
DATE: 4/20/2000 PAGES: 222  
AUTHOR(S): Noah H. Myers/Ecology & Environment, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION: Final Removal Action Quality Assurance Project Plan. TDD: 99-09-0019.

1. 9. 6.. Vol. 1 - 1127729 DOC ID: 1127729 IMAGED  
DATE: 5/1/2000 PAGES: 287  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Beth Sheldrake/EPA

DESCRIPTION: Removal Action Investigation, Sampling and Quality Assurance Plan.

1. 9. 6.. Vol. 1 - 1114260 DOC ID: 1114260 IMAGED  
DATE: 5/2/2000 PAGES: 23  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S): Beth Sheldrake/EPA

DESCRIPTION: Letter transmits a report describing the development of isopleth maps of contaminant concentration contours.

1. 9. 6.. Vol. 1 - 1116990 DOC ID: 1116990 IMAGED  
DATE: 7/1/2000 PAGES: 50  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Superfund Technical Assessment and Response Team  
(START)

Beth Sheldrake/EPA

DESCRIPTION: Removal Action Air Monitoring Quality Assurance Plan.

1. 9. 6.. Vol. 1 - DOC ID: 1167100 IMAGED  
DATE: 9/29/2000 PAGES: 2  
AUTHOR(S): Unknown ADDRESSEE(S):  
Dan Heister/EPA

DESCRIPTION: Sample Plan Alteration Form, Removal Action; TDD: 99-09-0019.

**SUB-HEAD: 1. 9. 7.. Vol. 1 - Site Safety**

1. 9. 7.. Vol. 1 - 1116426 DOC ID: 1116426 IMAGED  
DATE: 11/22/1999 PAGES: 44  
AUTHOR(S): Maul Foster & Alongi, Inc. ADDRESSEE(S):  
Taylor Lumber and Treating, Inc.

DESCRIPTION: Health and Safety Plan.

**SUB-HEAD: 1. 9. 8.. Vol. 1 - Pollution Reports on CD-ROM**

1. 9. 8.. Vol. 1 - 1127773 DOC ID: 1127773 IMAGED  
DATE: 11/9/2000 PAGES: 1  
AUTHOR(S): EPA ADDRESSEE(S):  
EPA

DESCRIPTION: CD-ROM: Removal Action Pollution Reports 1 through 13 dated December 3, 1999 through November 9, 2000, plus photographs.

**SUB-HEAD: 1. 9. 9.. Vol. 1 - Sampling Data**

1. 9. 9.. Vol. 1 - 1116932 DOC ID: 1116932 IMAGED  
DATE: 2/1/1999 PAGES: 5  
AUTHOR(S): Unknown ADDRESSEE(S):  
Unknown

DESCRIPTION: NPDES Water Sample Results.

1. 9. 9.. Vol. 1 - 1109241 DOC ID: 1109241 IMAGED  
DATE: 6/14/1999 PAGES: 123  
AUTHOR(S): Ginna Grepo-Grove/EPA ADDRESSEE(S):  
Michael Sibley/EPA  
Mark A. Ader/EPA



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Data Validation Report for Semi-Volatile Organic Analysis of Samples from Taylor Lumber and Treating Site Investigation and Removal Activities, samples 99214103-4216.

1. 9. 9.. Vol. 1 - 1109242 DOC ID: 1109242 IMAGED  
DATE: 6/23/1999 PAGES: 179  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Mark A. Ader/EPA  
Michael Sibley/EPA

DESCRIPTION:

Data Validation Report for the Semi-Volatile Organic Analysis of Samples from Taylor Lumber and Treating Combined Site Investigation and Removal Activities, samples 99214129-4562.

1. 9. 9.. Vol. 1 - 1109243 DOC ID: 1109243 IMAGED  
DATE: 6/28/1999 PAGES: 29  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Polychlorinated Dibenzodioxine and Polychlorinated Dibenzofurans Analysis of Samples from Taylor Lumber and Treating Combined Site Investigation and Removal Activities, samples 99224104-4211.

1. 9. 9.. Vol. 1 - 1109244 DOC ID: 1109244 IMAGED  
DATE: 6/30/1999 PAGES: 25  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Michael Sibley/EPA  
Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Semi-Volatile Organic Compound Analysis of Samples from Taylor Lumber and Treating Combined Site Investigation and Removal Activities, samples 99234275-99234276 and 99244697-99244699.

1. 9. 9.. Vol. 1 - 1109245 DOC ID: 1109245 IMAGED  
DATE: 7/13/1999 PAGES: 82  
AUTHOR(S): ADDRESSSEE(S):  
Chris Pace/EPA Ginna Grepo-Grove/EPA

DESCRIPTION:

Data Validation Report for Volatile Organic and pesticide/polychlorinated biphenyl Analysis of Samples from Taylor Lumber and Treating Combined Site Investigation and Removal Activities, samples JP161-371, JP165DL-265DL.

1. 9. 9.. Vol. 1 - 1109246 DOC ID: 1109246 IMAGED  
DATE: 7/13/1999 PAGES: 197  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Mark A. Ader/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Ginna Grepo-Grove/EPA

Michael Sibley/EPA

DESCRIPTION:

Data Validation Report for Total Inorganic Analyses of Samples from Taylor Lumber and Treating Combined Site Investigation and Removal Activities, samples MJQ638, MJAG27, MJQ722, MJQ642, MJAG20, MJAF81, MJQ625, and MJAF82.

1. 9. 9.. Vol. 1 - 1109247 DOC ID: 1109247 IMAGED  
DATE: 7/14/1999 PAGES: 70

AUTHOR(S):  
Ginna Grepo-Grove/EPA

ADDRESSEE(S):  
Mark A. Ader/EPA

Michael Sibley/EPA

DESCRIPTION:

Data Validation Report for Volatile Organic Analysis and Pesticide/Polychlorobiphenyls Analysis of Samples from Taylor Lumber and Treating Combined Site Investigation and Removal Activities, SDGs: JP104.

1. 9. 9.. Vol. 1 - 1109248 DOC ID: 1109248 IMAGED  
DATE: 7/15/1999 PAGES: 76

AUTHOR(S):  
Ginna Grepo-Grove/EPA

ADDRESSEE(S):  
Mark A. Ader/EPA

Michael Sibley/EPA

DESCRIPTION:

Data Validation Report for Volatile Organic Analysis, Semi-Volatile Organic Analysis, and Pesticides/Polychlorobiphenyls Analysis, SDGs JP106.

1. 9. 9.. Vol. 1 - 1109249 DOC ID: 1109249 IMAGED  
DATE: 7/20/1999 PAGES: 70

AUTHOR(S):  
Ginna Grepo-Grove/EPA

ADDRESSEE(S):  
Mark A. Ader/EPA

Michael Sibley/EPA

DESCRIPTION:

Data Validation Report for Volatile Organic Analysis, and Pesticides/Polychlorobiphenyls Analysis, SDGs JP556.

1. 9. 9.. Vol. 1 - 1109250 DOC ID: 1109250 IMAGED  
DATE: 7/20/1999 PAGES: 104

AUTHOR(S):  
Ginna Grepo-Grove/EPA

ADDRESSEE(S):  
Mark A. Ader/EPA

Michael Sibley/EPA

DESCRIPTION:

Data Validation Report for Volatile Organic Analysis, Semi-Volatile Organic Analysis, and Pesticides/Polychlorobiphenyls Analysis, SDGs JP137.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 9.. Vol. 1 - 1109251 DOC ID: 1109251 IMAGED  
DATE: 7/24/1999 PAGES: 339  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Mark A. Ader/EPA  
  
Michael Sibley/EPA

DESCRIPTION: Data Validation Report for Semi-Volatile Organic Compound Analysis, SDGs K9903532, 3576, 3567, 3669, 3668, 3593, 3504, 3758, 3718, 3715, 3700, 3757, and 3699.

1. 9. 9.. Vol. 1 - 1109252 DOC ID: 1109252 IMAGED  
DATE: 7/25/1999 PAGES: 22  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Mark A. Ader/EPA  
  
Michael Sibley/EPA

DESCRIPTION: Data Validation Report for Volatile Organic Analysis, and Pesticides/Polychlorobiphenyls Analysis, samples JP343-347 and JP392.

1. 9. 9.. Vol. 1 - 1109253 DOC ID: 1109253 IMAGED  
DATE: 7/25/1999 PAGES: 22  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Michael Sibley/EPA  
  
Mark A. Ader/EPA

DESCRIPTION: Data Validation Report for Volatile Organic Analysis, Pesticides/Polychlorobiphenyls, and Metals Analysis, samples 99224198, 99224513 and 99234359.

1. 9. 9.. Vol. 1 - 1109254 DOC ID: 1109254 IMAGED  
DATE: 7/26/1999 PAGES: 256  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Mark A. Ader/EPA  
  
Michael Sibley/EPA

DESCRIPTION: Data Validation Report for Volatile Organic Compounds, Semi-Volatile Organic Compounds, and Pesticides/Polychlorobiphenyls Analysis, SDGs JP264 and JP348.

1. 9. 9.. Vol. 1 - 1109255 DOC ID: 1109255 IMAGED  
DATE: 7/27/1999 PAGES: 94  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Mark A. Ader/EPA  
  
Michael Sibley/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Data Validation Report for Volatile Organic Analysis, and Pesticides/Polychlorobiphenyls Analysis, SDGs JP264 and JP223.

1. 9. 9.. Vol. 1 - 1109256 DOC ID: 1109256 IMAGED  
DATE: 7/27/1999 PAGES: 73  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Michael Sibley/EPA  
Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Volatile Organic Analysis, and Pesticides/Polychlorobiphenyls Analysis, SDGs JP264 and JP269.

1. 9. 9.. Vol. 1 - 1109257 DOC ID: 1109257 IMAGED  
DATE: 7/28/1999 PAGES: 13  
AUTHOR(S): ADDRESSSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Metals Analysis, samples 99214103, 99214107, 99214109, 99214114, 99214117, 99214123, 99214129 and 99214134.

1. 9. 9.. Vol. 1 - 1109258 DOC ID: 1109258 IMAGED  
DATE: 7/28/1999 PAGES: 20  
AUTHOR(S): ADDRESSSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Metals Analysis, Service Request Numbers K9903235 and K9903239.

1. 9. 9.. Vol. 1 - 1109259 DOC ID: 1109259 IMAGED  
DATE: 8/3/1999 PAGES: 47  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Mark A. Ader/EPA  
Michael Sibley/EPA

DESCRIPTION:

Data Validation Report for Volatile Organic Analysis, Semi-Volatile Organic Compounds, and Pesticide/Polychlorobiphenyls Analysis, SDG JP404.

1. 9. 9.. Vol. 1 - 1109260 DOC ID: 1109260 IMAGED  
DATE: 8/4/1999 PAGES: 137  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Michael Sibley/EPA  
Mark A. Ader/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Data Validation Report for Total Inorganic Analyses, SDGs MJQ725, MJQ713, MJAG36, MJAG08, MJAG47, MJAG10 and MJQ730.

1. 9. 9.. Vol. 1 - 1109262 DOC ID: 1109262 IMAGED  
DATE: 8/4/1999 PAGES: 312  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Mark A. Ader/EPA  
  
Michael Sibley/EPA

DESCRIPTION:

Data Validation Report for Volatile Organic Compounds, Semi-Volatile Organic Compounds, and Pesticide/Polychlorobiphenyls Analysis, SDGs JP195, JP437, JP222 and JP311.

1. 9. 9.. Vol. 1 - 1109263 DOC ID: 1109263 IMAGED  
DATE: 8/5/1999 PAGES: 11  
AUTHOR(S): ADDRESSSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Metals Analysis, samples 99214187, 99214190, 99214194, 99214206, 99214210 and 99214214.

1. 9. 9.. Vol. 1 - 1109264 DOC ID: 1109264 IMAGED  
DATE: 8/5/1999 PAGES: 15  
AUTHOR(S): ADDRESSSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Metals Analysis, Service Request Numbers K9903288 and K9903329.

1. 9. 9.. Vol. 1 - 1109265 DOC ID: 1109265 IMAGED  
DATE: 8/9/1999 PAGES: 73  
AUTHOR(S): ADDRESSSEE(S):  
Robert G. Melton/EPA Michael Sibley/EPA  
  
Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Volatile Organic Analysis, and Pesticides/Polychlorobiphenyls Analysis, samples JP285-288, JP290, JP292-296, JP330, JP334-342.

1. 9. 9.. Vol. 1 - 1109266 DOC ID: 1109266 IMAGED  
DATE: 8/10/1999 PAGES: 17  
AUTHOR(S): ADDRESSSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Metals Analysis, Service Request Numbers K9903365, K9903404, K9903405.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 9.. Vol. 1 - 1109267 DOC ID: 1109267 IMAGED  
DATE: 8/12/1999 PAGES: 17  
AUTHOR(S): ADDRESSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA

DESCRIPTION: Data Validation Report for Metals Analysis, Service Request Numbers K9903482, K9903520, K9903564.

1. 9. 9.. Vol. 1 - 1109268 DOC ID: 1109268 IMAGED  
DATE: 8/13/1999 PAGES: 77  
AUTHOR(S): ADDRESSEE(S):  
Ginna Grepo-Grove/EPA Michael Sibley/EPA

Mark A. Ader/EPA

DESCRIPTION: Data Validation Report for Volatile Organic, and Pesticides/Polychlorobiphenyls Analysis, samples JP144-148, JP155, JP185-186, JP188-189, JP253-260, JP262-263.

1. 9. 9.. Vol. 1 - 1124094 DOC ID: 1124094 IMAGED  
DATE: 8/22/1999 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION: Air Sampling Daily Log.

1. 9. 9.. Vol. 1 - 1124095 DOC ID: 1124095 IMAGED  
DATE: 8/23/1999 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION: Air Sampling Daily Log.

1. 9. 9.. Vol. 1 - 1109269 DOC ID: 1109269 IMAGED  
DATE: 8/24/1999 PAGES: 15  
AUTHOR(S): ADDRESSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA

DESCRIPTION: Data Validation Revised Report for Metals Analysis, Service Request Numbers K9903288, K9903329.

1. 9. 9.. Vol. 1 - 1124096 DOC ID: 1124096 IMAGED  
DATE: 8/24/1999 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Air Sampling Daily Log.

1. 9. 9.. Vol. 1 - 1124097 DOC ID: 1124097 IMAGED  
DATE: 8/25/1999 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION:

Air Sampling Daily Log.

1. 9. 9.. Vol. 1 - 1124098 DOC ID: 1124098 IMAGED  
DATE: 8/26/1999 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION:

Air Sampling Daily Log.

1. 9. 9.. Vol. 1 - 1124099 DOC ID: 1124099 IMAGED  
DATE: 8/27/1999 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION:

Air Sampling Daily Log.

1. 9. 9.. Vol. 1 - 1124100 DOC ID: 1124100 IMAGED  
DATE: 8/27/1999 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION:

Air Sampling Sample Identification Tracking Sheet.

1. 9. 9.. Vol. 1 - 1124101 DOC ID: 1124101 IMAGED  
DATE: 8/27/1999 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION:

Air Sampling Sample Identification Tracking Sheet.

1. 9. 9.. Vol. 1 - 1124102 DOC ID: 1124102 IMAGED  
DATE: 8/28/1999 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION:

Air Sampling Sample Identification Tracking Sheet.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 9.. Vol. 1 - 1124103 DOC ID: 1124103 IMAGED  
DATE: 8/28/1999 PAGES: 5  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION: Air Sampling Sample Identification Tracking Sheet.

1. 9. 9.. Vol. 1 - 1124104 DOC ID: 1124104 IMAGED  
DATE: 8/29/1999 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION: Air Sampling Daily Log.

1. 9. 9.. Vol. 1 - 1109270 DOC ID: 1109270 IMAGED  
DATE: 8/31/1999 PAGES: 97  
AUTHOR(S): ADDRESSEE(S):  
Robert G. Melton/EPA Michael Sibley/EPA  
Mark A. Ader/EPA

DESCRIPTION: Data Validation Report for Volatile Organic Analysis, Semi-Volatiles, and Pesticides/Polychlorobiphenyls Analysis, SDG JP382.

1. 9. 9.. Vol. 1 - 1109271 DOC ID: 1109271 IMAGED  
DATE: 9/16/1999 PAGES: 24  
AUTHOR(S): ADDRESSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA

DESCRIPTION: Data Validation Report for Metals Analysis, Service Request Numbers K9903594, K9903669, K9903700.

1. 9. 9.. Vol. 1 - 1109272 DOC ID: 1109272 IMAGED  
DATE: 9/16/1999 PAGES: 11  
AUTHOR(S): ADDRESSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA

DESCRIPTION: Data Validation Report for Metals Analysis, samples 99234320, 99234322, 99234328, 99234391-92, 99234397.

1. 9. 9.. Vol. 1 - 1109273 DOC ID: 1109273 IMAGED  
DATE: 9/16/1999 PAGES: 7  
AUTHOR(S): ADDRESSEE(S):  
Laura Castrilli/EPA Mark A. Ader/EPA



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Data Validation Report for Metals Analysis, samples 99244688, 99244692.

1. 9. 9.. Vol. 1 - 1109274 DOC ID: 1109274 IMAGED  
DATE: 9/20/1999 PAGES: 82  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Michael Sibley/EPA  
Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Polychlorinated Dibenzodioxins, and Polychlorinated Dibenzofurans Analysis, samples 99214140, 99214143-4144, 99214149-4151, 99214160-4161, 99214166-4167, 99214169, 99214174-4175, 99214180-4181, 99214200, 99214215-4216.

1. 9. 9.. Vol. 1 - 1109275 DOC ID: 1109275 IMAGED  
DATE: 10/4/1999 PAGES: 139  
AUTHOR(S): ADDRESSSEE(S):  
Ginna Grepo-Grove/EPA Michael Sibley/EPA  
Mark A. Ader/EPA

DESCRIPTION:

Data Validation Report for Polychlorinated Dibenzodioxins, and Polychlorinated Dibenzofurans Analysis, job 38807 and 38737.

1. 9. 9.. Vol. 1 - 1109191 DOC ID: 1109191 IMAGED  
DATE: 10/18/1999 PAGES: 54  
AUTHOR(S): ADDRESSSEE(S):  
Annette Sackman-Franzen/Ecology & Environment, Inc. Steven P. Taylor/Maul Foster & Alongi, Inc.

DESCRIPTION:

Letter of transmittal for draft analytical summary tables for Taylor Lumber and Treating Integrated Assessment (tables attached).

1. 9. 9.. Vol. 1 - 1116433 DOC ID: 1116433 IMAGED  
DATE: 10/18/1999 PAGES: 20  
AUTHOR(S): ADDRESSSEE(S):  
Mark Woodke/Ecology & Environment, Inc. Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Inorganic data quality assurance reviews of 17 air filter samples.

1. 9. 9.. Vol. 1 - 1116434 DOC ID: 1116434 IMAGED  
DATE: 10/18/1999 PAGES: 23  
AUTHOR(S): ADDRESSSEE(S):  
Mark Woodke/Ecology & Environment, Inc. Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Inorganic data quality assurance reviews of 20 air filter samples.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 9.. Vol. 1 - 1116435 DOC ID: 1116435 IMAGED  
DATE: 10/18/1999 PAGES: 23  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Inorganic data quality assurance reviews of 20 air filter samples.

1. 9. 9.. Vol. 1 - 1109276 DOC ID: 1109276 IMAGED  
DATE: 10/20/1999 PAGES: 9  
AUTHOR(S): Laura Castrilli/EPA ADDRESSEE(S): Mark A. Ader/EPA

DESCRIPTION: Data Validation Report for Metals Analysis, samples 99234275, 99234276.

1. 9. 9.. Vol. 1 - 1109277 DOC ID: 1109277 IMAGED  
DATE: 10/21/1999 PAGES: 27  
AUTHOR(S): Ginna Grepo-Grove/EPA ADDRESSEE(S): Mark A. Ader/EPA  
Michael Sibley/EPA

DESCRIPTION: Data Validation Report for Volatile Organic Analysis, and Semi-Volatile Compound Analysis, Job Numbers K9903594 and 8001.

1. 9. 9.. Vol. 1 - 1109278 DOC ID: 1109278 IMAGED  
DATE: 10/24/1999 PAGES: 103  
AUTHOR(S): Ginna Grepo-Grove/EPA ADDRESSEE(S): Michael Sibley/EPA  
Mark A. Ader/EPA

DESCRIPTION: Data Validation Report for Polychlorinated Dibenzodioxins, and Polychlorinated Dibenzofurans Analysis, Job Numbers 38985, 38907.

1. 9. 9.. Vol. 1 - 1116436 DOC ID: 1116436 IMAGED  
DATE: 11/4/1999 PAGES: 11  
AUTHOR(S): Rod Peroff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Organic data quality assurance review of eight air filter samples.

1. 9. 9.. Vol. 1 - 1116437 DOC ID: 1116437 IMAGED  
DATE: 11/4/1999 PAGES: 11  
AUTHOR(S): Rod Peroff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Organic data quality assurance review of eight air filter samples.

1. 9. 9.. Vol. 1 - 1116438 DOC ID: 1116438 IMAGED  
DATE: 11/8/1999 PAGES: 15  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Organic data quality assurance review of eight air filter samples.

1. 9. 9.. Vol. 1 - 1116439 DOC ID: 1116439 IMAGED  
DATE: 11/8/1999 PAGES: 11  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Organic data quality assurance review of eight air filter samples.

1. 9. 9.. Vol. 1 - 1116440 DOC ID: 1116440 IMAGED  
DATE: 11/8/1999 PAGES: 11  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Organic data quality assurance review of eight air filter samples.

1. 9. 9.. Vol. 1 - 1116441 DOC ID: 1116441 IMAGED  
DATE: 11/8/1999 PAGES: 11  
AUTHOR(S): Rod Peroff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Organic data quality assurance review of eight air filter samples.

1. 9. 9.. Vol. 1 - 1116442 DOC ID: 1116442 IMAGED  
DATE: 11/9/1999 PAGES: 2  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Total organic carbon data quality assurance review of one sediment sample.

1. 9. 9.. Vol. 1 - 1116443 DOC ID: 1116443 IMAGED  
DATE: 11/9/1999 PAGES: 2  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Total organic carbon data quality assurance review of two sediment samples.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 9.. Vol. 1 - 1116444 DOC ID: 1116444 IMAGED  
DATE: 11/9/1999 PAGES: 2  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Total organic carbon data quality assurance review of two sediment samples.

1. 9. 9.. Vol. 1 - 1116445 DOC ID: 1116445 IMAGED  
DATE: 11/9/1999 PAGES: 2  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Total organic carbon data quality assurance review of five sediment samples.

1. 9. 9.. Vol. 1 - 1116446 DOC ID: 1116446 IMAGED  
DATE: 11/9/1999 PAGES: 2  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Total organic carbon data quality assurance review of seven sediment samples.

1. 9. 9.. Vol. 1 - 1116447 DOC ID: 1116447 IMAGED  
DATE: 11/9/1999 PAGES: 2  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Total organic carbon data quality assurance review of 13 sediment samples.

1. 9. 9.. Vol. 1 - 1116448 DOC ID: 1116448 IMAGED  
DATE: 11/10/1999 PAGES: 2  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Total organic carbon data quality assurance review of 11 sediment samples.

1. 9. 9.. Vol. 1 - 1116449 DOC ID: 1116449 IMAGED  
DATE: 11/11/1999 PAGES: 2  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Total organic carbon data quality assurance review of one sediment sample.

1. 9. 9.. Vol. 1 - 1116450 DOC ID: 1116450 IMAGED  
DATE: 11/11/1999 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Leatta L. Dahlhoff/Ecology & Environment, Inc.

Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Total organic carbon data quality assurance review of three sediment samples.

1. 9. 9.. Vol. 1 - 1116451 DOC ID: 1116451 IMAGED  
DATE: 11/11/1999 PAGES: 2

AUTHOR(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc.

ADDRESSEE(S):  
Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Total organic carbon data quality assurance review of seven sediment samples.

1. 9. 9.. Vol. 1 - 1116452 DOC ID: 1116452 IMAGED  
DATE: 11/11/1999 PAGES: 2

AUTHOR(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc.

ADDRESSEE(S):  
Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Total organic carbon data quality assurance review of 12 sediment samples.

1. 9. 9.. Vol. 1 - 1116453 DOC ID: 1116453 IMAGED  
DATE: 11/11/1999 PAGES: 2

AUTHOR(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc.

ADDRESSEE(S):  
Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION:

Total organic carbon data quality assurance review of 14 sediment samples.

1. 9. 9.. Vol. 1 - 1088908 DOC ID: 1088908 IMAGED  
DATE: 11/15/1999 PAGES: 28

AUTHOR(S):  
Annette Sackman-Franzen/Ecology & Environment, Inc.

ADDRESSEE(S):  
Steven P. Taylor/Maul Foster & Alongi, Inc.

DESCRIPTION:

Letter of transmittal for abandonment borehole logs for Taylor Lumber and Treating Integrated Assessment (logs attached).

1. 9. 9.. Vol. 1 - 1124105 DOC ID: 1124105 IMAGED  
DATE: 11/15/1999 PAGES: 7

AUTHOR(S):  
Ecology & Environment, Inc.

ADDRESSEE(S):  
Unknown

DESCRIPTION:

Wind Rose Plot.

1. 9. 9.. Vol. 1 - 1124106 DOC ID: 1124106 IMAGED  
DATE: 12/16/1999 PAGES: 7

AUTHOR(S):  
Ecology & Environment, Inc.

ADDRESSEE(S):  
Unknown

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION: Wind Rose Plot.

1. 9. 9.. Vol. 1 - 1124107 DOC ID: 1124107 IMAGED  
DATE: 12/16/1999 PAGES: 1  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S): Unknown

DESCRIPTION: Air Sampling Meteorological Data Summary Sheet.

1. 9. 9.. Vol. 1 - 1116454 DOC ID: 1116454 IMAGED  
DATE: 1/6/2000 PAGES: 26  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Organic data quality assurance review of 18 soil and four water samples.

1. 9. 9.. Vol. 1 - 1116455 DOC ID: 1116455 IMAGED  
DATE: 1/6/2000 PAGES: 20  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Organic data quality assurance review of ten soil and seven water samples.

1. 9. 9.. Vol. 1 - 1116456 DOC ID: 1116456 IMAGED  
DATE: 1/6/2000 PAGES: 16  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Organic data quality assurance review of 13 water samples.

1. 9. 9.. Vol. 1 - 1116457 DOC ID: 1116457 IMAGED  
DATE: 1/7/2000 PAGES: 26  
AUTHOR(S): Rod Peroff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Organic data quality assurance review of three water, six soil, and two sediment samples.

1. 9. 9.. Vol. 1 - 1116458 DOC ID: 1116458 IMAGED  
DATE: 1/7/2000 PAGES: 39  
AUTHOR(S): Rod Peroff/Ecology & Environment, Inc. ADDRESSEE(S): Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Organic data quality assurance review of two water and 15 soil samples.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 9.. Vol. 1 - 1109279 DOC ID: 1109279 IMAGED  
DATE: 1/11/2000 PAGES: 11  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION: Monitoring Well Groundwater Analytical Results for Chlorinated Phenolics at Taylor Lumber and Treating, Inc.

1. 9. 9.. Vol. 1 - 1116459 DOC ID: 1116459 IMAGED  
DATE: 1/17/2000 PAGES: 44  
AUTHOR(S): ADDRESSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Organic data quality assurance review of 16 soil and four sediment samples.

1. 9. 9.. Vol. 1 - 1116460 DOC ID: 1116460 IMAGED  
DATE: 1/17/2000 PAGES: 21  
AUTHOR(S): ADDRESSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Annette Franzen/Ecology & Environment, Inc.

DESCRIPTION: Organic data quality assurance review of seven soil and two sediment samples.

1. 9. 9.. Vol. 1 - 1127582 DOC ID: 1127582 IMAGED  
DATE: 1/17/2000 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
Jason Coury/Environmental Quality Management, Inc. Michael Sibley/EPA

DESCRIPTION: Fax transmitting sample results on the northwest corner.

1. 9. 9.. Vol. 1 - 1114259 DOC ID: 1114259 IMAGED  
DATE: 2/2/2000 PAGES: 20  
AUTHOR(S): ADDRESSEE(S):  
Jayant Shringarpure/Southwest Laboratory of Oklahoma, Inc. Jason Coury/Environmental Quality Management, Inc.

DESCRIPTION: Letter of transmittal for analytical results of sample received at lab 1/19/00.

1. 9. 9.. Vol. 1 - DOC ID: 1167101 IMAGED  
DATE: 5/23/2000 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Oregon State Dept. of Environmental Quality Unknown

DESCRIPTION: Met Data Summary for the period 8/22/99 through 8/28/99.

1. 9. 9.. Vol. 1 - 1124009 DOC ID: 1124009 IMAGED  
DATE: 6/14/2000 PAGES: 9  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Jeffrey Fowlow/Ecology & Environment, Inc.

Michael Sibley/EPA

DESCRIPTION:

Letter transmits validated dioxin analytical data for soil samples.

1. 9. 9.. Vol. 1 - 1114262 DOC ID: 1114262 IMAGED  
DATE: 6/19/2000 PAGES: 4  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S): Roger Culleton/Ecology & Environment, Inc.

DESCRIPTION:

Memorandum of transmittal for Arsenic XRF and Commercial Laboratory Results, Taylor Lumber Site, Sheridan, Oregon.

1. 9. 9.. Vol. 1 - 1114268 DOC ID: 1114268 IMAGED  
DATE: 6/20/2000 PAGES: 31  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S): Marcia L. Bailey/EPA

DESCRIPTION:

Letter of transmittal for validated analytical data packages for soil samples collected from stockpiled soil at Taylor Lumber Site, January 2000.

1. 9. 9.. Vol. 1 - 1114269 DOC ID: 1114269 IMAGED  
DATE: 7/3/2000 PAGES: 6  
AUTHOR(S): Jason Coury/Environmental Quality Management, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Faxed transmittal for total arsenic data from stockpiled soil at Taylor Lumber Site.

1. 9. 9.. Vol. 1 - 1114263 DOC ID: 1114263 IMAGED  
DATE: 7/13/2000 PAGES: 8  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc. ADDRESSEE(S): Michael Sibley/EPA

DESCRIPTION:

Faxed transmittal for analytical results for soil samples from stockpiles "burritos" constructed at Taylor Lumber Site, Sheridan, Oregon.

1. 9. 9.. Vol. 1 - 1124011 DOC ID: 1124011 IMAGED  
DATE: 9/8/2000 PAGES: 15  
AUTHOR(S): Harvey Jacky/Columbia Analytical Services, Inc. ADDRESSEE(S): Greg Hays/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter transmits an analytical report for soil samples.

1. 9. 9.. Vol. 1 - DOC ID: 1167102 IMAGED  
DATE: 9/26/2000 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Darla Powell/Sound Analytical Services, Inc.

Jason Coury/Environmental Quality Management,  
Inc.

DESCRIPTION: Preliminary results for arsenic only.

1. 9. 9.. Vol. 1 - DOC ID: 1167103 IMAGED  
DATE: 9/26/2000 PAGES: 6

AUTHOR(S): Darla Powell/Sound Analytical Services, Inc.  
ADDRESSEE(S): Jason Coury/Environmental Quality Management,  
Inc.

DESCRIPTION: Preliminary results.

1. 9. 9.. Vol. 1 - 1116937 DOC ID: 1116937 IMAGED  
DATE: 9/29/2000 PAGES: 611

AUTHOR(S): Maul Foster & Alongi, Inc.  
ADDRESSEE(S): Taylor Lumber and Treating, Inc.

DESCRIPTION: Ditch Excavation Confirmation Sample Results.

1. 9. 9.. Vol. 1 - 1116938 DOC ID: 1116938 IMAGED  
DATE: 11/21/2000 PAGES: 447

AUTHOR(S): Harvey Jacky/Columbia Analytical Services, Inc.  
ADDRESSEE(S): Greg Hays/Taylor Lumber and Treating, Inc.

DESCRIPTION: Analysis of soil samples.

1. 9. 9.. Vol. 1 - 1116922 DOC ID: 1116922 IMAGED  
DATE: 11/29/2000 PAGES: 750

AUTHOR(S): Harvey Jacky/Columbia Analytical Services, Inc.  
ADDRESSEE(S): Darin Cole/Taylor Lumber and Treating, Inc.

DESCRIPTION: Analysis of soil samples.

**SUB-HEAD: 1. 9. 10.. Vol. 1 - Chain of Custody Documents**

1. 9. 10.. Vol. 1 - 1124077 DOC ID: 1124077 IMAGED  
DATE: 5/19/1999 PAGES: 54

AUTHOR(S): Ecology & Environment, Inc.  
ADDRESSEE(S): Unknown

DESCRIPTION: Field Sample Data and Chain of Custody Sheet.

1. 9. 10.. Vol. 1 - 1124078 DOC ID: 1124078 IMAGED  
DATE: 5/19/1999 PAGES: 84

AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Ecology & Environment, Inc.

Unknown

DESCRIPTION: Field Sample Data and Chain of Custody Sheet.

1. 9. 10.. Vol. 1 - 1124108 DOC ID: 1124108 IMAGED  
DATE: 5/20/1999 PAGES: 6  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S): Melody Walker/EPA

DESCRIPTION: Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124109 DOC ID: 1124109 IMAGED  
DATE: 5/21/1999 PAGES: 2  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Melody Walker/EPA

DESCRIPTION: Memo transmits a Chain of Custody Record.

1. 9. 10.. Vol. 1 - 1124110 DOC ID: 1124110 IMAGED  
DATE: 5/22/1999 PAGES: 7  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Melody Walker/EPA

DESCRIPTION: Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124111 DOC ID: 1124111 IMAGED  
DATE: 5/25/1999 PAGES: 6  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Melody Walker/EPA

DESCRIPTION: Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124112 DOC ID: 1124112 IMAGED  
DATE: 5/26/1999 PAGES: 10  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S): Melody Walker/EPA

DESCRIPTION: Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124113 DOC ID: 1124113 IMAGED  
DATE: 5/27/1999 PAGES: 7  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S): Melody Walker/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124114 DOC ID: 1124114 IMAGED  
DATE: 5/28/1999 PAGES: 7  
AUTHOR(S): ADDRESSSEE(S):  
Jeffrey Fowlow/Ecology & Environment, Inc. Melody Walker/EPA

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124079 DOC ID: 1124079 IMAGED  
DATE: 6/1/1999 PAGES: 44  
AUTHOR(S): ADDRESSSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION:

Field Sample Data and Chain of Custody Sheet.

1. 9. 10.. Vol. 1 - 1124080 DOC ID: 1124080 IMAGED  
DATE: 6/1/1999 PAGES: 68  
AUTHOR(S): ADDRESSSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION:

Field Sample Data and Chain of Custody Sheet.

1. 9. 10.. Vol. 1 - 1124115 DOC ID: 1124115 IMAGED  
DATE: 6/1/1999 PAGES: 8  
AUTHOR(S): ADDRESSSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Melody Walker/EPA

Jeffrey Fowlow/Ecology & Environment, Inc.

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124116 DOC ID: 1124116 IMAGED  
DATE: 6/2/1999 PAGES: 4  
AUTHOR(S): ADDRESSSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Melody Walker/EPA

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124117 DOC ID: 1124117 IMAGED  
DATE: 6/2/1999 PAGES: 8  
AUTHOR(S): ADDRESSSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Melody Walker/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124118 DOC ID: 1124118 IMAGED  
DATE: 6/4/1999 PAGES: 9  
AUTHOR(S): ADDRESSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Melody Walker/EPA

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124119 DOC ID: 1124119 IMAGED  
DATE: 6/7/1999 PAGES: 12  
AUTHOR(S): ADDRESSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Melody Walker/EPA

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124120 DOC ID: 1124120 IMAGED  
DATE: 6/8/1999 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Melody Walker/EPA

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124121 DOC ID: 1124121 IMAGED  
DATE: 6/9/1999 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Melody Walker/EPA

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124122 DOC ID: 1124122 IMAGED  
DATE: 6/10/1999 PAGES: 5  
AUTHOR(S): ADDRESSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Melody Walker/EPA

DESCRIPTION:

Memo transmits Chain of Custody Records.

1. 9. 10.. Vol. 1 - 1124123 DOC ID: 1124123 IMAGED  
DATE: 6/14/1999 PAGES: 9  
AUTHOR(S): ADDRESSEE(S):  
Leatta L. Dahlhoff/Ecology & Environment, Inc. Melody Walker/EPA

DESCRIPTION:

Memo transmits Chain of Custody Records.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

1. 9. 10.. Vol. 1 - 1124082 DOC ID: 1124082 IMAGED  
DATE: 8/24/1999 PAGES: 20  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Field Sample Data and Chain of Custody Sheet.

1. 9. 10.. Vol. 1 - 1124081 DOC ID: 1124081 IMAGED  
DATE: 8/30/1999 PAGES: 4  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Chain of Custody Record.

1. 9. 10.. Vol. 1 - 1124083 DOC ID: 1124083 IMAGED  
DATE: 8/30/1999 PAGES: 4  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Chain of Custody Record.

1. 9. 10.. Vol. 1 - DOC ID: 1167104 IMAGED  
DATE: 11/8/1999 PAGES: 1  
AUTHOR(S): Mark Woodke/Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Chain of Custody Record; Project KJ0004, DI 1901 RA.

1. 9. 10.. Vol. 1 - DOC ID: 1167106 IMAGED  
DATE: 1/1/2000 PAGES: 1  
AUTHOR(S): Alan Noell/Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Chain of Custody Record; TDD: 99-01-0019. (TDD: 99-09-0019?)

Note: Document date is estimated.

1. 9. 10.. Vol. 1 - DOC ID: 1167105 IMAGED  
DATE: 1/17/2000 PAGES: 1  
AUTHOR(S): Leatta L. Dahlhoff/Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Chain of Custody Record; Project 99-09-0019.

1. 9. 10.. Vol. 1 - DOC ID: 1167107 IMAGED  
DATE: 1/24/2000 PAGES: 8  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Mark Woodke/Ecology & Environment, Inc.

Unknown

DESCRIPTION: Chain of Custody Record; Case No. KJ0005; TDD: 99-09-0019.

**SUB-HEAD: 1. 9. 11.. Vol. 1 - Well Logs**

1. 9. 11.. Vol. 1 - DOC ID: 1167108 IMAGED  
DATE: 5/11/1999 PAGES: 58  
AUTHOR(S): ADDRESSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Drilling Logs of Well/Boring for May, 1999.

1. 9. 11.. Vol. 1 - 1124085 DOC ID: 1124085 IMAGED  
DATE: 5/21/1999 PAGES: 12  
AUTHOR(S): ADDRESSEE(S):  
Reid Kenner/GeoEngineers, Inc. State of Oregon

DESCRIPTION: Geotechnical Hole Report.

1. 9. 11.. Vol. 1 - 1124087 DOC ID: 1124087 IMAGED  
DATE: 5/26/1999 PAGES: 62  
AUTHOR(S): ADDRESSEE(S):  
Reid Kenner/GeoEngineers, Inc. State of Oregon

DESCRIPTION: Geotechnical Hole Report.

1. 9. 11.. Vol. 1 - 1124088 DOC ID: 1124088 IMAGED  
DATE: 5/28/1999 PAGES: 17  
AUTHOR(S): ADDRESSEE(S):  
Reid Kenner/GeoEngineers, Inc. State of Oregon

DESCRIPTION: Geotechnical Hole Report.

1. 9. 11.. Vol. 1 - DOC ID: 1167109 IMAGED  
DATE: 6/1/1999 PAGES: 51  
AUTHOR(S): ADDRESSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION: Drilling Logs of Well/Boring for June, 1999.

1. 9. 11.. Vol. 1 - 1124092 DOC ID: 1124092 IMAGED  
DATE: 6/7/1999 PAGES: 61  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Jeffrey Fowlow/Ecology & Environment, Inc.

State of Oregon

DESCRIPTION: Geotechnical Hole Report.

1. 9. 11.. Vol. 1 - 1124093 DOC ID: 1124093 IMAGED  
DATE: 6/8/1999 PAGES: 16  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S):  
State of Oregon

DESCRIPTION: Geotechnical Hole Report.

1. 9. 11.. Vol. 1 - 1124091 DOC ID: 1124091 IMAGED  
DATE: 6/9/1999 PAGES: 2  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S):  
State of Oregon

DESCRIPTION: Geotechnical Hole Report.

1. 9. 11.. Vol. 1 - 1124090 DOC ID: 1124090 IMAGED  
DATE: 6/10/1999 PAGES: 20  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S):  
State of Oregon

DESCRIPTION: Geotechnical Hole Report.

1. 9. 11.. Vol. 1 - 1124089 DOC ID: 1124089 IMAGED  
DATE: 6/11/1999 PAGES: 4  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S):  
State of Oregon

DESCRIPTION: Geotechnical Hole Report.

1. 9. 11.. Vol. 1 - DOC ID: 1167110 IMAGED  
DATE: 1/12/2000 PAGES: 5  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Drilling Logs of Well/Boring for January 2000.

1. 9. 11.. Vol. 1 - DOC ID: 1167111 IMAGED  
DATE: 1/12/2000 PAGES: 25  
AUTHOR(S): Alan Noell/Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Handwritten Drilling Logs for January 2000.

1. 9. 11.. Vol. 1 -	DOC ID: 1167112	IMAGED
DATE: 5/13/2000	PAGES: 220	
AUTHOR(S):	ADDRESSEE(S):	
Alan Noell/Ecology & Environment, Inc.	Unknown	

DESCRIPTION:

Handwritten Drilling Logs for TB-101 through TB-122.

1. 9. 11.. Vol. 1 -	DOC ID: 1167113	IMAGED
DATE: 5/22/2000	PAGES: 1	
AUTHOR(S):	ADDRESSEE(S):	
Matt Dunckel & Associates	Unknown	

DESCRIPTION:

Test Bore Data.

1. 9. 11.. Vol. 1 -	DOC ID: 1167114	IMAGED
DATE: 10/23/2000	PAGES: 32	
AUTHOR(S):	ADDRESSEE(S):	
Ecology & Environment, Inc.	Unknown	

DESCRIPTION:

Drilling Logs of Well/Boring for October 2000.

**SUB-HEAD: 1. 9. 13.. Vol. 1 - Removal Action Report**

1. 9. 13.. Vol. 1 -	DOC ID: 1167115	IMAGED
DATE: 12/12/2000	PAGES: 1	
AUTHOR(S):	ADDRESSEE(S):	
Ecology & Environment, Inc.	Unknown	

DESCRIPTION:

Index for the Removal Action Report CD images.

1. 9. 13.. Vol. 1 -	DOC ID: 1150692	IMAGED
DATE: 1/1/2001	PAGES: 699	
AUTHOR(S):	ADDRESSEE(S):	
Superfund Technical Assessment and Response Team (START)	Michael Sibley/EPA	

DESCRIPTION:

Removal Action Report. TDD: 09-00-09-0015.

**SUB-HEAD: 1. 9. 14.. Vol. 1 - Groundwater Characterization Report**

1. 9. 14.. Vol. 1 -	1114267	DOC ID: 1114267	IMAGED
DATE: 6/1/2000		PAGES: 183	
AUTHOR(S):	ADDRESSEE(S):		



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Jeffrey Fowlow/Ecology & Environment, Inc.

Beth Sheldrake/EPA

DESCRIPTION: Removal Action Investigation Groundwater Characterization Report. TDD: 99-09-0019.

**SUB-HEAD: 1. 10... Vol. 1 - Stormwater Treatment**

**SUB-HEAD: 1. 10. 1.. Vol. 1 - Correspondence**

**SUB-HEAD: 1. 10. 1. 1. Vol. 1 - Formal Correspondence**

1. 10. 1. 1. Vol. 1 - DOC ID: 1144629 IMAGED  
DATE: 2/27/1996 PAGES: 8  
AUTHOR(S): ADDRESSEE(S):  
Bruce Long/EPA Albert L. Odmark/EPA  
Robert Hartman/EPA

DESCRIPTION: Memo transmitting a copy of Taylor Lumber's Storm Water Control Report.

1. 10. 1. 1. Vol. 1 - DOC ID: 1144630 IMAGED  
DATE: 10/6/1997 PAGES: 45  
AUTHOR(S): ADDRESSEE(S):  
Steven P. Taylor/Maul Foster & Alongi, Inc. Bruce Long/EPA  
Neil R. Alongi/Maul Foster & Alongi, Inc.

DESCRIPTION: Letter responding to EPA's September 4, 1997 comments on the May 15, 1997 draft Interim Corrective Measures Stormwater Treatment Plan.

1. 10. 1. 1. Vol. 1 - 1127688 DOC ID: 1127688 IMAGED  
DATE: 3/17/1999 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Steven P. Taylor/Maul Foster & Alongi, Inc. Jerry Lauer/Ecology & Environment, Inc.

DESCRIPTION: Fax transmitting a plan for expanding the ditches in the southeast corner of the plant for stormwater storage.

1. 10. 1. 1. Vol. 1 - 1124184 DOC ID: 1124184 IMAGED  
DATE: 3/18/1999 PAGES: 7  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Steven P. Taylor/Maul Foster & Alongi, Inc.

Roland Mueller/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Fax memo transmits another stormwater treatment technology.

1. 10. 1. 1. Vol. 1 - 1116785      DOC ID: 1116785      IMAGED  
DATE: 4/13/1999      PAGES: 2  
AUTHOR(S): Vince Gullette/Taylor Lumber and Treating, Inc.      ADDRESSEE(S):  
Michael A. Bussell/EPA  
Michael F. Gearheard/EPA

DESCRIPTION:

Letter discusses constructing an alternative stormwater treatment system.

1. 10. 1. 1. Vol. 1 - 1124185      DOC ID: 1124185      IMAGED  
DATE: 4/27/1999      PAGES: 6  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc.      ADDRESSEE(S):  
Vince Gullette/Taylor Lumber and Treating, Inc.  
Roland Mueller/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Fax memo transmits storm filter bench test results.

1. 10. 1. 1. Vol. 1 - 1116926      DOC ID: 1116926      IMAGED  
DATE: 6/25/1999      PAGES: 9  
AUTHOR(S): James J. Maul/Maul Foster & Alongi, Inc.      ADDRESSEE(S):  
Betty Wiese/EPA  
Steven P. Taylor/Maul Foster & Alongi, Inc.

DESCRIPTION:

Letter discusses and transmits information related to soil excavation of the stormwater treatment system.

1. 10. 1. 1. Vol. 1 - 1127714      DOC ID: 1127714      IMAGED  
DATE: 7/1/1999      PAGES: 7  
AUTHOR(S): Superfund Technical Assessment and Response Team      ADDRESSEE(S):  
(START) Michael Sibley/EPA

DESCRIPTION:

Trip Report: Storm Water System Observations, with handwritten notes.

1. 10. 1. 1. Vol. 1 - 1127689      DOC ID: 1127689      IMAGED  
DATE: 7/2/1999      PAGES: 8  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc.      ADDRESSEE(S):  
Betty Wiese/EPA  
James J. Maul/Maul Foster & Alongi, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Letter compiles cost estimates for construction of alternative stormwater treatment systems.

1. 10. 1. 1. Vol. 1 - 1127694 DOC ID: 1127694 IMAGED  
DATE: 7/7/1999 PAGES: 1  
AUTHOR(S): Jeffrey Fowlow/Ecology & Environment, Inc. ADDRESSEE(S): Beth Sheldrake/EPA

DESCRIPTION:

Letter transmits a trip report for June 22, 1998 regarding the storm water system observations.  
(Less enclosures)

1. 10. 1. 1. Vol. 1 - 1127740 DOC ID: 1127740 IMAGED  
DATE: 7/21/1999 PAGES: 3  
AUTHOR(S): Michael A. Bussell/EPA ADDRESSEE(S): Vince Gullette/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter responds to recent letters regarding consideration of an alternative to the approved stormwater treatment system.

1. 10. 1. 1. Vol. 1 - 1127690 DOC ID: 1127690 IMAGED  
DATE: 8/19/1999 PAGES: 4  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc. ADDRESSEE(S): Betty Wiese/EPA

James J. Maul/Maul Foster & Alongi, Inc.

DESCRIPTION:

Letter discusses regulatory issues related to installation of a stormwater treatment system.

1. 10. 1. 1. Vol. 1 - 1127742 DOC ID: 1127742 IMAGED  
DATE: 8/20/1999 PAGES: 2  
AUTHOR(S): Bruce Summers/Taylor Lumber and Treating, Inc. ADDRESSEE(S): Michael A. Bussell/EPA

DESCRIPTION:

Letter discusses approval of the Stormwater Treatment System and Removal Action.

1. 10. 1. 1. Vol. 1 - 1127691 DOC ID: 1127691 IMAGED  
DATE: 9/9/1999 PAGES: 2  
AUTHOR(S): Steven P. Taylor/Maul Foster & Alongi, Inc. ADDRESSEE(S): Betty Wiese/EPA

DESCRIPTION:

Letter transmits and discusses the February 8, 1999 design for Phase 1 of the Stormwater Treatment System. (Less attachment)

1. 10. 1. 1. Vol. 1 - 1127744 DOC ID: 1127744 IMAGED  
DATE: 9/10/1999 PAGES: 7  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Bruce Long/EPA

Bruce Summers/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter regarding a determination of the applicability of a policy letter to soils excavation work for installation of the conveyance system for a storm water treatment system.

1. 10. 1. 1. Vol. 1 - 1127692 DOC ID: 1127692 IMAGED

DATE: 10/26/1999 PAGES: 2

AUTHOR(S):

Bruce Long/EPA

ADDRESSEE(S):

Vince Gullette/Taylor Lumber and Treating, Inc.

DESCRIPTION:

Letter discusses Phase 1 of the Stormwater Treatment System.

1. 10. 1. 1. Vol. 1 - 1127736 DOC ID: 1127736 IMAGED

DATE: 12/3/1999 PAGES: 13

AUTHOR(S):

Steven P. Taylor/Maul Foster & Alongi, Inc.

ADDRESSEE(S):

Bruce Long/EPA

DESCRIPTION:

Letter requests approval for a modification to the depth of the stormwater conveyance system piping.

1. 10. 1. 1. Vol. 1 - 1127693 DOC ID: 1127693 IMAGED

DATE: 12/10/1999 PAGES: 3

AUTHOR(S):

Bruce Long/EPA

ADDRESSEE(S):

Steven P. Taylor/Maul Foster & Alongi, Inc.

DESCRIPTION:

Letter discusses modifications to the Conveyance Piping System for Phase 1 of the Stormwater Treatment System.

1. 10. 1. 1. Vol. 1 - 1127737 DOC ID: 1127737 IMAGED

DATE: 12/30/1999 PAGES: 15

AUTHOR(S):

Steven P. Taylor/Maul Foster & Alongi, Inc.

ADDRESSEE(S):

Betty Wiese/EPA

DESCRIPTION:

Letter requests approval for construction of the stormwater treatment system.

1. 10. 1. 1. Vol. 1 - DOC ID: 1144631 IMAGED

DATE: 5/31/2000 PAGES: 60

AUTHOR(S):

Steven P. Taylor/Maul Foster & Alongi, Inc.

ADDRESSEE(S):

Bruce Long/EPA

DESCRIPTION:

Letter responding to EPA's comments at the May 9, 2000 meeting regarding the proposed Stormwater Treatment System.

1. 10. 1. 1. Vol. 1 - DOC ID: 1144632 IMAGED

DATE: 6/15/2000 PAGES: 1

AUTHOR(S):

ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Steven P. Taylor/Maul Foster & Alongi, Inc.

Bruce Long/EPA

DESCRIPTION:

Memo transmitting the report: Stormwater Treatment System-Phase 2. (Less attachment)

1. 10. 1. 1. Vol. 1 -

DATE: 8/14/2000

DOC ID: 1144633 IMAGED

PAGES: 24

AUTHOR(S):

Steven P. Taylor/Maul Foster & Alongi, Inc.

ADDRESSEE(S):

Timothy C. McFetridge/Oregon State Dept. of  
Environmental Quality

Bruce Long/EPA

DESCRIPTION:

Letter regarding modifications to the Stormwater Treatment System.

**SUB-HEAD: 1. 10. 2.. Vol. 1 -**

**Stormwater Treatment Plan**

1. 10. 2.. Vol. 1 -

DATE: 10/1/1997

DOC ID: 1144636 IMAGED

PAGES: 223

AUTHOR(S):

Neil R. Alongi/Maul Foster & Alongi, Inc.

ADDRESSEE(S):

Taylor Lumber and Treating, Inc.

Steven P. Taylor/Maul Foster & Alongi, Inc.

DESCRIPTION:

Final Interim Corrective Measures, Stormwater Treatment Plan.

**SUB-HEAD: 1. 10. 3.. Vol. 1 -**

**Stormwater Treatment System**

1. 10. 3.. Vol. 1 - 1124183

DATE: 6/1/1998

DOC ID: 1124183 IMAGED

PAGES: 192

AUTHOR(S):

Maul Foster & Alongi, Inc.

ADDRESSEE(S):

Taylor Lumber and Treating, Inc.

DESCRIPTION:

Stormwater Treatment System-Phase 1.

1. 10. 3.. Vol. 1 - 1127763

DATE: 2/8/1999

DOC ID: 1127763 IMAGED

PAGES: 182

AUTHOR(S):

Maul Foster & Alongi, Inc.

ADDRESSEE(S):

Taylor Lumber and Treating, Inc.

DESCRIPTION:

Stormwater Treatment System-Phase 1; Revision 1.0.

1. 10. 3.. Vol. 1 -

DATE: 6/14/2000

DOC ID: 1144637 IMAGED

PAGES: 372

AUTHOR(S):

Alistaire Clary/Maul Foster & Alongi, Inc.

ADDRESSEE(S):

Taylor Lumber and Treating, Inc.

Steven P. Taylor/Maul Foster & Alongi, Inc.

Taylor Lumber and Treating, Inc.

DESCRIPTION: Stormwater Treatment System, Phase 1 and Phase 2.

**SUB-HEAD: 1. 10. 4.. Vol. 1 - Stormwater Treatment System Operation & Maintenance Manual**

1. 10. 4.. Vol. 1 -

DOC ID: 1144638 IMAGED

DATE: 12/1/2000

PAGES: 444

AUTHOR(S):

ADDRESSEE(S):

Van McKay/Maul Foster & Alongi, Inc.

Taylor Lumber and Treating, Inc.

Steven P. Taylor/Maul Foster & Alongi, Inc.

DESCRIPTION: Stormwater Treatment System, Operation and Maintenance Manual, Revision 1.1.

**HEADING: 2. 0... REMEDIAL INVESTIGATION/FEASIBILITY STUDY**

**SUB-HEAD: 2. 1... Vol. 1 - Correspondence**

**SUB-HEAD: 2. 1. 1.. Vol. 1 - Formal Correspondence**

2. 1. 1.. Vol. 1 - DOC ID: 1224710 IMAGED  
DATE: 2/19/2004 PAGES: 31  
AUTHOR(S): ADDRESSEE(S):  
Robin Strauss/CH2M Hill, Inc. Loren C. McPhillips/EPA

DESCRIPTION: Technical Memorandum: Response to Comments on Draft Remedial Investigation Report and Draft Baseline Risk Assessment.

2. 1. 1.. Vol. 1 - DOC ID: 1224665 IMAGED  
DATE: 9/26/2005 PAGES: 9  
AUTHOR(S): ADDRESSEE(S):  
Valerie Panek/CH2M Hill, Inc. Karen L. Keeley/EPA  
Robin Strauss/CH2M Hill, Inc.

DESCRIPTION: Memo regarding evaluation of pump and treat assumptions.

**SUB-HEAD: 2. 1. 2.. Vol. 1 - Notes/Email**

2. 1. 2.. Vol. 1 - DOC ID: 1224666 IMAGED  
DATE: 4/6/2005 PAGES: 6  
AUTHOR(S): ADDRESSEE(S):  
Sheila M. Eckman/EPA Karen L. Keeley/EPA

DESCRIPTION: Email regarding Tribal comments on the Remedial Investigation/Feasibility Study.

2. 1. 2.. Vol. 1 - DOC ID: 1205809 IMAGED  
DATE: 5/25/2005 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Karen L. Keeley/EPA Robin Strauss/CH2M Hill, Inc.

DESCRIPTION: Email considers the 4-volume Remedial Investigation/Feasibility Study dated December 2004 to be final. (Less attachments)

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

2. 1. 2.. Vol. 1 - DOC ID: 1224669 IMAGED  
DATE: 7/5/2005 PAGES: 2  
AUTHOR(S): Mark Brady/Environment International, Ltd. ADDRESSEE(S):  
Karen L. Keeley/EPA

DESCRIPTION: Email commenting on the Proposed Plan.

2. 1. 2.. Vol. 1 - DOC ID: 1224670 IMAGED  
DATE: 7/26/2005 PAGES: 1  
AUTHOR(S): Karen L. Keeley/EPA ADDRESSEE(S):  
Robin Strauss/CH2M Hill, Inc.

DESCRIPTION: Email commenting on the April 2005 sampling event, field and data report.

2. 1. 2.. Vol. 1 - DOC ID: 1224671 IMAGED  
DATE: 9/19/2005 PAGES: 4  
AUTHOR(S): Robin Strauss/CH2M Hill, Inc. ADDRESSEE(S):  
Karen L. Keeley/EPA

DESCRIPTION: Email regarding zoning.

2. 1. 2.. Vol. 1 - DOC ID: 1224672 IMAGED  
DATE: 9/21/2005 PAGES: 1  
AUTHOR(S): Robin Strauss/CH2M Hill, Inc. ADDRESSEE(S):  
Karen L. Keeley/EPA

DESCRIPTION: Email regarding indoor air.

**SUB-HEAD: 2. 2... Vol. 1 - Work Plan**

2. 2... Vol. 1 - DOC ID: 1224712 IMAGED  
DATE: 7/1/2002 PAGES: 99  
AUTHOR(S): CH2M Hill, Inc. ADDRESSEE(S):  
EPA

DESCRIPTION: Phase 2 Field Investigation Work Plan.

**SUB-HEAD: 2. 3... Vol. 1 - Sampling Plan**

2. 3... Vol. 1 - DOC ID: 1150117 IMAGED  
DATE: 1/1/2002 PAGES: 22  
AUTHOR(S): CH2M Hill, Inc. ADDRESSEE(S):  
EPA



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION: Groundwater Monitoring Field Sampling Plan.

2. 3... Vol. 1 - DOC ID: 1150118 IMAGED  
DATE: 1/1/2002 PAGES: 44  
AUTHOR(S): CH2M Hill, Inc. ADDRESSEE(S): EPA

DESCRIPTION: Groundwater Monitoring Quality Assurance Project Plan.

2. 3... Vol. 1 - DOC ID: 1150119 IMAGED  
DATE: 1/22/2002 PAGES: 7  
AUTHOR(S): Laura Castrilli/EPA ADDRESSEE(S): Loren C. McPhillips/EPA

DESCRIPTION: Memo commenting on the Draft Groundwater Monitoring Quality Assurance Project Plan.

2. 3... Vol. 1 - DOC ID: 1150120 IMAGED  
DATE: 2/7/2002 PAGES: 5  
AUTHOR(S): Laura Castrilli/EPA ADDRESSEE(S): Loren C. McPhillips/EPA

DESCRIPTION: Memo commenting on the Groundwater Monitoring Quality Assurance Project Plan.

2. 3... Vol. 1 - DOC ID: 1224713 IMAGED  
DATE: 5/1/2002 PAGES: 25  
AUTHOR(S): CH2M Hill, Inc. ADDRESSEE(S): EPA

DESCRIPTION: Groundwater Monitoring Field Sampling Plan; May 2002 Event.

2. 3... Vol. 1 - DOC ID: 1224714 IMAGED  
DATE: 8/1/2002 PAGES: 27  
AUTHOR(S): CH2M Hill, Inc. ADDRESSEE(S): EPA

DESCRIPTION: Groundwater Monitoring Field Sampling Plan; August 2002 Event.

2. 3... Vol. 1 - DOC ID: 1224715 IMAGED  
DATE: 6/1/2004 PAGES: 29  
AUTHOR(S): CH2M Hill, Inc. ADDRESSEE(S): EPA

DESCRIPTION: Monitor Well MW-24S Installation and Sampling Plan.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

2. 3... Vol. 1 - DOC ID: 1224716 IMAGED  
DATE: 8/10/2004 PAGES: 30  
AUTHOR(S): ADDRESSEE(S):  
CH2M Hill, Inc. EPA

DESCRIPTION: Monitor Well MW-24S Installation and Sampling Plan. (June 2004 revised August 2004)

2. 3... Vol. 1 - DOC ID: 1224717 IMAGED  
DATE: 8/10/2004 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Laura Castrilli/EPA Loren C. McPhillips/EPA

DESCRIPTION: Sample Alteration Form changing groundwater sampling field procedure or analysis variation.

2. 3... Vol. 1 - DOC ID: 1224673 IMAGED  
DATE: 4/22/2005 PAGES: 16  
AUTHOR(S): ADDRESSEE(S):  
CH2M Hill, Inc. EPA

DESCRIPTION: Monitor Well MW-24S Installation and Sampling Plan.

**SUB-HEAD: 2. 4... Vol. 1 - Sampling Data**

2. 4... Vol. 1 - DOC ID: 1150122 IMAGED  
DATE: 3/11/2002 PAGES: 43  
AUTHOR(S): ADDRESSEE(S):  
Steven H. Reimer/EPA Loren C. McPhillips/EPA

DESCRIPTION: Validation Memo Quality Assurance for water samples for pentachlorophenol; Project Code: TEC-440H.

2. 4... Vol. 1 - DOC ID: 1150123 IMAGED  
DATE: 3/11/2002 PAGES: 70  
AUTHOR(S): ADDRESSEE(S):  
M. K. Parker/EPA Loren C. McPhillips/EPA

DESCRIPTION: Quality assurance data review of classical chemistry analyses for fluoride, chloride, sulfate, total dissolved solids, and mercury; Project TEC-440H.

2. 4... Vol. 1 - DOC ID: 1150124 IMAGED  
DATE: 4/19/2002 PAGES: 136  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Loren C. McPhillips/EPA

DESCRIPTION: Quality assurance review of 28 water samples; Project Code: TEC-440H.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

2. 4... Vol. 1 - DOC ID: 1150125 IMAGED  
DATE: 4/19/2002 PAGES: 119  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Loren C. McPhillips/EPA

DESCRIPTION: Quality assurance review of 28 water samples; Project Code: TEC-440H.

2. 4... Vol. 1 - DOC ID: 1150126 IMAGED  
DATE: 5/13/2002 PAGES: 44  
AUTHOR(S): ADDRESSEE(S):  
Katherine "Katie" Adams/EPA Loren C. McPhillips/EPA

DESCRIPTION: Review and verification of metals results from 28 water samples; Project Code: TEC-440H.

2. 4... Vol. 1 - DOC ID: 1150127 IMAGED  
DATE: 5/15/2002 PAGES: 178  
AUTHOR(S): ADDRESSEE(S):  
EPA EPA

DESCRIPTION: Combined Final Report for Project TEC-440H.

2. 4... Vol. 1 - DOC ID: 1150128 IMAGED  
DATE: 6/17/2002 PAGES: 44  
AUTHOR(S): ADDRESSEE(S):  
Steven H. Reimer/EPA Loren C. McPhillips/EPA

DESCRIPTION: Validation Memo Quality Assurance for water samples; Project Code TEC-440I.

2. 4... Vol. 1 - DOC ID: 1150129 IMAGED  
DATE: 6/26/2002 PAGES: 32  
AUTHOR(S): ADDRESSEE(S):  
M. K. Parker/EPA Loren C. McPhillips/EPA

DESCRIPTION: Quality assurance data review of classical chemistry analyses; Project Code TEC-440I.

2. 4... Vol. 1 - DOC ID: 1150130 IMAGED  
DATE: 7/1/2002 PAGES: 15  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Loren C. McPhillips/EPA

DESCRIPTION: Quality assurance review of seven water samples analyzed for total metals.

2. 4... Vol. 1 - DOC ID: 1150131 IMAGED  
DATE: 7/2/2002 PAGES: 27  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Chris Pace/EPA

Loren C. McPhillips/EPA

DESCRIPTION:

Quality assurance review of nineteen water samples analyzed for total metals.

2. 4... Vol. 1 -

DATE: 7/2/2002

DOC ID: 1150132 IMAGED

PAGES: 101

AUTHOR(S):

Gerald H. Dodo/EPA

ADDRESSEE(S):

Loren C. McPhillips/EPA

DESCRIPTION:

Data validation report of semivolatiles analyses results for water samples.

2. 4... Vol. 1 -

DATE: 7/10/2002

DOC ID: 1150133 IMAGED

PAGES: 43

AUTHOR(S):

Gerald H. Dodo/EPA

ADDRESSEE(S):

Loren C. McPhillips/EPA

DESCRIPTION:

Peer review and data validation report of the low level polynuclear aromatic hydrocarbon analyses results for water samples; Project Code TEC 440I.

2. 4... Vol. 1 -

DATE: 7/13/2002

DOC ID: 1150135 IMAGED

PAGES: 123

AUTHOR(S):

EPA

ADDRESSEE(S):

EPA

DESCRIPTION:

Combined Final Report for Project TEC-440I.

2. 4... Vol. 1 -

DATE: 8/23/2002

DOC ID: 1150884 IMAGED

PAGES: 4

AUTHOR(S):

EPA

ADDRESSEE(S):

Unknown

DESCRIPTION:

Temperature log of samples received; Project Code TEC-440K.

2. 4... Vol. 1 -

DATE: 8/30/2002

DOC ID: 1150136 IMAGED

PAGES: 27

AUTHOR(S):

Chris Pace/EPA

ADDRESSEE(S):

Loren C. McPhillips/EPA

DESCRIPTION:

Quality assurance review of nineteen soil samples analyzed for total metals.

2. 4... Vol. 1 -

DATE: 9/3/2002

DOC ID: 1150137 IMAGED

PAGES: 29

AUTHOR(S):

Chris Pace/EPA

ADDRESSEE(S):

Loren C. McPhillips/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Quality assurance review of nineteen soil samples analyzed for total metals.

2. 4... Vol. 1 -	DOC ID: 1150138	IMAGED
DATE: 9/3/2002	PAGES: 9	
AUTHOR(S):	ADDRESSEE(S):	
Chris Pace/EPA	Loren C. McPhillips/EPA	

DESCRIPTION:

Quality assurance review of one rinsate blank sample analyzed for total metals.

2. 4... Vol. 1 -	DOC ID: 1150139	IMAGED
DATE: 9/4/2002	PAGES: 28	
AUTHOR(S):	ADDRESSEE(S):	
Chris Pace/EPA	Loren C. McPhillips/EPA	

DESCRIPTION:

Quality assurance review of twenty soil samples analyzed for total metals.

2. 4... Vol. 1 -	DOC ID: 1150140	IMAGED
DATE: 9/5/2002	PAGES: 75	
AUTHOR(S):	ADDRESSEE(S):	
Chris Pace/EPA	Loren C. McPhillips/EPA	

DESCRIPTION:

Quality assurance review of twenty soil samples analyzed for semi-volatile organic compounds.

2. 4... Vol. 1 -	DOC ID: 1150141	IMAGED
DATE: 9/6/2002	PAGES: 47	
AUTHOR(S):	ADDRESSEE(S):	
Chris Pace/EPA	Loren C. McPhillips/EPA	

DESCRIPTION:

Quality assurance review of thirteen water samples analyzed for semi-volatile organic compounds.

2. 4... Vol. 1 -	DOC ID: 1150142	IMAGED
DATE: 9/6/2002	PAGES: 17	
AUTHOR(S):	ADDRESSEE(S):	
M. K. Parker/EPA	Loren C. McPhillips/EPA	

DESCRIPTION:

Tabular report of nine Mercury TCLP samples.

2. 4... Vol. 1 -	DOC ID: 1150143	IMAGED
DATE: 9/9/2002	PAGES: 65	
AUTHOR(S):	ADDRESSEE(S):	
Chris Pace/EPA	Loren C. McPhillips/EPA	

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Quality assurance review of nineteen soil samples analyzed for semi-volatile organic compounds.

2. 4... Vol. 1 -                      DOC ID: 1150887    IMAGED  
    DATE: 9/16/2002              PAGES: 21  
AUTHOR(S):                                      ADDRESSEE(S):  
    Gerald H. Dodo/EPA                      Loren C. McPhillips/EPA

DESCRIPTION:

Data verification report of TCLP semivolatiles for soil samples; Project Code TEC-440J.

2. 4... Vol. 1 -                      DOC ID: 1150873    IMAGED  
    DATE: 9/20/2002              PAGES: 24  
AUTHOR(S):                                      ADDRESSEE(S):  
    Chris Pace/EPA                      Loren C. McPhillips/EPA

DESCRIPTION:

Data validation report for the inorganic analysis of soil samples, Case 30784, SDG MJ0MA6.

2. 4... Vol. 1 -                      DOC ID: 1150874    IMAGED  
    DATE: 9/20/2002              PAGES: 9  
AUTHOR(S):                                      ADDRESSEE(S):  
    Chris Pace/EPA                      Loren C. McPhillips/EPA

DESCRIPTION:

Data validation report for the inorganic analysis of one water sample, Case 30784, SDG MJ0ME4.

2. 4... Vol. 1 -                      DOC ID: 1150875    IMAGED  
    DATE: 9/23/2002              PAGES: 17  
AUTHOR(S):                                      ADDRESSEE(S):  
    Chris Pace/EPA                      Loren C. McPhillips/EPA

DESCRIPTION:

Data validation report for the inorganic analysis of soil samples, Case 30784, SDG MJ0MA7.

2. 4... Vol. 1 -                      DOC ID: 1150888    IMAGED  
    DATE: 9/27/2002              PAGES: 46  
AUTHOR(S):                                      ADDRESSEE(S):  
    Gerald H. Dodo/EPA                      Loren C. McPhillips/EPA

DESCRIPTION:

Peer review and data verification report of low level polynuclear aromatic hydrocarbon results for water samples; Project Code TEC-440K.

2. 4... Vol. 1 -                      DOC ID: 1150876    IMAGED  
    DATE: 10/1/2002              PAGES: 77  
AUTHOR(S):                                      ADDRESSEE(S):  
    Chris Pace/EPA                      Loren C. McPhillips/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Data validation report for the semi-volatile organic compound analysis of soil samples, Case 30784, SDG JOLN4.

2. 4... Vol. 1 -                      DOC ID: 1150877    IMAGED  
    DATE: 10/2/2002              PAGES: 31  
AUTHOR(S):                                      ADDRESSEE(S):  
    Chris Pace/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

Data validation report for the semi-volatile organic compound analysis of soil samples, Case 30784, SDG JOLR7.

2. 4... Vol. 1 -                      DOC ID: 1150878    IMAGED  
    DATE: 10/3/2002              PAGES: 66  
AUTHOR(S):                                      ADDRESSEE(S):  
    Chris Pace/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

Data validation report for the semi-volatile organic compound analysis of soil samples, Case 30784, SDG JOLW2.

2. 4... Vol. 1 -                      DOC ID: 1150886    IMAGED  
    DATE: 10/3/2002              PAGES: 19  
AUTHOR(S):                                      ADDRESSEE(S):  
    Gerald H. Dodo/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

Memo regarding resubmission of TCLP semivolatiles; Project Code TEC-440J.

2. 4... Vol. 1 -                      DOC ID: 1150868    IMAGED  
    DATE: 10/15/2002              PAGES: 17  
AUTHOR(S):                                      ADDRESSEE(S):  
    Laura Castrilli/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

CLP Metals Analysis, Data Validation, Case 30869, SDG MJ0MG9.

2. 4... Vol. 1 -                      DOC ID: 1150869    IMAGED  
    DATE: 10/15/2002              PAGES: 18  
AUTHOR(S):                                      ADDRESSEE(S):  
    Laura Castrilli/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

CLP Metals Analysis, Data Validation, Case 30869, SDG MJ0MJ1.

2. 4... Vol. 1 -                      DOC ID: 1150870    IMAGED  
    DATE: 10/15/2002              PAGES: 18  
AUTHOR(S):                                      ADDRESSEE(S):  
    Laura Castrilli/EPA                                      Loren C. McPhillips/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

CLP Metals Analysis, Data Validation, Case 30869, SDG MJ0MQ3.

2. 4... Vol. 1 - DOC ID: 1150889 IMAGED  
DATE: 10/17/2002 PAGES: 122  
AUTHOR(S): ADDRESSEE(S):  
Steven H. Reimer/EPA Loren C. McPhillips/EPA

DESCRIPTION:

Peer review and validation memo quality assurance narrative for water samples analyzed for pentachlorophenol; Project Code TEC-440K.

2. 4... Vol. 1 - DOC ID: 1150885 IMAGED  
DATE: 10/24/2002 PAGES: 31  
AUTHOR(S): ADDRESSEE(S):  
Peggy Knight/EPA Scott Echols/CH2M Hill, Inc.

DESCRIPTION:

Email explaining method of reporting data and transmitting a reissuance of the data; Project Code TEC-440I.

2. 4... Vol. 1 - DOC ID: 1150891 IMAGED  
DATE: 10/28/2002 PAGES: 36  
AUTHOR(S): ADDRESSEE(S):  
Katherine "Katie" Adams/EPA Loren C. McPhillips/EPA

DESCRIPTION:

Review and validation of soils and TCLP analysis for metals; Project Code TEC-440J.

2. 4... Vol. 1 - DOC ID: 1150890 IMAGED  
DATE: 10/29/2002 PAGES: 129  
AUTHOR(S): ADDRESSEE(S):  
Manchester Environmental Laboratory File

DESCRIPTION:

Combined final report for Project Code TEC-440I.

2. 4... Vol. 1 - DOC ID: 1150892 IMAGED  
DATE: 10/29/2002 PAGES: 85  
AUTHOR(S): ADDRESSEE(S):  
Katherine "Katie" Adams/EPA Loren C. McPhillips/EPA

DESCRIPTION:

Review and validation of water analysis for metals; Project Code TEC-440J.

2. 4... Vol. 1 - DOC ID: 1150879 IMAGED  
DATE: 11/5/2002 PAGES: 67  
AUTHOR(S): ADDRESSEE(S):  
Chris Pace/EPA Loren C. McPhillips/EPA



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Data validation report for the semi-volatile organic compound analysis of water samples, Case 30869, SDG J0LY9.

2. 4... Vol. 1 -                      DOC ID: 1150880    IMAGED  
    DATE: 11/5/2002              PAGES: 44  
AUTHOR(S):                                      ADDRESSEE(S):  
    Chris Pace/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

Data validation report for the semi-volatile organic compound analysis of water samples, Case 30869, SDG J0M08.

2. 4... Vol. 1 -                      DOC ID: 1150881    IMAGED  
    DATE: 11/5/2002              PAGES: 47  
AUTHOR(S):                                      ADDRESSEE(S):  
    Chris Pace/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

Data validation report for the semi-volatile organic compound analysis of water samples, Case 30869, SDG J0M22.

2. 4... Vol. 1 -                      DOC ID: 1150883    IMAGED  
    DATE: 12/13/2002              PAGES: 35  
AUTHOR(S):                                      ADDRESSEE(S):  
    M. K. Parker/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

Quality assurance data review of classical chemistry analysis; Project Code TEC-440L.

2. 4... Vol. 1 -                      DOC ID: 1150871    IMAGED  
    DATE: 12/16/2002              PAGES: 19  
AUTHOR(S):                                      ADDRESSEE(S):  
    Laura Castrilli/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

CLP Metals Analysis, Data Validation, Case 31194, SDG MJ0TE2.

2. 4... Vol. 1 -                      DOC ID: 1150872    IMAGED  
    DATE: 12/16/2002              PAGES: 21  
AUTHOR(S):                                      ADDRESSEE(S):  
    Laura Castrilli/EPA                                      Loren C. McPhillips/EPA

DESCRIPTION:

CLP Metals Analysis, Data Validation, Case 31194, SDG MJ0TE4.

2. 4... Vol. 1 -                      DOC ID: 1150882    IMAGED  
    DATE: 1/13/2003              PAGES: 92  
AUTHOR(S):                                      ADDRESSEE(S):  
    Chris Pace/EPA                                      Loren C. McPhillips/EPA

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Data validation report for the semi-volatile organic compound full scan and selected monitoring analysis of water samples, Case 31194, SDG J0TF5 (full scan), J0TG8 (SIM).

2. 4... Vol. 1 -                      DOC ID: 1224674    IMAGED  
    DATE: 5/25/2005              PAGES: 3  
AUTHOR(S):                      ADDRESSEE(S):  
    Wendi Gale/CH2M Hill, Inc.              Trish Larson/CH2M Hill, Inc.  
  
   Robin Strauss/CH2M Hill, Inc.

DESCRIPTION:

Technical Memorandum: Data Usability Review Report for Dioxins/Furans - Taylor Lumber and Treating Field Investigation Soil Samples - April 2005 Sampling Event.

2. 4... Vol. 1 -                      DOC ID: 1224675    IMAGED  
    DATE: 7/7/2005              PAGES: 37  
AUTHOR(S):                      ADDRESSEE(S):  
    Robin Strauss/CH2M Hill, Inc.              Karen L. Keeley/EPA  
  
    Barry Collom/CH2M Hill, Inc.

DESCRIPTION:

Memorandum: April 2005 Sampling Event, Field and Data Report.

**SUB-HEAD: 2. 7... Vol. 1 -                      Reports**

**SUB-HEAD: 2. 7. 1.. Vol. 1 -                      Remedial Investigation/Feasibility Study Report**

2. 7. 1.. Vol. 1 -                      DOC ID: 1132357    IMAGED  
    DATE: 1/1/2002              PAGES: 334  
AUTHOR(S):                      ADDRESSEE(S):  
    CH2M Hill, Inc.                      EPA

DESCRIPTION:

Phase 1 Remedial Investigation Report.

2. 7. 1.. Vol. 1 -                      DOC ID: 1205711    IMAGED  
    DATE: 12/1/2004              PAGES: 326  
AUTHOR(S):                      ADDRESSEE(S):  
    CH2M Hill, Inc.                      EPA

DESCRIPTION:

Volume I, Remedial Investigation Report, and Appendix A.

2. 7. 1.. Vol. 1 -                      DOC ID: 1205712    IMAGED  
    DATE: 12/1/2004              PAGES: 531  
AUTHOR(S):                      ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

CH2M Hill, Inc.

EPA

DESCRIPTION: Volume II, Remedial Investigation Report Appendices B through E.

2. 7. 1.. Vol. 1 - DOC ID: 1205713 IMAGED  
DATE: 12/1/2004 PAGES: 474  
AUTHOR(S): CH2M Hill, Inc. ADDRESSEE(S):  
EPA

DESCRIPTION: Volume III, Baseline Risk Assessment.

2. 7. 1.. Vol. 1 - DOC ID: 1205714 IMAGED  
DATE: 12/1/2004 PAGES: 174  
AUTHOR(S): CH2M Hill, Inc. ADDRESSEE(S):  
EPA

DESCRIPTION: Volume IV, Feasibility Study.

2. 7. 1.. Vol. 1 - DOC ID: 1205768 IMAGED  
DATE: 5/18/2005 PAGES: 7  
AUTHOR(S): Robin Strauss/CH2M Hill, Inc. ADDRESSEE(S):  
Karen L. Keeley/EPA

Michael Niemet/CH2M Hill, Inc.

DESCRIPTION: Memo containing an errata sheet for the Remedial Investigation/Feasibility Study Report, and responses to comments.

Revised Figures 4-1 and 4-2 and the revised sections of the Baseline Risk Assessment are inserted into their respective documents.

**SUB-HEAD: 2. 7. 1. 1. Vol. 1 - Final RI/FS Report on CD-ROM**

2. 7. 1. 1. Vol. 1 - DOC ID: 1205845 IMAGED  
DATE: 5/18/2005 PAGES: 1  
AUTHOR(S): CH2M Hill, Inc. ADDRESSEE(S):  
EPA

DESCRIPTION: CD-ROM containing the final Remedial Investigation/Feasibility Study Report, Volumes I-IV, and the Errata Memo.

**SUB-HEAD: 2. 9... Vol. 1 - Proposed Plan**

2. 9... Vol. 1 - DOC ID: 1205961 IMAGED  
DATE: 7/21/2005 PAGES: 29  
AUTHOR(S): EPA ADDRESSEE(S):  
Unknown

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Proposed Plan for the Taylor Lumber and Treating Superfund Site.

**SUB-HEAD: 2. 9. 1.. Vol. 1 -**

**Comments on Proposed Plan**

2. 9. 1.. Vol. 1 -

DOC ID: 1224662 IMAGED

DATE: 8/22/2005

PAGES: 2

AUTHOR(S):

Robert Halderman/Pacific Wood Preserving of Oregon, Inc.

ADDRESSEE(S):

Karen L. Keeley/EPA

DESCRIPTION:

Letter commenting on the Taylor Lumber Proposed Plan.

2. 9. 1.. Vol. 1 -

DOC ID: 1224663 IMAGED

DATE: 8/22/2005

PAGES: 2

AUTHOR(S):

Sonia Shoukry/InterLink Business Management, Inc.

ADDRESSEE(S):

Karen L. Keeley/EPA

DESCRIPTION:

Letter commenting on the Taylor Lumber Proposed Plan.

2. 9. 1.. Vol. 1 -

DOC ID: 1224664 IMAGED

DATE: 8/25/2005

PAGES: 6

AUTHOR(S):

Scott Slesinger/Environmental Technology Council

ADDRESSEE(S):

Karen L. Keeley/EPA

DESCRIPTION:

Letter commenting on the Taylor Lumber Proposed Plan.

Note: RPM Karen Keeley says author actually commented on the Proposed Plan, incorrectly referencing the Feasibility Study.

**HEADING: 3. 0... RECORD OF DECISION**

**SUB-HEAD: 3. 1... Vol. 1 - Correspondence/Email**

3. 1... Vol. 1 -                      DOC ID: 1224676   IMAGED  
    DATE: 9/26/2005              PAGES: 1  
AUTHOR(S):                                      ADDRESSEE(S):  
    Karen L. Keeley/EPA                      Sheila M. Eckman/EPA

DESCRIPTION:              Email regarding a Tribal contact update on the Record of Decision.

3. 1... Vol. 1 -                      DOC ID: 1224677   IMAGED  
    DATE: 9/30/2005              PAGES: 1  
AUTHOR(S):                                      ADDRESSEE(S):  
    Kerri L. Nelson/Oregon State Dept. of Environmental Quality              Daniel D. Opalski/EPA

DESCRIPTION:              Letter concurring with the Record of Decision.

**SUB-HEAD: 3. 2... Vol. 1 - Record of Decision**

3. 2... Vol. 1 -                      DOC ID: 1224678   IMAGED  
    DATE: 9/30/2005              PAGES: 96  
AUTHOR(S):                                      ADDRESSEE(S):  
    EPA    Unknown

DESCRIPTION:              Final Record of Decision, Taylor Lumber and Treating Superfund Site.  
                                    Note: The EPA Identification Number cited in the Record of Decision should be ORD009042532.

3. 2... Vol. 1 -                      DOC ID: 1224771   IMAGED  
    DATE: 9/30/2005              PAGES: 1  
AUTHOR(S):                                      ADDRESSEE(S):  
    Karen L. Keeley/EPA                      File

DESCRIPTION:              Memo correcting the Taylor Lumber EPA Identification Number cited in the Record of Decision.  
                                    The correct ID Number is ORD009042532.

**HEADING: 4. 0... POST-NPL REMOVAL ACTIONS**

**SUB-HEAD: 4. 3... Vol. 1 - Action Memoranda**

4. 3... Vol. 1 - DOC ID: 1205938 IMAGED  
DATE: 10/25/2004 PAGES: 28  
AUTHOR(S): ADDRESSEE(S):  
Carl G. Kitz/EPA Daniel D. Opalski/EPA

DESCRIPTION: Action Memorandum: Request for a Time-Critical Removal Action at the Klingler property.  
Note: This is the Redacted Version of Confidential document No. 1205939.

**SUB-HEAD: 4. 5... Vol. 1 - Removal Action Report**

4. 5... Vol. 1 - DOC ID: 1205480 IMAGED  
DATE: 1/31/2005 PAGES: 49  
AUTHOR(S): ADDRESSEE(S):  
Renee Nordeen/Ecology & Environment, Inc. Carl G. Kitz/EPA

DESCRIPTION: Taylor Lumber Removal Site Trip Report; TDD: 04-11-0001; Klingler residence.

**SUB-HEAD: 4. 7... Vol. 1 - NPDES Waste Discharge Permit**

4. 7... Vol. 1 - DOC ID: 1205844 IMAGED  
DATE: 12/29/2004 PAGES: 35  
AUTHOR(S): ADDRESSEE(S):  
Michael H. Korten Hof/Oregon State Dept. of Environmental Pacific Wood Preserving of Oregon, Inc.  
Quality

DESCRIPTION: National Pollutant Discharge Elimination System Waste Discharge Permit No. 101267.

**HEADING: 8. 0... STATE COORDINATION**

**SUB-HEAD: 8. 1... Vol. 1 - Correspondence/Email**

8. 1... Vol. 1 - 1124179 DOC ID: 1124179 IMAGED  
DATE: 1/26/1998 PAGES: 26  
AUTHOR(S): Gary Messer/Oregon State Dept. of Environmental Quality ADDRESSEE(S): Taylor Lumber and Treating, Inc.

DESCRIPTION: Letter transmits an Air Contaminant Discharge Permit.

8. 1... Vol. 1 - 1116371 DOC ID: 1116371 IMAGED  
DATE: 8/23/2000 PAGES: 2  
AUTHOR(S): Charles E. Findley/EPA ADDRESSEE(S): John A. Kitzhaber/State of Oregon

DESCRIPTION: Letter seeks State concurrence to place Taylor Lumber on the National Priorities List.

8. 1... Vol. 1 - DOC ID: 1205749 IMAGED  
DATE: 9/27/2000 PAGES: 2  
AUTHOR(S): John A. Kitzhaber/State of Oregon ADDRESSEE(S): Carol M. Browner/EPA

DESCRIPTION: Letter concurs with proposal to place Taylor Lumber on National Priorities List.

8. 1... Vol. 1 - DOC ID: 1224718 IMAGED  
DATE: 12/20/2001 PAGES: 4  
AUTHOR(S): Marilyn Daniel/Oregon State Dept. of Environmental Quality ADDRESSEE(S): Loren C. McPhillips/EPA  
Robin Strauss/CH2M Hill, Inc.

DESCRIPTION: Memo commenting on the draft Phase I Remedial Investigation Report.

8. 1... Vol. 1 - DOC ID: 1224719 IMAGED  
DATE: 1/29/2003 PAGES: 3  
AUTHOR(S): Nancy Sawka/Oregon State Dept. of Environmental Quality ADDRESSEE(S): Loren C. McPhillips/EPA

DESCRIPTION: Memo commenting on the draft Conceptual Exposure Model and Baseline Risk Assessment Outline.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

8. 1... Vol. 1 - DOC ID: 1224720 IMAGED  
DATE: 11/26/2003 PAGES: 2  
AUTHOR(S): Nancy Sawka/Oregon State Dept. of Environmental Quality ADDRESSEE(S):  
Loren C. McPhillips/EPA

DESCRIPTION: Letter commenting on the October 2003 draft Remedial Investigation Report.

8. 1... Vol. 1 - DOC ID: 1224721 IMAGED  
DATE: 12/4/2003 PAGES: 9  
AUTHOR(S): Nancy Sawka/Oregon State Dept. of Environmental Quality ADDRESSEE(S):  
Loren C. McPhillips/EPA

DESCRIPTION: Letter commenting on the October 2003 draft Baseline Risk Assessment Report.

8. 1... Vol. 1 - DOC ID: 1224722 IMAGED  
DATE: 8/25/2004 PAGES: 5  
AUTHOR(S): Nancy Sawka/Oregon State Dept. of Environmental Quality ADDRESSEE(S):  
Loren C. McPhillips/EPA

DESCRIPTION: Letter commenting on the July 2004 draft Feasibility Study Report.

8. 1... Vol. 1 - DOC ID: 1224668 IMAGED  
DATE: 6/30/2005 PAGES: 1  
AUTHOR(S): Karen L. Keeley/EPA ADDRESSEE(S):  
Nancy Sawka/Oregon State Dept. of Environmental  
Quality

DESCRIPTION: Email transmitting guidance on ARARs. (Less attachment)

8. 1... Vol. 1 - DOC ID: 1224679 IMAGED  
DATE: 8/5/2005 PAGES: 1  
AUTHOR(S): Nancy Sawka/Oregon State Dept. of Environmental Quality ADDRESSEE(S):  
George Gabriel/Squires Holdings, LLC

DESCRIPTION: Letter urging addressee to review and comment on the Taylor Lumber Proposed Plan.

8. 1... Vol. 1 - DOC ID: 1224680 IMAGED  
DATE: 8/5/2005 PAGES: 1  
AUTHOR(S): Nancy Sawka/Oregon State Dept. of Environmental Quality ADDRESSEE(S):  
Robert Harris/"D" Stake Mill, Inc.

DESCRIPTION: Letter urging addressee to review and comment on the Taylor Lumber Proposed Plan.

8. 1... Vol. 1 - DOC ID: 1224681 IMAGED  
DATE: 8/5/2005 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Nancy Sawka/Oregon State Dept. of Environmental Quality      J. J. Klingler/Unknown

DESCRIPTION: Letter urging addressee to review and comment on the Taylor Lumber Proposed Plan.

**HEADING: 10. 0... TRIBAL COORDINATION**

**SUB-HEAD: 10. 1... Vol. 1 - Grand Ronde Tribe**

10. 1... Vol. 1 - DOC ID: 1224723 IMAGED  
DATE: 11/21/2003 PAGES: 6  
AUTHOR(S): ADDRESSEE(S):  
Rodney N. Thompson/Confederated Tribes of the Grand Loren C. McPhillips/EPA  
Ronde Community of Oregon  
Pamela J. Bridgen/Environment International, Ltd.

DESCRIPTION: Memo commenting on the Remedial Investigation and Baseline Risk Assessment Reports.

10. 1... Vol. 1 - DOC ID: 1224724 IMAGED  
DATE: 8/27/2004 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Pamela J. Bridgen/Environment International, Ltd. Loren C. McPhillips/EPA

Rodney N. Thompson/Confederated Tribes of the Grand  
Ronde Community of Oregon

DESCRIPTION: Memo commenting on the draft Feasibility Study Report.

10. 1... Vol. 1 - DOC ID: 1224667 IMAGED  
DATE: 6/20/2005 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
Jeff Baker/Confederated Tribes of the Grand Ronde Mark Brady/Environment International, Ltd.  
Community of Oregon

DESCRIPTION: Email commenting on the draft Proposed Plan.

**HEADING: 12. 0... ENFORCEMENT**

**SUB-HEAD: 12. 1... Vol. 1 - Correspondence/Email**

12. 1... Vol. 1 - 1088893 DOC ID: 1088893 IMAGED  
DATE: 4/26/1999 PAGES: 1  
AUTHOR(S): ADDRESSSEE(S):  
Michael F. Gearheard/EPA Bruce Summers/Taylor Lumber and Treating, Inc.

DESCRIPTION: Correspondence responding to letter of 4/6/99 requesting meeting with EPA personnel to discuss issues arising from Taylor Lumber obligations under corrective action order.

12. 1... Vol. 1 - 1088896 DOC ID: 1088896 IMAGED  
DATE: 11/5/1999 PAGES: 30 MICROFILM: BEGIN: END:  
AUTHOR(S): ADDRESSSEE(S):  
Michael F. Gearheard/EPA Bruce Summers/Taylor Lumber and Treating, Inc.

DESCRIPTION: Letter grants Taylor Lumber's request to be given time to perform removal activities contingent on acceptance of the Unilateral Administrative Order and Work Plan.

12. 1... Vol. 1 - 1116339 DOC ID: 1116339 IMAGED  
DATE: 9/26/2000 PAGES: 8 MICROFILM: BEGIN: END:  
AUTHOR(S): ADDRESSSEE(S):  
Amber L. Wong/EPA David M. Evans/EPA

DESCRIPTION: Memo requests a waiver of RCRA deferral.

**SUB-HEAD: 12. 6... Vol. 1 - Administrative Orders**

12. 6... Vol. 1 - 1088910 DOC ID: 1088910 IMAGED  
DATE: 11/12/1999 PAGES: 27 MICROFILM: BEGIN: END:  
AUTHOR(S): ADDRESSSEE(S):  
Michael F. Gearheard/EPA Taylor Lumber and Treating, Inc.

DESCRIPTION: Unilateral Administrative Order for Removal Response Activities.

**SUB-HEAD: 12. 9... Vol. 1 - Prospective Purchaser Agreement**

12. 9... Vol. 1 - DOC ID: 1144604 IMAGED  
DATE: 2/1/2002 PAGES: 30  
AUTHOR(S): ADDRESSSEE(S):  
L. John Iani/EPA Elaina Jackson/Pacific Wood Preserving of Oregon, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Prospective Purchaser Agreement, Pacific Wood Preserving of Oregon, Agreement and Covenant Not To Sue.

12. 9... Vol. 1 -

DATE: 8/8/2002

DOC ID: 1224725 IMAGED

PAGES: 2

AUTHOR(S):

Loren C. McPhillips/EPA

ADDRESSEE(S):

Roland Mueller/Pacific Wood Preserving of Oregon, Inc.

DESCRIPTION:

Letter discussing maintenance of the asphalt cover, and other site activities.

12. 9... Vol. 1 -

DATE: 9/16/2002

DOC ID: 1224726 IMAGED

PAGES: 2

AUTHOR(S):

Loren C. McPhillips/EPA

ADDRESSEE(S):

Roland Mueller/Pacific Wood Preserving of Oregon, Inc.

DESCRIPTION:

Letter discussing the beneficial reuse of excavated soil.

12. 9... Vol. 1 -

DATE: 11/27/2002

DOC ID: 1224727 IMAGED

PAGES: 29

AUTHOR(S):

Charles R. Blumenfeld/Perkins Coie

ADDRESSEE(S):

Jennifer Byrne/EPA

Loren C. McPhillips/EPA

DESCRIPTION:

Letter submitting the Prospective Purchaser Agreement; Docket CERCLA 10-2002-0034, filed with the Yamhill County Recorder June 18, 2002.

12. 9... Vol. 1 -

DATE: 1/13/2003

DOC ID: 1224728 IMAGED

PAGES: 1

AUTHOR(S):

Robert Halderman/Pacific Wood Preserving of Oregon, Inc.

ADDRESSEE(S):

Loren C. McPhillips/EPA

DESCRIPTION:

Letter regarding maintenance of the asphalt cover.

12. 9... Vol. 1 -

DATE: 5/19/2003

DOC ID: 1224729 IMAGED

PAGES: 1

AUTHOR(S):

Robert Halderman/Pacific Wood Preserving of Oregon, Inc.

ADDRESSEE(S):

Loren C. McPhillips/EPA

DESCRIPTION:

Letter regarding maintenance of the asphalt cover.

12. 9... Vol. 1 -

DATE: 7/25/2005

DOC ID: 1224730 IMAGED

PAGES: 2

AUTHOR(S):

Karen L. Keeley/EPA

ADDRESSEE(S):

Roland Mueller/Pacific Wood Preserving of Oregon, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION: Email regarding compliance with the Prospective Purchaser Agreement.

**HEADING: 13. 0... HEALTH ASSESSMENTS**

**SUB-HEAD: 13. 1... Vol. 1 - Correspondence**

13. 1... Vol. 1 -                      DOC ID: 1164370 IMAGED  
DATE: 12/22/2003                      PAGES: 1  
AUTHOR(S):                                      ADDRESSEE(S):  
Max M. Howie/ATSDR                      Loren C. McPhillips/EPA

DESCRIPTION: Letter transmitting the December 16, 2003 Public Health Assessment. (Less enclosure)

**SUB-HEAD: 13. 2... Vol. 1 - ATSDR Health Assessment**

13. 2... Vol. 1 -                      1127752                      DOC ID: 1127752 IMAGED  
DATE: 10/14/1999                      PAGES: 8  
AUTHOR(S):                                      ADDRESSEE(S):  
U. S. Dept. of Health and Human Services                      Unknown

DESCRIPTION: Health Consultation.

13. 2... Vol. 1 -                      1127751                      DOC ID: 1127751 IMAGED  
DATE: 11/15/1999                      PAGES: 6  
AUTHOR(S):                                      ADDRESSEE(S):  
U. S. Dept. of Health and Human Services                      Unknown

DESCRIPTION: Health Consultation.

13. 2... Vol. 1 -                      1127764                      DOC ID: 1127764 IMAGED  
DATE: 11/24/1999                      PAGES: 6  
AUTHOR(S):                                      ADDRESSEE(S):  
U. S. Dept. of Health and Human Services                      Unknown

DESCRIPTION: Health Consultation.

13. 2... Vol. 1 -                      1114266                      DOC ID: 1114266 IMAGED  
DATE: 5/19/2000                      PAGES: 7  
AUTHOR(S):                                      ADDRESSEE(S):  
ATSDR                                      Unknown

DESCRIPTION: Health Consultation, Taylor Lumber and Treating, Inc., Sheridan, Yamhill County, Oregon.

## 13. 2... Vol. 1 -

DATE: 12/16/2003

PAGES: 39

AUTHOR(S):

ADDRESSEE(S):

Unknown

ATSDR

DESCRIPTION:

Public Health Assessment for Taylor Lumber and Treating, Inc.

**HEADING: 14. 0... NATURAL RESOURCE TRUSTEES**

**SUB-HEAD: 14. 1... Vol. 1 - Correspondence**

14. 1... Vol. 1 - 1116572 DOC ID: 1116572 IMAGED  
DATE: 6/14/1991 PAGES: 11  
AUTHOR(S): ADDRESSEE(S):  
Jonathan P. Deason/U. S. Dept. of the Interior Charles E. Findley/EPA

DESCRIPTION: Letter discusses the results of a preliminary natural resources survey on the Taylor site.

14. 1... Vol. 1 - 1116356 DOC ID: 1116356 IMAGED  
DATE: 6/28/2000 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
Helen E. Hillman/NOAA Mark A. Ader/EPA

DESCRIPTION: Letter supports placing Taylor Lumber on the National Priorities List.

14. 1... Vol. 1 - DOC ID: 1193897 IMAGED  
DATE: 1/4/2002 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
David C. Powell/NOAA Loren C. McPhillips/EPA

DESCRIPTION: Letter reviewing the Phase 1 Remedial Investigation.

14. 1... Vol. 1 - DOC ID: 1224709 IMAGED  
DATE: 11/20/2003 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Marla Steinhoff/NOAA Loren C. McPhillips/EPA

DESCRIPTION: Letter commenting on the Phase 2 Remedial Investigation.

14. 1... Vol. 1 - DOC ID: 1224711 IMAGED  
DATE: 8/24/2004 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
Marla Steinhoff/NOAA Loren C. McPhillips/EPA

DESCRIPTION: Letter commenting on the draft Feasibility Study.



**HEADING: 16. 0... PUBLIC PARTICIPATION**

**SUB-HEAD: 16. 1... Vol. 1 - Correspondence**

**SUB-HEAD: 16. 2... Vol. 1 - Community Relations Plan**

16. 2... Vol. 1 - 1109195 DOC ID: 1109195 IMAGED  
DATE: 2/1/2000 PAGES: 7  
AUTHOR(S): ADDRESSEE(S):  
EPA Unknown

DESCRIPTION: Community Involvement Plan, Taylor Lumber Treatment Inc. Superfund Site, Sheridan, Oregon.

16. 2... Vol. 1 - DOC ID: 1224733 IMAGED  
DATE: 5/1/2001 PAGES: 6  
AUTHOR(S): ADDRESSEE(S):  
EPA Unknown

DESCRIPTION: Community Involvement Plan.

16. 2... Vol. 1 - DOC ID: 1224732 IMAGED  
DATE: 1/1/2002 PAGES: 8  
AUTHOR(S): ADDRESSEE(S):  
EPA Unknown

DESCRIPTION: Community Involvement Plan.

**SUB-HEAD: 16. 5... Vol. 1 - Fact Sheets/Press Releases**

16. 5... Vol. 1 - 1088911 DOC ID: 1088911 IMAGED  
DATE: 11/1/1999 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
EPA Unknown

DESCRIPTION: EPA Fact Sheet. In the next couple of weeks, either the EPA or Taylor Lumber, will begin removal activities.

16. 5... Vol. 1 - 1127679 DOC ID: 1127679 IMAGED  
DATE: 11/8/1999 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

EPA

Unknown

DESCRIPTION:

EPA News Release: Wood Treating Plant on S. Yamhill Issued Cleanup Ultimatum By EPA.

16. 5... Vol. 1 - 1086884 DOC ID: 1086884 IMAGED  
DATE: 3/1/2000 PAGES: 2  
AUTHOR(S): ADDRESSSEE(S):  
EPA Unknown

DESCRIPTION:

Superfund Fact Sheet: The EPA and Taylor Lumber finished removal activities for the winter season.

16. 5... Vol. 1 - 1116275 DOC ID: 1116275 IMAGED  
DATE: 7/1/2000 PAGES: 3  
AUTHOR(S): ADDRESSSEE(S):  
EPA Unknown

DESCRIPTION:

Superfund Fact Sheet: The EPA and Taylor Lumber anticipate finishing hazardous waste removal activities this year.

16. 5... Vol. 1 - 1116274 DOC ID: 1116274 IMAGED  
DATE: 12/1/2000 PAGES: 3  
AUTHOR(S): ADDRESSSEE(S):  
EPA Unknown

DESCRIPTION:

Environmental Fact Sheet: The EPA proposes Taylor Lumber be added to the National Priorities List.

16. 5... Vol. 1 - 1127680 DOC ID: 1127680 IMAGED  
DATE: 6/1/2001 PAGES: 4  
AUTHOR(S): ADDRESSSEE(S):  
EPA Unknown

DESCRIPTION:

Superfund Fact Sheet: Site Approved for EPA Investigation and Cleanup.

16. 5... Vol. 1 - DOC ID: 1144530 IMAGED  
DATE: 6/1/2002 PAGES: 3  
AUTHOR(S): ADDRESSSEE(S):  
EPA Unknown

DESCRIPTION:

Superfund Fact Sheet: New Owner To Continue Site Cleanup.

16. 5... Vol. 1 - DOC ID: 1205965 IMAGED  
DATE: 7/1/2005 PAGES: 4  
AUTHOR(S): ADDRESSSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

EPA

Unknown

DESCRIPTION: Environmental Fact Sheet: Comments Requested on Taylor Lumber and Treating Cleanup Plan.

**SUB-HEAD: 16. 6... Vol. 1 - Mailing Lists**

16. 6... Vol. 1 - 1116580 DOC ID: 1116580 IMAGED  
DATE: 10/1/1999 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
Unknown Taylor Lumber and Treating, Inc.

DESCRIPTION: Redacted version of Taylor Lumber and Treating project mailing list.

**SUB-HEAD: 16. 9... Vol. 1 - Newspaper/Journal Articles**

16. 9... Vol. 1 - 1127681 DOC ID: 1127681 IMAGED  
DATE: 11/9/1999 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Cheryl Martinis/The Oregonian Unknown

DESCRIPTION: Newspaper Article: EPA comes down on lumber mill in Sheridan.

16. 9... Vol. 1 - 1127682 DOC ID: 1127682 IMAGED  
DATE: 11/11/1999 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
Pat Forgey/The McMinnville News Register Unknown

DESCRIPTION: Newspaper Article: Taylor may be named a Superfund cleanup site.

16. 9... Vol. 1 - 1127683 DOC ID: 1127683 IMAGED  
DATE: 11/13/1999 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
The Oregonian Unknown

DESCRIPTION: Newspaper Article: Sheridan wood plant maps steps to heed EPA demands.

16. 9... Vol. 1 - 1127684 DOC ID: 1127684 IMAGED  
DATE: 11/13/1999 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Pat Forgey/The McMinnville News Register Unknown

DESCRIPTION: Newspaper Article: Taylor Lumber has EPA history.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

16. 9... Vol. 1 - 1127685 DOC ID: 1127685 IMAGED  
DATE: 11/16/1999 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
Pat Forgey/The McMinnville News Register Unknown

DESCRIPTION: Newspaper Article: Taylor plan likely to win EPA approval.

16. 9... Vol. 1 - 1116786 DOC ID: 1116786 IMAGED  
DATE: 6/15/2000 PAGES: 3  
AUTHOR(S): ADDRESSEE(S):  
Brent Merrill/The Smoke Signals Unknown

DESCRIPTION: Journal Article: No contamination in city's water supply.

16. 9... Vol. 1 - 1124003 DOC ID: 1124003 IMAGED  
DATE: 6/28/2000 PAGES: 4  
AUTHOR(S): ADDRESSEE(S):  
Vince Gullette/Taylor Lumber and Treating, Inc. Unknown

DESCRIPTION: Newspaper Article: Taylor Lumber explains case with EPA.

16. 9... Vol. 1 - 1124004 DOC ID: 1124004 IMAGED  
DATE: 12/5/2000 PAGES: 2  
AUTHOR(S): ADDRESSEE(S):  
Pat Forgey/The McMinnville News Register Unknown

DESCRIPTION: Newspaper Article: Lumber plant eyed for major cleanup.

**HEADING: 17. 0... GRAPHICS**

**SUB-HEAD: 17. 1... Vol. 1 - Blueprints/Drawings**

17. 1... Vol. 1 - 1127783 DOC ID: 1127783 IMAGED  
DATE: 2/1/1998 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Maul Foster & Alongi, Inc. Unknown

DESCRIPTION:  
Drawing of the Treatment System.

17. 1... Vol. 1 - 1127784 DOC ID: 1127784 IMAGED  
DATE: 2/1/1998 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Maul Foster & Alongi, Inc. Unknown

DESCRIPTION:  
Drawing, with handwritten notes, of the Conveyance Piping.

17. 1... Vol. 1 - 1127782 DOC ID: 1127782 IMAGED  
DATE: 9/1/1999 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Maul Foster & Alongi, Inc. Unknown

DESCRIPTION:  
Drawing of the Staging Pile Construction Detail.

17. 1... Vol. 1 - 1116993 DOC ID: 1116993 IMAGED  
DATE: 1/1/2000 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Unknown Unknown

DESCRIPTION:  
Drawing of slurry wall.  
Note: Document date is estimated.

**SUB-HEAD: 17. 2... Vol. 1 - Maps/Plans**

17. 2... Vol. 1 - 1116596 DOC ID: 1116596 IMAGED  
DATE: 1/9/1990 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):  
Ecology & Environment, Inc. Unknown

DESCRIPTION:  
Map: Soil and Air Sample Location Map.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

17. 2... Vol. 1 - 1116599 DOC ID: 1116599 IMAGED  
DATE: 1/9/1990 PAGES: 1  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Map: Listing Site Inspection On-Site Soil Grid Sample Location Map.

17. 2... Vol. 1 - 1116600 DOC ID: 1116600 IMAGED  
DATE: 1/9/1990 PAGES: 1  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Map: On-Site Soil Grid Total PAH FASP Results.

17. 2... Vol. 1 - 1116601 DOC ID: 1116601 IMAGED  
DATE: 1/9/1990 PAGES: 1  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Map: Groundwater, Sediment, and Surface Water Sample Location Map.

17. 2... Vol. 1 - 1116789 DOC ID: 1116789 IMAGED  
DATE: 1/1/1996 PAGES: 1  
AUTHOR(S): EMCON Northwest, Inc. ADDRESSEE(S):  
Taylor Lumber and Treating, Inc.

DESCRIPTION: Oversize Map: Stormwater Sampling Locations.  
Note: This map is available in paper only, no electronic format.

17. 2... Vol. 1 - 1116597 DOC ID: 1116597 IMAGED  
DATE: 4/4/1999 PAGES: 1  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Map: Site Vicinity Map.

17. 2... Vol. 1 - 1116598 DOC ID: 1116598 IMAGED  
DATE: 4/4/1999 PAGES: 1  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION: Map: Site Layout Map.

17. 2... Vol. 1 - 1116788 DOC ID: 1116788 IMAGED  
DATE: 4/16/1999 PAGES: 1  
AUTHOR(S): ADDRESSEE(S):

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

Ecology & Environment, Inc.

Taylor Lumber and Treating, Inc.

DESCRIPTION:

Oversize Map: Surface Water and Sediment Sample Location.

Note: This map is available in paper only, no electronic format.

17. 2... Vol. 1 - 1116923 DOC ID: 1116923 IMAGED  
DATE: 5/7/1999 PAGES: 1  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION:

Annotated map showing January 1997 alluvial aquifer.

17. 2... Vol. 1 - 1116995 DOC ID: 1116995 IMAGED  
DATE: 11/2/1999 PAGES: 1  
AUTHOR(S): Bruce Morris/Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION:

Oversize Map: Removal Action Surface Soil Sample Location Plan.

Note: This map is available in paper only, no electronic format.

17. 2... Vol. 1 - 1127796 DOC ID: 1127796 IMAGED  
DATE: 11/2/1999 PAGES: 1  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION:

Oversize Map of the EPA Removal Action Paving Cover and Berming Plan.

Note: This map is available in paper only, no electronic format.

17. 2... Vol. 1 - 1167122 DOC ID: 1167122 IMAGED  
DATE: 5/22/2000 PAGES: 1  
AUTHOR(S): Matt Dunckel & Associates ADDRESSEE(S):  
Environmental Quality Management, Inc.

DESCRIPTION:

Oversize Map: As Built Survey.

Note: This map is available in paper only, no electronic format.

17. 2... Vol. 1 - 1127786 DOC ID: 1127786 IMAGED  
DATE: 6/30/2000 PAGES: 1  
AUTHOR(S): Ecology & Environment, Inc. ADDRESSEE(S):  
Unknown

DESCRIPTION:

Map: Figure 1, EPA Removal Action, Area of Contamination Location.

17. 2... Vol. 1 - 1167119 DOC ID: 1167119 IMAGED  
DATE: 2/15/2001 PAGES: 1  
AUTHOR(S): Matt Dunckel & Associates ADDRESSEE(S):  
Environmental Quality Management, Inc.

(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Oversize Map: As Built Surveys, Bentonite Wall.

Note: This map is available in paper only, no electronic format.

17. 2... Vol. 1 -

DOC ID: 1167120 IMAGED

DATE: 2/15/2001

PAGES: 1

AUTHOR(S):

Matt Dunckel & Associates

ADDRESSEE(S):

Environmental Quality Management, Inc.

DESCRIPTION:

Oversize Map: As Built Survey for the Stockpile.

Note: This map is available in paper only, no electronic format.

17. 2... Vol. 1 -

DOC ID: 1167121 IMAGED

DATE: 2/15/2001

PAGES: 1

AUTHOR(S):

Matt Dunckel & Associates

ADDRESSEE(S):

Environmental Quality Management, Inc.

DESCRIPTION:

Oversize Map: As Built Profile.

Note: This map is available in paper only, no electronic format.

**SUB-HEAD: 17. 3... Vol. 1 -**

**Photographs**

17. 3... Vol. 1 -

1116606

DOC ID: 1116606 IMAGED

DATE: 7/27/1963

PAGES: 3

AUTHOR(S):

Unknown

ADDRESSEE(S):

Unknown

DESCRIPTION:

Aerial photograph of Taylor Lumber Co. with overlay.

17. 3... Vol. 1 -

1116607

DOC ID: 1116607 IMAGED

DATE: 7/5/1970

PAGES: 3

AUTHOR(S):

Unknown

ADDRESSEE(S):

Unknown

DESCRIPTION:

Aerial photograph of Taylor Lumber Co. with overlay.

17. 3... Vol. 1 -

1116608

DOC ID: 1116608 IMAGED

DATE: 6/9/1982

PAGES: 3

AUTHOR(S):

Unknown

ADDRESSEE(S):

Unknown

DESCRIPTION:

Aerial photograph of Taylor Lumber Co. with overlay.

17. 3... Vol. 1 -

1116609

DOC ID: 1116609 IMAGED

DATE: 6/11/1986

PAGES: 3

AUTHOR(S):

Unknown

ADDRESSEE(S):

Unknown



(TLTRR) TAYLOR LUMBER AND TREATING INC. - REMEDIAL ADMINISTRATIVE RECORD INDEX

DESCRIPTION:

Aerial photograph of Taylor Lumber Co. with overlay.

**SUB-HEAD: 17. 3. 1.. Vol. 1 -                      Photographs on CD-ROM**

17. 3. 1.. Vol. 1 -

DOC ID: 1205847 IMAGED

DATE: 4/10/2000

PAGES: 1

AUTHOR(S):

ADDRESSEE(S):

Unknown

Unknown

DESCRIPTION:

CD-ROM: Consolidation of photographs taken between November 30, 1999 and April 10, 2000.